GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/GH/2025/SZ/34 No.

Dated: .1.7/.01/2025

FIRE SAFETY CERTIFICATE

Certified that the Lodging House in the Name & Style of M/s Mira International (A Unit of Sai Prem Hospitalities Pvt Ltd) at Plot No 103, Block-B, Pocket- 10, Sector 13, Dwarka, New Delhi 110078 comprised of Basement, Ground plus three upper floor owned/occupied by A Unit of Sai Prem Hospitalities Pvt Ltd was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/2021/SZ/GH/534 dated 20/12/2021. The premise was re-inspected by the officer concerned of this department on 09/01/2025 in the presence of Mr. Arvind Saxena and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (1st Floor (08 G/Rooms) 2nd Floor (08 G/Rooms) & 3rd Floor (6 G/Rooms) total 22 Guest Rooms only and validity upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on 17/01 /2025 at New Delhi by

DELHI FIRE SERVICE

Copy to: -

1. The Addl. Commissioner of Police (Lic.), 1st Floor, P.S. Defence Colony, New Delhi-110049 (Ref. MCD Portal ID 2024122918507 dated 29/12/2024)

Conditions for the validity of Fire Safety Certificate: -

1. The Staircase & passage to the stairs shall be kept open and free from lock & key.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

3. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire fighting

system.

5. The basement shall be used as per the provisions of BBL-/NBC Part- IV.

6. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

7. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-

2016), if any.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six month prior to its expiry."



-	INSPECT	ION DEDODE			
1	Name & Address of the Building M/s Mirr Internation 1 (4 7)				
	and delivered many many	M/s Mira International (A Unit of Sai Prem Hospitalities Pvt Ltd) at Plot No 103, Block-B, Pocket- 10, Sector 13, Dwarka, New Delhi 110078			
2	Type of Occupancy				
3	Building Comprised of	Residential, "Group-A" (Guest House)			
	7.0	Basement, Ground + 03 upper floors, 1 st to 3 ^r floor -total 22 Guest Rooms			
4	Type of Case	Renewal	Guest Kooms	N. T.	
5	Details of Previous NOC	F6/DFS/MS/2021/SZ/GH/534/ dated 20/12/2021			
6	Fire Safety Directives Letter No	Nil Nil			
7	Date of Inspection	09/01/2025			
8	Name of the Inspecting Officers	ADO (BCP)			
9	Name & Designation of Officers from the building side	Mr. Arvind Saxena			
10	Year of construction	2015			
11	Applicant letter No.	MCD Portal ID 2024122918507 dated 29/12/2024			
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC requirements	Provided at Site	Remarks MR/NMR	
1	Access to Building.			MICHAL	
	Road width	Accessible	18 mtr	MR	
9	Gate width	4.5 mtr	Directly accessible	MR	
•	Width of internal road	-NA-	-NA-	-NA-	
2	Number, width, type & arrangement of exits.		and the second s		
	a) Number of Staircase				
	 Upper floors. Basement floor. 	01 No	02 No	MR	
	The Control of the Co	02 No	Provided	MR	
	b) Width of Staircase	, 111	7 Y 11-87 K		
	▶ Upper floors▶ Basement floor	1.25 mtr	1.25 mtr & 0.75 mtr	MR	
		1.25 mtr	Provided	MR	
	c) Protection of exits > Fire check door	As per clause 7.31 of UBBL 2016			
Juli	> Pressurization	Required	Provided	MR	
		-NA-	-NA-	-NA-	
2014	d) No. of continuous staircase to terrace e) Width of corridor	Required	Provided	MR	
125	e) Width of corridor f) Door size	1.35 mtr	Provided	MR	
3	Compartmentation.	1.35 mtr	Provided	MR	
	Fire check door.	-NA-	-NA-	374	
196	Sealing of electrical shafts.	Required	10-779-12	-NA-	
	Fire rating of shaft door.	-NA-	Provided	MR	
AIR-	Water curtain	-NA-	-NA-	-NA-	
H) N	Fire dampers.	-NA-	-NA-	-NA-	
4	Smoke Management system.	As per clause 7.31 of UBBL 2016			
_	Basement	30 ACPH	Exhaust fan provided	MR	
100	Upper floors	12 ACPH	Exhaust fan provided	MR	
5	Fire Extinguishers.	-1111	provided	IVIK	
101.0	Total numbers	12 Nos	Provided	MR	
	Types	ABC / CO2	ABC & CO2	MR	
TV.	ISI Marking	ISI marked	Provided	MR	
6	First Aid Hose Reels.		district and the	TATIC	
	Total numbers on each floor.	One	Provided	MR	



	a Longth of horse and the	30 mtr	D	
	 Length of hose-reel hose. Nozzle Diameter 		Provided	MR
7		5 mm	Provided	MR
'	Automatic fire detection & alarming system.	As per clause 7.3		
	Type of detectors Location of Main Panel	Co. Mo. Type	Provided	MR
		Required -NA-	Provided	MR
	Location of Repeater Panel		-NA-	-NA-
	Alternate source of power	Required	Provided	MR
8	Hooter's location MOEFA	· -NA-	-NA-	-NA-
9		Required	Provided	MR
10	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System Basement	D ! 4	D 11.1	
		Required	Provided	MR
	Upper floors.	-NA-	-NA-	-NA-
11	Sprinkler above false ceiling	-NA-	-NA-	-NA-
11	Internal Hydrants.			
	Size of Riser/Down-comer	100 mm	Provided	MR
	Number of Hydrant per floor	01 No	Provided	MR
	Hose box.	01 No	Provided	MR
12	Yard Hydrants.	REORGANIA MA	A Mariana and and and	1
	Total number of hydrants.	-NA-	-NA-	-NA-
22	Hose box.	-NA-	-NA-	-NA-
13	Pumping arrangements.	14		
	Ground Level			
	Discharge of main pump.	-NA-	-NA-	-NA-
	Head of main pump.	-NA-	-NA-	-NA-
	Number of main pumps.	-NA-	-NA-	-NA-
	Jockey Pump output.	-NA-	-NA-	-NA-
	Jockey Pump head.	-NA-	-NA-	-NA-
	Standby Pump output. Standby Pump head	-NA-	-NA-	-NA-
	Standby Pump head.Auto Starting/Manual Stopping.	-NA-	-NA-	-NA-
	Pump house access.	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
	Terrace Level		1 1 1 V	-
	Discharge of pump.	900 LPM	900 + 180 LPM	MR
	Head of pump.	40 m	Provided	MR
	Power supply. Auto starting of nump	Provided	Provided	MR
14	Tate starting of pump.	Provided	Provided	MR
14	Captive water storage for fire fighting.			
	Underground tank capacity.	-NA-	NA	-NA-
160	Draw-off connection.	-NA-	-NA-	-NA-
	Fire Service Inlet.	-NA-	-NA-	-NA-
	Access to tank.	-NA-	-NA-	-NA-
	Overhead tank capacity.	15,000 ltr	Provided	MR
15	Exit Signage.	Required	Provided	2207
16	Provision of Lifts.			MR
	Pressurization of lift shaft.	-NA-	NT A	20/20
	Pressurization of lift lobby.	-NA-	-NA-	-NA-
	Communication in lift car.	Required	-NA-	-NA-
	• Fireman's switch.	Required	Provided	MR
	Lift signage		Provided	MR
17	Standby Power Supply	Required	Provided	MR
18	Refuge Area	Required	Provided	MR



	Total area	-NA-	-NA-	-NA-
	Location	-NA-	-NA-	-NA-
19	Fire Control Room.			-11//-
	 Detector system panel. Flow switch panel. PA system panel. Battery backup. 	-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		-NA-	-NA-	-NA-
		Required	Provided	MR
20	Building floor plan. Second Bird Broad State Second Bird Broad S	-NA-	-NA-	-NA-
20	Special Fire Protection System for the Protection of special Risk, if any.			-NA-

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the management has complied all the observation / Shortcoming already issued & communicated by this department vide letter of even no 738 dated 19/12/2024.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/NS/2021/SZ/GH/534 dated 20/12/2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Design: ADO (BCP)

F.t. Letter er portrep