



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

75
आजादी का
अमृत महोत्सव

No. F6/DFS/MS/School/2025/NDZ/ 636

Dated: 11 / 08 / 2025

To,

The Principal,
Modern Era Public School (Recognized),
B- 328, Ashok Nagar, Mandoli Road, Shahdara,
Delhi -110093.


Sub.: - Inspection Report in r/o Modern Era Public School (Recognized), located at B - 328, Ashok Nagar, Mandoli Road, Shahdara, Delhi - 110092.

Sir,

Please refer to your Outdoor Dairy No. 3705 dated 14/07/2025 on the subject cited above. In this connection, it is to inform you that the site was visited by officer concerned of this department on dated 23/07/2025 and observed that the shortcoming has still not complied with as issued by this department vide letter no. F6/DFS/MS/2019/1636 dated 02/04/2019 (copy enclosed).

In view of above, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building / premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner / occupier.

Yours faithfully,


11/8/2025

VIRENDRA SINGH
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
01/8/2025

Enclosed: as above

Copy to: -

1. The Director of Education, MCD Civic Centre, Jawahar Lal Nehru Marg, New Delhi - 110002.

C-8

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001

No. 1-6/AFS/MS/2019/1636
To,

Dated 2/4/19

The Manager,
M/s Modern Era Public School,
B-328, Ashok Nagar Mandoli,
Delhi 110094

Sub:- Regarding Issuance of Fire Safety Certificate in r/o M/s Modern Era Public School at B-328, Ashok Nagar Mandoli, Delhi 110094.

Sir,

This is in reference to your letter No. MEPS/172, Dated 07/02/19 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection of the above mentioned school from fire safety point of view in presence of Mrs. Meenu Aroda, Manager. During the course of inspection the following points / shortcomings were noticed in the school building comprised of ground plus two upper floors.

1. The width of staircase shall be 1.50 meter or an additional staircase of 0.75 meter shall be provided.
2. Only 02 fire extinguishers provided in place of 06 fire extinguishers as required.
3. First-Aid hose reels not provided.
4. A fire pump having 225 LPM output at 40 meters head not provided at terrace.
5. Over Head water storage tank 2,500 liters capacity exclusively for fire fighting not provided at terrace.
6. Exit Signage not provided.

In view of above, the school building can not be considered for issue of Fire Safety Certificate at this stage. Therefore you are suggested to rectify the above mentioned shortcomings under the intimation to this department for further course of action.

Yours faithfully


(Sunil Chawdhary)
Dy. Chief Fire Officer

Copy:-
The Director of Education, EDMC,
Udyog Sadan, Plot No.419, FIE,
Patparganj Industrial Area,
Delhi-110092