GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



6. F6/DFS/MS/EH/SZ/2025/114

Dated: 02 04 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s. Naarma Unit of Samyra Café Pvt. Ltd. located at Unit No. Plaza 3, Ground Floor, Epicuria, Nehru Palace Metro Station, New Delhi-110019, restaurant is running at Ground Floor in a building comprised of Lower Ground Floor & Upper Ground Floor, owned/occupied by M/s. Naarma Unit of Samyra Café Pvt. Ltd. The building/premises was inspected by the officer concerned of this department on 21/03/2025 in the presence of Sh. Raj (Manager, Project & Operation) and found that the said premises/building have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises/building is fit for occupancy class "Assembly Building" (Group-D) (Restaurant at Ground Floor only) with effect from O2 O4 O4 O5 and valid upto 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010. Conditions mentioned below.

Issued on . O. 2 . O. 4. 2025 at New Delhi by

Director Tel. No. 011-23414000

Copy to:

 The Joint Commissioner of Police, Licensing Unit, 1st floor, Police Station, Defence Colony, New Delhi in r/o computer id no. 2025030602960 dated 04/03/2025

The Dy. Health Officer, MCD, Office of Dy. Health Officer, South Zone, Green Park, New Delhi-110016

3. The Authorized Signatory, Naarma Unit of Samyra Café Pvt. Ltd. located at Unit No. Plaza 3, Ground Floor, Epicuria, Nehru Palace Metro Station, New Delhi-110019.

Conditions for the validity of Fire Safety Certificate:-

- 1. This FSC is valid for restaurant area's ground floor only.
- 2. All the means of escape shall be kept free of all type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 5. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 6. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.
- 7. All comments / directions of licensing Department shall always be permitted and followed.
- 8. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in
- 9. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

1.	Name & address of the building	NSPECTION REPOR				
	a decises of the building	Naarma Unit of San	nyra Cafe Ltd. located	at Unit No.Pla		
		3, Ground Floor Epi	curia, Nehru Palace Me	tro Station, N		
2.	Type of Occupancy	Delhi-110019.				
3.	Type of Case		Assembly (Group-D)			
4.		New case				
5.	Details of previous NOC	Nil				
	Fire Safety directives letter No	Nil				
6.	Date of inspection	21/03/2025	HOT II - FFE HOLD			
7.	Name of the Inspecting Officers	Aman Kumar Lathar	, ADO (JWP)			
8.	Name and designation of officers	Sh. Raj (Manager, Pr				
	from the building side		L I I I			
9.	Year of Construction	2013 (As per MHA P	Portal)			
10.	Applicant's letter No.	Application No. 2025	030602960 dated 04/03	/2025		
The	said restaurant running at Ground	Floor, in a building c	omprised of Lower gro	ound & Uppe		
Gro	und Floors (PD area at Nehru Place	metro station).				
S.	Minimum Standards on fire	BBL /NBC	Provided at site	Remarks		
No.	prevention and fire safety U/R 3	Requirement		MR/NMR		
1	Access to building					
	 Road width 	Restaurant	As above	MR		
	Gate width	Within	As above	NA		
	• Width of internal road	TDI Mall	As above	NÁ		
2	Number, Width, Type & Arrange	ment of Exits				
	a. Number of staircases		Maintained by TDI Mal	I/DMRC		
	• Upper Floors	NA	Rest. at GF	NA		
	Basements	NA	As above	NA .		
	b. Width of staircases	Provided & Maintained by TDI Mall/DMRC				
	Upper Floors	NA	Rest. at GF	NA		
	Basements	NA	As above	NA		
	c. Protection of exits	Provided & 1	Maintained by TDI Mal	I/DMRC		
	Fire check door	NA	NA	NA		
	Pressurization	NA	NA	NA		
	e. No. of continuous staircases to terra	ce Required	One	MR		
	f. Width of Corridor	ŇA	NA	NA		
	g. Door Size	1.5 mtr x 2	Provided	MR		
	Compartmentation.	Provided & N	Maintained by TDI Mall	/DMRC		
	Fire check door	NA	NA	NA		
	 Sealing of electrical shafts 	NA	NA .	NA		
	Fire Rating of shaft door	NA	NA	NA		
	Water Curtain	NA NA	NA NA	NA NA		
	Fire Dampers Smoke Management System.	70 (A)C (A)C	faintained by TDI Mall/			
	Basements	NA NA	NA NA	NA		
	Upper floors	NA NA	NA NA	NA NA		
		IVA	MA			
	Fire Extinguishers	06 mar	Provided	MD		
	Total numbers	06 nos. CO ₂ , ABC type		MR		
	Types	ISI marked	Provided	MR		
	IS marking		Provided	MR		
	First-Aid Hose Reels.	Provided & Ma	aintained by TDI Mall/D	MRC		
	Total numbers on each floor	01	Provided	MR		
	Length of hose reel hose	30m	Provided	MR		
	-	241				
- 1	 Nozzle diameter 	Smm	Provided	MR		

B/

TI.

v.	-2	_
----	----	---

7	Automatic fire detection and alarming sy Type of detectors	Required	Provided Provided	1	
	Location of Main Panel	Required	Provided Provided	M	
	Location of Main Panel Location of Repeater Panel	Required		M	
		Required	Provided Provided	M	
	Alternate source of power Hooters' Location	Required	Provided	M	
•	Hooters' Location		Provided	MI	
9	MOEFA Public Address System	Required NA	Provided	MI	
10	Public Address System. Automatic Sprinkler System.		NA	NA	
IO			ntained by TDI Mall/	DMRC	
	Basement	Required	Provided	MF	
	Upper Floor	Required	Provided	MF	
	Sprinkler above false ceiling	Required	Provided	MR	
11	Internal Hydrants		intained by TDI Mall	/DMRC	
	Size of riser/down-comer	Required	Provided	MR	
-	Number of hydrants per floor	Required	Provided	MR	
	Hose Box	Required	Provided	MR	
12	Yard Hydrants.				
	Total number of hydrants	Required	Provided	MR	
	Hose Box	Required	Provided	MR	
13	Pumping Arrangements.			IVIK	
	Ground Level	Provided & M	aintained by TDI Mall	/DMPC	
	Discharge of main Pump	1800 LPM			
	Head of Main pump	70 m	Provided	MR	
	> Number of main pumps	70 m	Provided	MR	
	> Jockey Pump out put	180 LPM	Provided Provided	MR MR	
	> Jockey pump head	70 m	Provided	MR	
	> Standby Pump out put	1800 LPM	Provided	MR	
	> Standby Pump Head	70 m	Provided	MR	
	> Auto Starting/ Manual stopping	Required	Provided	MR	
ı v	> Pump House Access	Required	Provided	MR	
	Terrace level	Charles Charles Charles Charles	aintained by TDI Mall	150000	
	➤ Discharge of pump	NA	As above	NA	
	➤ Head of the pump	NA	As above	NA	
	> Power Supply	NA	As above	NA	
	➤ Auto Starting of pump	NA	As above	NA	
14	Captive Water Storage for fire fighting.	Provided & Mai	ntained by TDI Mall/D	OMRC	
	Underground tank capacity	Required	Provided	MR	
	> Draw-off connection	Required	Provided	MR	
	> Fire service inlet	Required	Provided	MR	
	> Access to tank	Required	Provided	MR	
	Overhead Tank capacity	Required	Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of Lifts. Provided & Maintained by TDI Mall/DMRC				
	Pressurization of Lift Shaft	As above	NA	NA	
	Pressurization of Lift lobby	As above	NA	NA	
	Communication In lift Car	NA NA	NA	NA	
			NA NA	NA	
	Fireman's Grounding Switch	NA NA		NA	
	Lift Signage	NA	NA		
	Standby power supply	Required	Provided	MR	

8	Refuge Area.		Del		
	> Total Area	NA	NA	NA	
	Location	NA	NA	NA	
9	Fire Control Room	Provided & M	aintained by TDI Ma	all/DMRC	
	Detector System Panel	NA	NA	NA	
	Flow Switch Panel	NA	NA	NA	
	PA System Panel	NA	NA	NA	
	Battery backup	NA	NA	NA	
	Building Floor Plans	NA	ΝA	NA	
20	Special Fire Protection Systems for	NA	NA	NA	
	Protection of special Risks, if any:	-			

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention & fire safety requirement under the rules and it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010.

Aman Kumar Lathar ADO (JWP)

F.S. letter is put-up for your mondown M.

Pill to "

Alliu 25