



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001**

F.6/DFS/MS/School/2025/SZ/ 327 No.

Dated: 05/05/2025

To

Dr. Kuldeep Sharma (Manager), Nav Gian Deep Public School, Block-A1/66 Vijay Enclave, Dabri Palam Road, New Delhi-110045

Regarding issuance of Fire Safety Certificate in r/o Nav Gian Deep Public School, Sub: Block-A1/66, Vijay Enclave, Dabri Palam Road, New Delhi-110045

Sir,

This has a reference to your letter No. NGDPS/DFS/01/2025 dated 19/03/2025 received in this department vide outdoor diary No.151 dated 03/04/2025, on the subject cited above. In this connection, the school premise school was re-inspected by the officer concerned of this department on 25/04/2025 to verify the compliance of shortcomings communicated vide this office letter No. F6/DFS/MS/SZ/2022/School/18 dated 18/01/2022 (copy enclosed) in the presence of Sh. Subham Sharma (Coordinator) and observed that the shortcomings have not been complied so far.

In view of above, the application for issuance of fire safety certificate is rejected and you are re-advised to rectify/submit compliance of the shortcomings under intimation to this department for further action in the matter.

Yours faithfully,

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI

No.F6/DFS/MS/SZ/2022/ School 18

Dated: 18 /01/2022

To,

Dr. Kuldeep Sharma (Manager) <navgiandeepschool@rediffmail.com> Nav Gian Deep Sr. Sec. Public School, A – 1/66, Vijay Enclave, New Delhi – 110045.

Subject: Issuance of Fire Safety Certificate in r/o Nav Gian Deep Sr. Sec. Public School Located at A – 1/66, Vijay Enclave, New Delhi – 110045.

Please refer to Email dated 09-12-2021 on the subject mentioned above. In this connection it is to inform you that the inspection of the premises was carried out by the officer concerned from this department on 23/12/2021.

During course of inspection the following shortcomings were observed:

- 1. The premise is not accessible to fire tender.
- 2. Two continuous staircases of 1.5m width for all the floors are not provided.
- 3. Corridor/ passage lead to stair must not be less than 1.5m.
- 4. One class room door for the class room having less than 45 students & two class room door for the class room having more than 45 students of 1.2m width are not provided.
- 5. P A system found not provided.

You are requested to comply the abovementioned shortcomings under intimation to this department.

In view of the above shortcomings Fire Safety Certificate cannot be considered at this stage.

Yours faithfully,

Delhi Fire Service

Copy to;-

1. Directorate of Education Old Secretariat Delhi - 110054