

C-38

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

F6/DFS/MS/NDZ/2025/ 49

Dated:- 03./02./2025

To,

Sh. Narender Kumar Gaur,
Fire officer,
Fire Department,
New Delhi Municipal Council,
Palika Kendra, New Delhi.

Sub:- Regarding renewal of Fire Safety Certificate in r/o NDMC, Service Corridor, Connaught Place, New Delhi.

Sir,

This has reference to your mail id fo@ndmc.gov.in dated 03.01.2025, on the subject cited above. In this regard, it is to inform that the site was inspected by the officers concerned of this department on 22/01/2025 in the presence of Sh. Harender Kumar (fire Officer) and the following shortcomings were observed:-

1. FCD at some staircases found broken.
2. Hose reel nozzle found missing at some hose reels.
3. Hoses and branch found missing at some Hose boxes.
4. MCP found nonfunctional.
5. Smoke management system is not integrated with automatic detection system.
6. All columns /parts shall be painted with florescent paint or tape to make visible.
7. Fire Pumps are not on 'Auto' Mode.

In view of above case is rejected, and FSC cannot be renewed at this stage. Therefore it is requested to rectify the above shortcomings at the earliest for further consideration in the matter. .

Yours faithfully

(Atul Garg)
DIRECTOR
Delhi Fire Service

Copy to:-

1. The Chief Architect, NDMC, Palika Kendra, New Delhi.