

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI – 110001

No. F6/DFS/MS/2025/ **237**

Dated **23.05/2025**

To,

The Assistant Engineer (E), HC-2,
 PWD, HMED (C),
 Lok Nayak Hospital, New Delhi.

Sub: Regarding issuance of fire safety at New O.T, Block Lok Nayak Hospital, New Delhi.
 Sir,

This has reference to your letter no. fire/AE(E)/HC-II/PWD/2025-26/13 dated 21.04.2025, on the subject cited above, it is to inform that the site was inspected by the officers concerned of this department on 14/05/25 in the presence of Mr. Manish, AE and the following shortcomings were observed.

1. Alternate staircase found locked/blocked in basement.
2. Smoke Management system found nonfunctional.
3. Fire-man lift switches found nonfunctional.
4. Sprinkler is not provided at some portion in basement storages area , required to be extended to left out area .
5. Lift serving to basement is not protected with lobby.

In view of above shortcomings, the application for issuance of FSC is rejected. The occupancy in the building without requisite fire safety arrangement shall be at risk and liability of owner /occupier of the building. The statutory /licensing authority may take necessary action as deemed fit.

Yours faithfully

(Atul Garg)
 DIRECTOR
 Delhi Fire Service

Copy to:

1. The Medical Superintendent, LNJP hospital, New Delhi.
2. The Assistant Engineer (E), Health maint. Elect. Division (C), PWD, LNJP, New Delhi.