GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No.F6/DFS/MS/EH/SZ/2025/ 398

Dated: 2.7./. J.1.. /2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name and style of M/s Pind Balluchi (A unit of Virsa Cuisine Hospitality) located at Ground Floor, Shop No. 31, 32, 33 & 34, MGF Metro Metropolitan Mall, Saket, Delhi – 110017 in the building comprised of 2-tier basement, ground plus seven upper floors was earlier granted FSC by this department vide letter No.F6/DFS/MS/EH/2023/SZ/517 Dated 04/11/2023 in name of Excuse Me Boss Café, Ground Floor, Shop No. 31, 32, 33 & 34, MGF Metro Metropolitan Mall, Saket, Delhi – 110017. Now, the premises was re-inspected by the officer concerned of this department on 11/11/2025 in the presence of Sh. Shakti Prasad (Manager Admin) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy "Assembly Building Group D" Restaurant at Ground Floor only with effect from .27/11.../2025 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 2.7.1.1.1 2.225. at New Delhi by.

(A. K Malik)
Dy. Chief Fire Officer
Delhi Fire Service

Copy to:-

- 1. The Commissioner, MCD, Civic Centre, Minto Road, New Delhi. (Online MCD ID-2025100413952 dated 01/11/2025)
- 2. The Manager, M/s Pind Balluchi (A unit of Virsa Cuisine Hospitality), Shop No. 31, 32, 33 & 34, MGF Metro Metropolitan Mall, Saket, Delhi 110017

Conditions for the validity of Fire Safety Certificate

- 1. This FSC is valid for restaurant at ground floor only subject to condition that renewal of FSC of the whole building shall be done before the expiry of the same.
- 2. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to nonfunctional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 8. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
- 9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry.
- 10. Any flammable material for interior decoration shall strictly prohibited.

		TION REPORT				
Name & address of the building Type of any and a second sec		Trospitality.	M/s Pind Balluchi (A unit of Virsa Cuisine Hospitality, Shop No. 31, 32, 33 & 34, MGF Metro Metropolitan Mall, Saket, Delhi –			
	Type of occupancy		at Ground Floor	Only	,	
3.	Comprised ()					
<u>4.</u>	Type of case	Renewal	nent + Ground +	- 7 U	pper Floors	
5. Details of previous FSC No.		No.F6/DFS/MS/EH/2023/SZ/517 Dated 04/11/2023 (issued to M/s Excuse Me Page				
6.	Fire safety directives No	Carc				
	Date of inspection: -	11/11/2025	S/BP/2005/2150	date	d 14/10/200:	
8.	Name of the inspecting officer: -					
9.	Name & designation of officer	Sh Shakti I	Prakash ADO(C	(C)		
	From the building side: -	on onaku i	Prasad (Manager	Adr	nin)	
10.	Year of construction: -	2007	14			
	Applicant's letter No: -		e ID. 20251004	1395	2 dated	
S. No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement/ Existing fire safety arrangements	Provided at	site	Remarks MR/NMF	
1.	Access to Building	FSC-F6/DFS/	/MS/2019/SZ/464	dated 04/10/2023		
	Road width	2 10	As above	iket,		
	 Gate width 	Restaurant.	A = 1		MR	
	Width of internal road	With in mall	As above		N/A	
2.	Number, Width Type & Arrangem	ent of Evita	As above		N/A	
	a. Number of staircases	Provided on	1 Maintain 11			
	Upper floors	N/A	Maintained by Restt. At GI	Mal	100000000000000000000000000000000000000	
	Basements	N/A	As above	6	N/A	
	b. Width of staircase		As above Maintained by	17.1	N/A	
	 Upper floors 	N/A	Restt. At GF	Mai		
	Basements	N/A	As above		N/A	
	c. Protection of exits		Maintained by	34-1	N/A	
	Fire check door	N/A	N/A	Mai		
	 Pressurization 	N/A	N/A		N/A	
	d. No. of continuous	N/A	One		N/A	
	staircase to terrace		One		N/A	
	e. Width of corridor	N/A	N/A		N/A	
	f. Door size	(1.50m x 2)	1.50m &1.50)m	MR	
3.	Compartmentation		Maintained by Mall			
	Fire check door	N/A	N/A	.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	N/A	
	 Sealing of electrical shafts 	N/A	N/A		N/A	
	 Fire rating of shaft door 	N/A	N/A		N/A	
	Water curtain	N/A	N/A		N/A	
	Fire Dampers	N/A	N/A		N/A	
4.	Smoke Management System	Provided and	Maintained by	Mall	- AUGUSTAN	
	Basements	N/A	12 ACHP	N.	/A	
	Upper floors	12 ACHP	Exhaust Fans Provided			
5.	Fire Extinguishers				¥:	
	 Total numbers 	Required	8 Nos	M	R	
	 Types 	ABC/CO ₂ ISI Marked	ABC-4,	M		
	ISI marking		W.CO ₂ -04 Provided	MR		
6.	First-Aid Hose Reel	Provided and	Maintained by N	M	K	
•						

				THE RESERVE OF THE PARTY OF THE	
	 Length of hose reel hose 	30m	Provided	A CONTRACTOR	
	Nozzle diameter	5mm	Provided	10	
7.	Automatic Fire Detection	Provided a	nd Maintained	by M	
	& Alarming System.	Provided and Maintained		oy Man	
	Type of detectors	N/A	As above	N/A	
	 Location of main panel 	N/A	As above	14/4	
	 Location of repeater panel 	N/A	As above	N/A	
	Alternate source of power	N/A	As above	N/A	
	Hooter's Location	N/A	As above	N/A	
8.	MOEFA	Required	Provided		
9.	Public Address System	N/A	Provided	MR	
10.	Automatic Sprinkler System	ISSOCIANCE VA	nd Maintained	N/A by Mall	
	Basement	N/A	N/A	NUA	
	Upper floors	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11.	Internal Hydrants		d Maintained	N/A	
	Size of riser/down-comer	N/A	N/A	N/A	
	Number of hydrants per floor	N/A	N/A	N/A N/A	
	Hose box	N/A	N/A	N/A N/A	
12.	Yard Hydrants		d Maintained b		
	Total number of hydrants	N/A	N/A	N/A	
	Hose box	N/A	N/A	N/A	
13.	Pumping Arrangement	A 11 A A	IVA	IN/A	
	Ground level	Provided and	d Maintained by	v Mall	
	Discharge of main pump	N/A	4500 LPM	N/A	
	Head of main pump	N/A	60 mtr	N/A	
	Number of main pumps	N/A	Two	N/A	
	Jockey pump out put	N/A	180 LPM	N/A	
	Jockey pump head	N/A	60 mtr	N/A N/A	
	Stand by pump output	N/A	4500 LPM	N/A N/A	
	 Stand by pump head 	N/A	60 mtr	N/A	
	 Auto starting/Manual stopping 	N/A	Provided	N/A	
	Pump House Access	N/A	Provided	N/A	
	Terrace level		Maintained by	Mall	
	Discharge of pump	450 LPM	As above	MR	
	Head of pump	70 m	As above	MR	
	Power supply	Required	As above	MR	
14	Auto starting of pump	Required	As above	MR	
14.	Captive Water Storage for Fire Fighting	Provided and Maintained by Mall			
_	Underground tank capacity	N/A	3,00,000 Ltr	s N/A	
	Draw-off connection	N/A	Provided	N/A	
	Fire service inlet	N/A	Provided	N/A	
	Access to tank	N/A	Provided	N/A	
_	Overhead tank capacity	20,000 ltrs	Provided	MR	
5.	Exit Signage.	Required	Provided	MR	
6.	Provision of Lifts.		Maintained by		
	Pressurization of lift shaft	N/A	N/A	N/A	
_	Pressurization of lift lobby	N/A	N/A	N/A	
	Communication in lift car	N/A	N/A	N/A	
	Fireman's switch	N/A	N/A	N/A	
	Lift signage	N/A	N/A	N/A	
7.	Stand by Power Supply	Required	Provided (DG Set)	MR	
3.	Refuge Area	27/4	NIA	NI/A	
	Total area location	N/A	N/A	N/A	
	Fire Control Room		Maintained by		
		N/A	Provided	N/A	
•	Detector system panel	N/A	Provided	N/A	

4121

PA system panel	N/A	Provided
Battery backup	N/A	D
Building floor plan	N/A	D
Special Fire Protection System for	N/A	N/A
Protection of special Risk, if any:		

The fire protection systems provided in the said restaurant building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules. Accordingly, FSC is recommended for approval.

Accordingly, DFA is put up for kind perusal and signature please. The last date of deemed approval is 01/12/2025.

Bhupender Prakash ADO (CC)

Dycoics24
18/4/25
A. K. MALIK

Reduci pel Dinotor

m. cro ho

20/11/25

A. K. MALIK

70/10/2

And lee

Pathitier Singh