



75/87
आजादी
अमृत महोत्सव

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/WZ/2025/ 401
To,

Dated: 20/08/2025

The Authorized signatory,
Govt. Building Police Staff Quarters,
Punjabi Bagh, New Delhi.

Sub: Inspection report in r/o Govt. Building Police Staff Quarters at Punjabi Bagh, New Delhi.

Sir,

Please refer to your letter No. 11099/Admn.-II/West Distt., dated 04/07/2025, received through outdoor diary No. 3829 dated 16/07/2025, on the subject cited above. In this connection, it is to inform you that the premises was inspected by officer concerned of this department on 28/07/2025 in the presence of Sh. Ram Avatar Meena (H.C.) to see the functioning of fire safety equipments provided in the Building.

During inspection, It has been observed that the said building comprised of 02 blocks (1st block=basement + stilt + 07 upper floors), 2nd block (basement + stilt + 06 upper floors), was issued FSC vide letter No. F6/DFS/MS/WZ/2018/2152 dated 05/10/2018. Fire safety arrangements such as Smoke Management System, Fire Extinguishers, MOEFA, First Aid hose reels are provided. However the following shortcomings were observed:-

1. First Aid Hose reels are provided but not functional.
2. MOEFA is provided but not functional.
3. Public Address System is provided but not functional.
4. Internal Hydrants are provided but not functional.
5. Main fire pump capacity of 2280 LPM, Standby pump capacity of 2280 LPM, Jockey pump capacity of 180LPM & terrace level pump capacity of 900 LPM are provided but not functional.
6. Exit Signage are found removed.

In view of above shortcomings, the application for renewal fire safety certificate is not considered at this stage & rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. the licensing authority/statutory authority may take suitable necessary action as deemed fit.

Yours faithfully,


19/8/2025
Virendra Singh
Chief Fire Officer

Copy To:-

1. The Executive Engineer (Bldg), HQs, MCD, Civic Centre, Minto Road, New Delhi.

42 889
19/8/2025