

FORM 'H': FORM FOR ISSUING FIRE SAFETY CERTIFICATE [See sub-rule (1) of rule 35]

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No F 6/DFS/MS/GH/2025/NDZ/ 568

Dated: 23 12 2025

P11 'A1

FIRE SAFETY CERTIFICATE

Certified that the M/s Rabbi Guest House located at 1141, Haveli Sadar Sadoor, Matia Mahal, Jama Masjid, Delhi, comprised of Ground + Mezzanine + 04 Upper floors, Ground floor (Commercial use), Mezzanine floor (Reception + Staff room + Store), 1st floor (03 Guest rooms), 2nd floor (03 Guest Rooms), 3rd & 4th floor not in use as per affidavit dated 13.08.2022, total 06 guest rooms up to 2nd floor only was issued FSC by this department vide letter No F6/DFS/MS/GH/NDZ/2022/400 dated 01.09.2022. The premise was re-inspected by the officer concerned of this department on 10.12.2025 in the presence of Jasim Ahmed and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Class A, Residential (Guest House for total 06 guest rooms up to 2nd floor only)" with effect from ... 23.12.225 for a period of three years in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40, subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

(Dr. S.K. Tomar)

Dy. Chief Fire Officer

The property of the control of the cont

Copy to: -

1. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as detailed above. (MCD Portal, ID No. 2025120415402)

2. M/s Rabbi Guest House located at 1141, Haveli Sadar Sadoor, Matia Mahal, Jama Masjid, Delhi.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.gov.in) along with a copy of this Certificate, six months prior to its expiry.
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The occupancy of 3rd floor and 4th floor not allowed as per clause 7.31 in UBBL-2016.

9. The means of escape shall be kept unobstructed/ unlocked for unhindered evacuation in case of an emergency.

INSPECTION REPORT

1. Name & address of the building: M/s Rabbi Guest House located at 1141, Haveli Sadar

Sadoor, Matia Mahal, Jama Masjid, Delhi.

2. Type of Occupancy 3. Building Comprised of

: Residential Building (Sub Division A-1). : Ground + Mezzanine + 04 Upper floor

Ground Floor – Commercial use (other shops) Mezzanine floor - (reception + staff rooms + store)

1st floor – (03 guest rooms)

2nd floor – (03 guest rooms)
3rd & 4th floor – not in use as per affidavit 13.08.2022

4. Type of Case

Renewal

5. Details of Previous NOC

F6/DFS/MS/GH/NDZ/2022/400 Dated 01/09/2022

6. Fire Safety directives letter No :

Nil

7. Date of inspection

10/12/2025

8. Name of Inspecting Officer

R.K.Sinha, ADO (Jawala Puri)

9. Name and designation of officers

From the building side 10. Year of Construction

Jasim Ahmed

: 1983 as per MCD portal

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	As per inspe report dated		Provided at site	Remarks MR/NMR		
1.	Access to building			701			
	Road width	NA	the proportion of the following a common of	(15 mtrs. away main road)	MR		
	Gate width	NA		NA	NA		
	Width of internal road	NA	grand and	NA	NA		
2.	Number, Width, Type & Arrangement of Exits						
	Number of staircases	1					
	Upper Floors	01 No	No. 01 No.		MR		
	Basements	NA		NA	NA		
-	Width of staircases						
	Upper Floor	0.80 m	0.	88 m to 1 m	MR		
117.00	Basements	NA	14 THE	NA	NA		
e i	Protection of exits	NA	. 400	NA	NA		
	Fire check door	NA	V. T. J	NA	NA		
	Pressurization	NA		NA	NA		
	No. of continuous staircases to terrace	NA		NA	NA		
	Width of Corridor	NA		NA	NA		
	Door Size	1 m		1 m	MR		
3.	Compartmentation				(BOTTE M		
	Fire check door	NA		NA	374		
	Sealing of electrical shafts	. NA		NA NA	NA		
	Fire Rating of shaft door	NA			NA		
	Water Curtain	NA		NA NA	NA		
	Fire Dampers	NA		NA NA	NA		
4.	Smoke Management System		W	INA	NA		
	Basements	NA		NA T			
-	1	7.01(8)	The least of the	NA	NA		

1		1,30 Required	Natural/Ventilated					
	Upper floor	Requise	reatural ventilated					
_	Fire Extinguishers							
	Total numbers	06 Nos.	07 Nos.	MR				
	Types	ABC/Co2 Type	Provided	MR				
	IS marking	Required	Provided					
	First-Aid Hose Reels			MR				
	Total numbers on each floor	01 Nos.	01 Nos.	MR				
	Length of hose reel hose	30 m	30 m	MR				
1	Nozzle diameter	5 mm	5 mm	MR				
7.	Automatic fire detection a	nd alarming system		IVIK				
	Type of detectors	Required	Provided	MR				
	Location of Main Panel	Required	Provided at mezzanine floor	MR				
B	Location of Repeater Panel	NA	NA	NA				
	Alternate source of power	Required	Provided	MR				
	Hooters' Location	Required	Provided	MR				
8.	MOEFA	NA	NA	NA				
9.	Public Address System	Required	Provided	MR				
10.	IVIN							
100	Basement	NA	NA	NA				
1	Entire restaurant	NA	NA	NA				
	Sprinkler above false ceiling	NA	NA	NA				
11.		Address of the State						
	Size of riser/down-comer	NA	NA	NA				
	Number of hydrants per floor	NA	NA	NA				
-	Hose Box	NA	NA	NA				
12.								
-	Total number of hydrants	NA	NA	NA				
	Hose Box	NA	NA	NA				
13	1 0 0		Vitability 1					
1	Ground Level		outsides Alleria					
	Discharge of main Pump	NA	NA	NA				
1	Head of Main pump	NA	NA	NA				
	Number of main pumps	NA	NA	NA				
	Jockey Pump out put	NA	NA	NA				
	Jockey pump head	NA	NA	NA				
	Standby Pump out put	NA	NA	NA				
	Standby Pump Head	NA	NA	NA				
	Auto Starting/Manual Stopping	NA	NA	NA				
	Pump House Access	NA	NA	NA				
	Terrace level							
-	Discharge of pump	225 1	0051					
	Head of the pump	225 lpm 25 m	225 lpm	MR				
	- road of the pump	25 III	25 m	MR				

M/s Rabbi Guest House, 1141, Haveli Sadar Sadoor, Matia Mahal, Jama Masjid, Delhi.

M/s Rabbi Guest House, 1141, Haveli Sadar Sadoor, Matia Mahal, Jama Masjid, Delhi.

	Power Supply	Required	Provided	MR		
	Auto Starting of pump	Required	Provided	MR		
14.	Captive Water Storage for fire fighting					
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA	NA		
	Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	Overhead Tank capacity	25,00 ltrs	25,00 ltrs	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	Pressurization of Lift	NA	NA	NA		
	Shaft Pressurization of Lift	NA	NA	NA		
	lobby	NA	NA	NA		
	Communication In lift	IVA	\$	NA		
	Car Fireman's Grounding	NA	NA	NA		
	Switch		NA	NA		
	Lift Signage	NA	Provided	MR		
17.	Standby power supply	Required	Provided			
18.	Defuge Area					
10.	Total Area	NA	NA NA	NA NA		
	Location	NA	NA.			
19.	Fire Control Room NA					
	Detector System Panel	NA	NA NA	NA		
	Flow Switch Panel	NA NA	NA NA	NA		
	PA System Panel	NA	NA NA	NA		
	Battery backup	NA	NA NA	NA		
	Building Floor Plans	NA		NA		
20.	Special Fire Protection System for Protection of special Risks, if any:	NA	NA	IXX		

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Keeping in view of deemed compliance of the minimum standards of fire prevention and fire safety measures as required under rules it is recommended to renew the Fire Safety Certificate issued vide letter no. F6DFS/MS/GH/NDZ/2022/400 dated 017.09/2022 under

Rule 37 of the Delhi Fire Service Rules 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/Jawala Puri