

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI-HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/GH/SZ/2025/BNOT 104

Dated: 06/06/2025

To

The Joint Commissioner of Police (Licensing), 1st Floor, Police Station, Defence Colony, New Delhi.

Ref:

etl.mcdonline application ID no. 2025050708036

Sub:

Regarding issuance of Fire Safety Certificate in r/o M/s Rajwada Banquet Hall (A Unit of Gk Food India) located at Plot No. 1A, Star City Mall, Mayur Vihar, Phase - I, New Delhi-91.

Sir,

This has reference to the etl.mcdonline application ID no. 2025050708036 on the subject cited above. In this context it is informed that the said Banquet Hall was inspected by officer concerned of this department on 22.05.2025 in the presence of Mr. Nadeem Malik (Manager) and it was observed that the shortcomings issued to the Banquet Hall vide letter no. F.6/DFS/MS/BNQT/2025/SZ/73 dated 01.05.2025 (Photocopy overleaf) has not been rectified completely till date. Hence FSC to the building cannot be considered at this stage.

In view of above shortcomings, the application for issuance of Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Statutory Authority may take suitable necessary action as deemed fit.

End: as above

Yours faithfully,

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service



GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI- 110001**

No. F.6/DFS/MS/BNQT/2025/SZ/ 73 Dated: 01./05./2025

To

The Addl. Commissioner of Police, Lic Branch, 1st Floor PS Defence Colony, New Delhi 110049.

Sub: Regarding issuance of FSC in r/o M/s Rajwada Banquet (A Unit of GK Food India) at Plot No 1A, Star City Mall, Mayur Vihar Ph-I, New Delhi 110091

Sir,

This has reference to your MCD Portal ID 2025040105132 dated 01/04/2025 on the subject cited above. In this connection, this is to inform you that the above mentioned premise was visited by the officers concerned of this department on 12.04.2025 in the presence of Mr. Vinay Aggarwal to verify the fire safety measures installed in the building. Accordingly fire safety arrangement were tested / checked and found following observation.

1. The Rear side exit gate found blocked.

2. Automatic detection system found removed at some area in banquet hall.

MOEFA found removed at some locations of banquet hall.

4. Automatic sprinkler System found removed at some area in banquet hall.

5. Exit signage's found removed.

In view of above Shortcomings, the application for issuance Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the owner/occupier. The Licensing authority/ Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

I FIRE SERVICE