

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

499/10/2015

No. F6/DFS/MS/GH/NDZ/2025/ 525

FIRE SAFETY CERTIFICATE

Certified that the Rossette Guest House, located at 8708, D.B.G. Road, Pahar Ganj, New Delhi110055, comprised of Basement + Ground + 03 Upper Floors, basement – storage purpose with separate exit
& entry and same is other's property, ground floor – reception + lobby + 06 guest room, 1st floor to 3rd floor
– 06 guest rooms at each floor, Total 24 guest rooms, owned/occupied by Rossette Guest House, was issued
Fire Safety Certificate by this department vide letter no. F6/DFS/MS/GH/NDZ/2022/169 dated 29/03/2022.
The said premise was re-inspected by the officer concerned of this department on03/10/2025 in the presence
of Sh. Ram Kumar (Manager) and found that the said building have deemed complied with the fire
prevention and fire safety requirements in accordance with the Rule 33 of the Delhi Fire Service Rules, 2010
and that the premises/building is fit for occupancy class of "Residential Building" Sub Division-A-1, ground
floor – reception + lobby + 06 guest room, 1st floor to 3rd floor – 06 guest rooms at each floor, Total 24 guest
rooms up to 3rd floor only, with effect from 17 10 2025 for a period of three years in accordance with
Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the
conditions under Rule 38 of the Delhi Fire Service Rules 2010 printed below.

Issued on 17 10 2015 at New Delhi by

Dr. S.K. Tomar Dy. Chief Fire Officer

New Delhi Zone

Copy to:-

1. The Commissioner, Municipal Corporation of Delhi, Civic Centre, Minto Road, New Delhi-110002:- in r/o computer id no. 2025091713507 dated 17/09/2025: to ensure occupancy as detailed above and deviation, if any.

2. The Authorized Signatory, Rossette Guest House, located at 8708, D.B.G. Road, Pahar Ganj, New

Delhi-110055.

Conditions for the validity of fire safety certificate:-

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.

4. Any deviation, with regards to construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.

5. The Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction / unauthorized use of land if any.

6. All comments / directions of licensing Department shall always be permitted and followed.

7. The owner /occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner / occupier shall apply for renewal of this Fire Safety Certificate to the Director in 'Form J' (sub Rule (1) of Rule 37) along with copy of the certificate, six months prior to its expiry.

9. The basement shall be used as per BBL.

10. Any flammable material for interior decoration is prohibited.

INSPECTION REPORT

 Name & address of the building: M/s Rossette Guest House, located at 8708, DBG Road, Paharganj, New Delhi-110055

2. Type of Occupancy : Residential, Sub Divison-A-1, comprised of Basement +

Ground + 03 Upper Floors, basement-storage purpose with separate exit & entry and it is other's property, ground floor-reception+lobby+06 guest rooms, 1st floor to 3rd floor-06 guest rooms ateach floor, Total 24 guest

rooms : Renewal

3. Type of Case : Renewa

4. Details of previous NOC : F6/DFS/MS/GH/NDZ/2022/169 dated 29/03/2022

5. Fire Safety directives Letter No. : Nil

6. Date of inspection : 03/10/2025

7. Name of the Inspecting Officer: Aman Kumar Lathar, ADO (JWP)

8. Name and designation of Officer

from the building side : Sh. Ram Kumar (Manager)

9. Year of Construction : 2007

10 Applicant's letter no. : 2025091713507dated 17/09/2025

S No	Minimum standards on fire prevention and fire safety U/R 33	Requirements Existing fire safety arrangements	Provided at site	Remarks MR/NMR			
1.	Access of building NA NA NA						
-	Road width	NA	18 m	NA NA			
	Gate width	NA	NA	NA NA			
	 Width of internal road 	NA	NA	IVA			
2.	Number, width, Type & Arrange	ments of exits					
2.	a. Number of staircases			MR			
	Upper floors	01 no.	Provided				
	Basements	01 no.	Provided	MR			
. 1	b. Width of staircases		T de les Land	1 10			
	 Upper floors 	0.80 m	1.23 m	MR			
	Basements	0:80 m	1.23 m	MR			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	NA	NA	NA			
1	d. No of continuous staircase to terrace	NA	NA	NA			
	e. Width Of Corridor	NA	NA	NA			
1	f. Door Size	1.0 m	Provided	MR			
3.	Compartmentation		1 H				
J.	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	 Fire Rating of shaft 	NA	NA	NA			
	door	NA	NA NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers		L. Judge				
4.	Smoke managements System						
1	Basements	Required	Exhaust Fan	MR			
	Upper floors	Required	Exhaust Fan	MR			
	Q			ar P			

	•			
5.	Fire Extinguishers			T N
	 Total numbers 	12nos.	Provided	MR
	• Types	ABC & CO ₂	Provided	MR
	 IS marking 		Provided	MR
6.	First - Aid Hose Reels	ISI marked	Flovided	
	 Total numbers on each floor 	01	Provided	MR
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	S	Provided	MR
7.	Automatic fire detection and alarming	system	110	
	Type of detectors	CO type	Provided	MR
	 Location of Main Panel 	Required	Provided	MR
	 Location of Repeater Panel 	NA	NA	NA
	Alternate source of power	Required	Provided	MR
	Hooters' Location	Required	Provided	MR
3.	MOEFA			MR
).	Public Address System	Required	Provided	MR
0.	Automatic Sprinkler System	Required	Provided	IVIK
	Basements	Required	Provided	MR
	Upper Floor	NA	NA NA	NA
	Sprinkler above false ceiling	NA NA	NA NA	NA NA
1.	Internal Hydrants:	INA	NA	INA
	Size of riser/down-comer	NA	NA	NA
	Number of hydrants per floor	NA NA	NA NA	NA NA
	Hose Box	NA NA	NA NA	NA NA
2.	Yard Hydrants	MA	INA	INA
	 Total number of hydrants 	NA	NA	NA
	Hose Box	NA NA	NA NA	NA NA
3.	Pumping Arrangements:		TVZ	IVA
	Ground Level			
	Discharge of main pump	NA	NA	NA
	Head of main pump	NA	NA NA	NA
	Number of main pumps	NA	NA	NA
	Jockey pump out put	NA	NA	NA
	Jockey pump head	NA	NA	NA
	Standby Pump out put	NA	NA	NA
	> Standby Pump Head	NA	NA	NA
	Auto Staring/Manual	NA	NA	NA
	stopping	NA	NA	NA
	> Pump House Access	85.01 II. III	V-1	- 11.
	Terrace level	207 7 77 - 1		70.
	Discharge of pump	225 LPM	Provided	MR
I	> Head of the pump	30 m	Provided	MR
1	Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
(Captive water Storage for fire fighting:			20900
	 Under ground tank capacity 	NA	NA	NA
	> Draw off connection	NA	NA	NA
	Fire service inlet	NA	NA	NA
	> Access to tank	NA	NA	NA
	Overhead Tank capacity	5000ltrs.	Provided	MR
F	xit Signage	Required	Provided	MR
	rovision of Lifts			1
1		NA	NA	NA
	> Pressurization of Lift Shaft	NA NA	NA	NA
	> Pressurization of lift lobby		NA I	NA
	Communication in lift Car	NA NA	NA NA	NA
	> Fireman's Grounding Switch	NA		NA
		NA	NA	INA
	➤ Lift Signage	Required	Provided	MR

18.	Refuge Area	***		NTA.		
	➤ Total area	NA	NA	NA		
1	> Location	NA	NA	NA		
9.	Fire control room					
	 Detector system panel Flow Switch Panel PA System Panel 	NA	NA	NA		
		NA	NA	NA		
		NA	NA	NA		
	> Battery backup	NA	NA	NA		
	> Building Floor Plans	NA	NA	NA		
20.	Special Fire Protection Systems for Protection of special Risks, if any;	NA	NA	NA		

The fire protection systems provided in the building were checked and found functional at the time of inspection. The shortcomings issued vide letter no. F.6/DFS/MS/GH/2025/SZ/389 dated 16/09/2025 found rectified.

Keeping in view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, **the FSC issued** vide letter no.F6/DFS/MS/GH/NDZ/2022/169 dated 29/03/2022,renewal under rule 37of the Delhi Fire Service Rule 2010, **is recommended**.

Accordingly, DFA is put up for approval & signature please.

Aman Kumar Lathar ADO (WP)

DO (CD) Andrealists

Dy. CFO (APOZ)

13/10/2r

Principal Director

m. Cts

14/10/2

Dy (50 (402)

ADOIBY RN

Sir, F.J. letter is Frit-up for your organative!

16/10/L7

placeded

D(FO(20172)

MS