

C/158

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS : DELHI FIRE SERVICE : NEW DELHI - 110001

No.F.6/DFS/MS/NDZ/2025/ 6 6

Dated: / 7 /02/2025

To

The Authorized Signatory,
Estate Maintenance Co. Padma Tower-II,
22, Rajindra Place, New Delhi-110008.

Sub: - Regarding renewal of fire safety certificate in r/o Estate Maintenance Co. Padma Tower-II, 22, Rajindra Place, New Delhi-110008.

Sir,

This has a reference to your letter no. EHC/DFS/2024 dated 01/01/2025, on the subject cited above. In this connection, it is to inform you that the premises was inspected by the officers concerned of this department on 10/02/2025 in the presence of Mr. Chandeshwar and observed that the following shortcomings are observed:

1. Fire check doors found broken and also found removed at some floors. Door closer also found removed.
2. Smoke managements system found nonfunctional in basement and also not provided at Upper floors.
3. Detectors not provided at some offices and also found nonfunctional at some offices.
4. PA system found nonfunctional.
5. lift signage's & exit signages are not provided.

In view of above, case is rejected with a request to rectify the above shortcomings at the earliest for further consideration in the matter.

Yours faithfully

(K. Garg)
DIRECTOR
Delhi Fire Service

Copy to:

1. The Commissioner, MCD, Civic Centre, New Delhi.