

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/2025/WZ/School/ 1230

Dated: 06/10/2025

FIRE SAFETY CERTIFICATE

Certified that the Ryan International School, H-3, Sector-11, Rohini, Delhi-85, comprised of Ground + 02 upper floors has already been issued FSC by this department vide letter No. F.6/DFS/MS/2022/WZ/School/689 dated 23.06.2022. The school building was re-inspected by the officer concerned of this department on 24.09.2025 in the presence of Mrs. Parul Narang (Principal) and found that now school building is comprised of Ground + 03 upper floors deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class 'Group B Educational' (for Ground + 03 upper floors) with effect from 06 10 2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 06 10 2025 at New Delhi by

M.K.Chattopadhyay Dy. Chief Fire Officer

Copy to :-

1. The Director of Education, Old Secretariat, Delhi

2. The Principal, Ryan International School, H-3, Sector-11, Rohini, Delhi-85.

Conditions for the validity of fire safety certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.

Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of firefighting system.

5. The owner/ occupier shall submit a declaration every year in Form 'K'[sub rule (2) of Rule 38] provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction (Clause 2.9.2 of UBBL-2016) or Alteration (Clause

1.4.3 of UBBL-2016), if any.

7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of Rule 37] along with a copy of this Certificate, six months prior to its expiry."

INSPECTION REPORT 1. Name & address of the building: Ryan International School, H-3, Sector-11, Rohini, Delhi-85. : Additional/Alternation (Ground + 03 upper floors) 4. Details of Previous NOC : (F.6/DFS/MS/2022/WZ/School/689 dated 23.06.2022 previous

5. Fire Safety directives letter No

: F.6/DFS//MS/2022/WZ/School/689 dated 23.06.2022. 6. Date of inspection 7. Name of Inspecting Officer

: A.K.Sharma ADO(Rohini) 8. Name and designation of officers

From the building side

: Mrs. Parul Narang (Principal) 9. Year of Construction

: 2005 & 2025 10. Applicant's letter No.

. No.	and fire safety U/R 33	968 dated 15.09.2025. NBC Part-IV	Provided at site	Remarks	
	Access to building	Requirement	and at site	MR/NMR	
	Road width			MINIMIR	
	• Gate width	Accessible	Accessible	MR	
	Width of internal road	Accessible	4.5m	MR	
2.	Number Width Town 2	-NA-	-NA-	-NA-	
	Number, Width, Type & Arrangement of a. Number of staircases	of Exits		-NA-	
	• Upper Floors				
	Basements	02nos.	02nos.	MR	
		-NA-	-NA-	0.000000	
	b. Width of staircases		141	-NA-	
	Upper Floor	1.5m	1.5m	1	
	Basements	-NA-	-NA-	MR	
	c. Protection of exits		11/1-	-NA-	
	Fire check door	-NA-	371		
32	 Pressurization 	774	-NA-	-NA-	
	d. No. of continuous staircases to terrace		01nos.	NA	
	e. Width of Corridor	- Toquilou	Provided	MR	
	f. Door Size	1.5m	Provided	MR	
3.	Compartmentation	1.0m & 1.2m	provided	MR	
	Fire check door				
	• Sealing of electrical shafts	-NA-	-NA-	-NA-	
	• Fire Rating of shaft door	-NA-	-NA-		
	Water Curtain	-NA-	-NA-	-NA-	
	 Fire Dampers 	-NA-		-NA-	
4.	Smoke Management System	-NA-	-NA-	-NA-	
	Basements Basements				
	The state of the s	-NA-	NA		
	Upper floors		-NA- Natural ventilation	-NA-	
3.	Fire Extinguishers	Pet tiout	Natural ventilation	MR	
	Total numbers	12000			
	• Types	12nos. ABC/CO2	15nos.	MR	
6.	• IS marking	ISI marked	ABC/CO2	MR	
9,	First-Aid Hose Reels	151 marked	Yes	MR	
	Total numbers on each floor	01nos.	n		
	Length of hose reel hose	30mm	Provided	MR	
7.	Nozzle diameter Automatic first line		Provided	MR MR	
,,	Trovided				
	Type of detectors	-NA-	NIA		
	Location of Main Panel Location of Panester Panester	-NA-	-NA-	-NA-	
	200 Library of Repeater Panel	-NA-	-NA-	-NA-	
	Alternate source of power	-NA-	-NA-		
	by		-NA-	-NA-	

)			
	Hooters' Location	-NA-	-NA-	-NA-			
	MOEFA	-NA-	-NA-	-NA-			
	Public Address System	-NA-	-NA-	-NA-			
0.	Automatic Sprinkler System			27.1			
0.	Basement	-NA-	-NA-	-NA-			
	Ground & Upper Floors	-NA-	-NA-	-NA-			
	Sprinkler above false ceiling	-NA-	-NA-	-NA-			
1.	Internal Hydrants						
-	Size of riser/down-comer	-NA-	01 DC system	-NA-			
	 Number of hydrants per floor 	-NA-	01nos.	-NA-			
	Hose Box	-NA-	01nos.	-NA-			
2.	Yard Hydrants	-		274			
	Total number of hydrants	-NA-	-NA-	-NA-			
	Hose Box	-NA-	-NA-	-NA-			
3.	Pumping Arrangements						
	Ground Level		371	27.4			
	Discharge of main Pump	-NA-	-NA-	-NA-			
	Head of Main pump	-NA-	-NA-	-NA-			
	Number of main pumps	-NA-	-NA-	-NA-			
	Jockey Pump out put	-NA-	-NA-	-NA-			
	Jockey pump head	-NA-	-NA-	-NA-			
	> Standby Pump out put	-NA-	-NA-	-NA-			
	> Standby Pump Head	-NA-	-NA-	-NA-			
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-			
	> Pump House Access	-NA-	-NA-	-NA-			
	Terrace level						
	> Discharge of pump	450lpm	450lpm	MR			
	> Head of the pump	40m	40m	MR			
	> Power Supply	Required	Provided	MR			
	Auto Starting of pump	Required	Provided	MR			
14.	Captive Water Storage for fire fighting						
	Underground tank capacity	-NA-	-NA-	-NA-			
	> Draw-off connection	-NA-	-NA-	-NA-			
	Fire service inlet	-NA-	-NA-	-NA-			
	Access to tank	-NA-	-NA-	-NA-			
	Overhead Tank capacity	10,000ltr	10,000ltr	MR			
15.	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts. Under installation						
	Pressurization of Lift Shaft	-NA-	-NA-	-NA-			
	Pressurization of Lift Shalt Pressurization of Lift lobby	-NA-	-NA-	-NA-			
			-NA-	-NA-			
	Communication In lift Car	-NA-					
	 Communication In lift Car Fireman's Grounding Switch 	-NA-					
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	-NA-	-NA-	-NA-			
1.7	Fireman's Grounding SwitchLift Signage	-NA-	-NA-	-NA-			
	 Fireman's Grounding Switch Lift Signage Standby power supply	-NA-	-NA-	-NA-			
	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. 	-NA- -NA-	-NA- -NA- -NA-	-NA- -NA- -NA-			
	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area 	-NA- -NA- -NA-	-NA- -NA- -NA-	-NA- -NA- -NA-			
18.	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location 	-NA- -NA-	-NA- -NA- -NA-	-NA- -NA- -NA-			
	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room 	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA-			
18.	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel 	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA- -NA-			
18.	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel Flow Switch Panel 	-NA- -NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA- -NA-			
17. 18.	 Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel 	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA-	-NA- -NA- -NA- -NA- -NA-			

1 . .

NA-			
NA Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-
Accordingly, the fire protection systems provided and found in working condition at the time of inspection with the substantial compliance of safety required as stipulated in NBC Part-4, and redated 10.09.2025, under the rules it is recommend of the Delhi Fire Service Rule 2010.	ction. the minimum stand emoval of shortco	dards on fire preventi mings issued vide let	on and fire ter no. 720
•		Chuy 25	a C
	Sig Na	nature of the Inspection	ng Officer ar Sharma
DO (NW) N/A			
Dy. CFO (WZ) Wash about for	e Check de	or in Staircas	ue as
Dy. CFO (WZ) What about fir recommended in qui	lalines?	di	
Ato (Rohini)		27/9	Jans Jdi w
Sw, it is a l	ow-rise cos	as pur No	se.
doesn't re	Deane		
Abo (Rohin) Sir, it is a l doesn't re Resultmin	1.00	Juno	
		140 V29	119/20
Desocusts	3010		
Cfo - not availab	ne (20/7		\
Pero (usz) Cfo - not availab Principal Direct	ui Dy	. cro ta)
	Dyle	e' (ms) ps/10	S
ADO (Robini)			
	Rin	letter to prof	Sigflean
Deta		. (