GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/School/SZ/2025/ 673

Dated: - 21/08/2025

To,

The Principal, Sanjeevani Public School, B-65 & 66, Arya Samaj Road, Uttam Nagar, New Delhi-110059.

Sub: - Regarding issuance of "FSC" from fire safety point of view in r/o Sanjeevani Public School at B-65 & 66, Arya Samaj Road, Uttam Nagar, New Delhi-59.

Sir,

Please refer to your letter No. Nil, dated 20.06.2025, on the subject cited above. In this connection it is to inform you that the above said school building have been inspected by the officer concerned of this department, in presence of Principal of the school on dated 04.08.2025, to check the status of the shortcomings already pointed out by this department vide letter No. F.6/DFS/MS/School/2020/SZ/36 dated 17.01.2020. During the course of inspection, it was observed that the shortcomings are not fully complied.

In view of the above, issuance of 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter and running school in absence of requisite fire safety arrangements shall be at the risk & liability of the school management.

Yours faithfully

(Virendra Singh) Chief Fire Officer

Copy to:-

1.

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/School/2020/SZ 36

Dated: 17/01/2020

To,

The Manager, Sanjeevani Public School, B-65 & 66, Arya Samaj Road, Uttam Nagar, New Delhi-110059

Sub: - Regarding issuance of Fire Safety Certificate in r/o Sanjeevani Public School, B-65 & 66, Arya Samaj Road, Uttam Nagar, New Delhi-110059

Sir/Madam,

This has reference to your Letter No. Nil dated 14.11.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 19.12.2019 to see the compliance of the requisite fire safety measures. Smt. Malla (Principal) was present at the time of inspection.

During the course of inspection it was observed that school building comprised of Ground plus two upper floors. The upper floors are served by single staircase having width 88 cms. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcomings were observed:-

1. The upper floors are served by single staircase having width 88 cms against required single staircase having width 150 cms, therefore staircase having width 88 cms is to be increased upto 150 cms or an additional staircase having width not less than 75 cms is to be provided from ground floor to terrace.

2. Door width is 90 cms against required width of 100 cms.

3. Required fire extinguishers are not provided. Seven fire extinguishers of DCP type/CO₂ type 2.5 Kg Capacity each are require to be provided.

4. Hose reel system not provided.

5. Fire pump of 450 LPM capacity not provided.

6. Overhead water storage tank of 10,000 ltrs. capacity not provided.

7. Exit signs are not provided.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate. It is further advice that email of school may also be intimated to this department for record purpose.

Copy to:-

Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054

(with a request to take further action as school does not have fire NOC)

DIRECTOR

DELHI FIRE SERVICE