

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001



lo. F6/DFS/MS/School/NDZ/2025/ 416

Dated: 20 /05/2025

To,

The Principal,
Sardar Patel Public School
108, Village Chilla Saronda,
Mayur Vihar Extn., Delhi – 110091.

Subject: - Regarding grant of Fire Safety Certificate in r/o Sardar Patel Public School located at 108, Village Chilla Saronda, Mayur Vihar Extn., Delhi – 110091.

Sir,

This has a reference to Outdoor diary No. 15131 dated 28/04/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officers concerned of this department on 09/05/2025 in the presence of Mr. Surajmal Verma (Manager) and observed that building comprised of ground plus two upper floors.

Following shortcomings were observed during time of inspection:

- 1. First-Aid-Hose Reel found removed.
- 2. Terrace level fire pump capacity of 450 LPM found removed.
- 3. Terrace fire water tank of 10,000 liters found removed
- 4. Exit & floors Signage's not provided at strategic location in the building

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

DIRECTOR

Copy to: -

1. The Director of Education, East Delhi Municipal Corporation, 419, Udyog Sadan, Patparganj Industrial Area, Delhi - 110092