## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6/DFS/MS/GH/2025/SZ/ 4 83

Dated: .02/09/2025

## **FIRE SAFETY CERTIFICATE**

Certified that the Lodging House in the Name & Style of M/s Shri Om Guest House located at 2036 First Floor, H.C. Sen Road, Chandni Chowk, Delhi-110006 comprised of Ground Mezzanine plus two upper floors, but guest house running at 1st Floor only (with 09 Guest Rooms) was issued Fire Safety Certificate by this department vide letter No.F.6/DFS/MS/GH/NDZ/2021/501 dated 15.11.2021. The premise was re-inspected by the officer concerned of this department on 20/08/2025 in the presence of Mr. Nikesh (Accountant) & Mr. Dinesh Kumar (Manager) and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy class "Residential, Group-A" (09 Guest Rooms with 09 Beds at 1st floor only) with effect from and validity up to 31/03/2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 02 09 /2025 at New Delhi by

CHIEF FIRE OFFICER **DELHI FIRE SERVICE** 

Copy to: -

1. The Commissioner, MCD, Civic Centre New Delhi, to ensure the occupancy as detailed above and deviation (if any). (Ref. MCD Portal ID 2025073112109 dated 31.06.2025)

## Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

system.

The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if

any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry."

7. This Fire Safety Certificate is valid for 1st floor only having 09 guest rooms.

	· D							
	1		INSPEC	CTION REPORT				
1.	1. Name & address of the building  M/s Shri Om Guest House located at 2036 First Fl Road, Chandni Chowk, Delhi-110006.							
2.	De of Occi	pancy	Resider	ntial Group A-1				
_	3. Comprised of building Ground			l + Mezzanine + 02 ι	+ Mezzanine + 02 upper floors			
4.	Type of Case		Renew	al				
5.	5. Details of Previous NOC F.6/DFS			S/MS/GH/NDZ/202	1/501 dated 15.11.2021	for 09 G/Roon		
6.	Fire Safety directives letter No -NA-							
7. Q	Date of inspec			8.2025				
	Name of Insp				Rajesh Kumar ADO (BCP)			
	From the buil	and the second s			Mr. Dinesh Kumar (M	(anager)		
	. Year of Const		1969 o	n MCD Portal				
	Applicant's le	tter No.	Online	application No.2025	073112109 dated 31.0	6.2025		
i. Io	Minimum St and fire safe	andards on fire prev by U/R 33	ention	Requirement/ Existing fire safety	Provided at site	Remarks MR/NMR		
•	Access to bu	lding		arrangement				
	Road	width		-NA-	20m	-NA-		
	Gate	width		-NA-	-NA-	7 (200)		
		of internal road		-NA-		-NA-		
		dth, Type & Arrang	om c=4 - f		-NA-	-NA-		
	a. Number o	f staircases	ement of	EXIUS				
			01					
	Upper Floors     Basements		01nos.	01nos.	MR			
	b. Width of			-NA-	-NA-	-NA-		
	Upper Floor		0.80m	0.90m	MR			
	Basements		-NA-	-NA-	-NA-			
	c. Protectio	5/5/22/2005/05/		2.8		,		
	• Fir	e check door	724	-NA-	-NA-	-NA-		
	• ]	Pressurization		-NA-	-NA-	-NA-		
	d. No. of con	tinuous staircases to	terrace	01nos.	01nos.	MR		
	e. Width of	Corridor		-NA-	-NA-	-NA-		
	f. Door Size			0.80m	0.85m	MR		
	Compartmentation				0.05111	IVIK		
	a) Fire c	heck door	for	-NA-	-NA-	N/A		
	b) Sealing of electrical shafts		-NA-	-NA-	-NA-			
	c) Fire Rating of shaft door		-NA-	-NA-	-NA-			
		d) Water Curtain		-NA-		-NA-		
	e) Fire Dampers		-NA-	-NA-	-NA-			
	Smoke Management System		-1101	-NA-	-NA-			
•	a) Basements		-NA-	NIA	E2.00 20			
-	b) Upper floors		Natural/mechanical	-NA-	-NA-			
			- 0	Tatural/Internanteal	Natural	MR		
	Fire Extinguishers		05nos.	Description of				
	a) Total numbers			Provided & functional	MR			
	TOTAL PROPERTY.	b) Types		ABC/CO2	Provided	MR		
	c) IS marking		ISI marked	Provided	MR			
5.	First-Aid Hose Reels			01				
	a) Total numbers on each floor		01nos.	Provided & functional	MR			
	b) Lengt	h of hose reel hose		30mm	Provided	MR		

	c) Nozzle diamet					
7.	1 1022le diameter		Provided	MR		
	Automatic fire detection and alarming system  a) Type of detectors  CO detectors  Provided  Provided					
	- JPC of detectors	CO detectors	Provided	MR		
	- Soution of Iviain Panel	At 1st floor	Provided	MR		
	The state of the s	-NA-	-NA-	-NA-		
	d) Alternate source of power	-NA-	-NA-	-NA-		
8.	e) Hooters' Location  MOEFA	-NA-	-NA-	-NA-		
9.		-NA-	-NA-	-NA-		
10.	Public Address System	-NA-	-NA-	-NA-		
	Automatic Sprinkler System  a) Basement					
		-NA-	-NA-	-NA-		
	b) Ground & Upper Floors	-NA-	-NA-	-NA-		
11.	c) Sprinkler above false ceiling  Internal Hydrants	-NA-	-NA-	-NA-		
	a) Size of : (					
	a) Size of riser/down-comer	-NA-	-NA-	-NA-		
	b) Number of hydrants per floor c) Hose Box	-NA-	-NA-	-NA-		
12.	, and Box	-NA-	-NA-	-NA-		
	- H. W 213 WI AIRIS					
	a) Total number of hydrants	-NA-	-NA-	-NA-		
13.	b) Hose Box	-NA-	-NA-	-NA-		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	-NA-	-NA-	-NA-		
	➤ Head of Main pump	-NA-	-NA-	-NA-		
	➤ Number of main pumps	-NA-	-NA-	-NA-		
	Jockey Pump out put	-NA-	-NA-	-NA-		
	Jockey pump head	-NA-	-NA-	-NA-		
	Standby Pump out put	-NA-	-NA-	-NA-		
	Standby Pump Head	-NA-	-NA-	-NA-		
	Auto Starting/Manual Stopping	-NA-	-NA-	-NA-		
	Pump House Access	-NA-	-NA-	-NA-		
	Terrace level					
	➢ Discharge of pump	225 lpm	Provided	MR		
	> Head of the pump	25 m	Provided	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump	Required	Provided	MR		
4.	Captive Water Storage for fire fighting					
7.	Underground tank capacity	-NA-	-NA-	-NA-		
	> Draw-off connection	-NA-	-NA-	-NA-		
	Fire service inlet	-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
	Access to tank	2500ltr	2500ltr	MR		
	Overhead Tank capacity	Required	Provided	MR		
5.	Exit Signage.					
6.	Provision of Lifts.	-NA-	-NA-	-NA-		
	a) Pressurization of Lift Shaft	-NA-	-NA-	-NA-		
Ī	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-		
1	c) Communication In lift Car	-NA-	-NA-	-NA-		
-	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-		
- 1	4/ 11101111	12.1				

		1
	λ.	25
*	<b>۷</b> ۱	>
•	- 5	1

1	Standby power supply	Required	Da	E S IT	
18.	The first Area				
_	a) Total Area	-NA-	NA		
	b) Location	-NA-	-NA-	-NA-	
19.	Fire Control Room -NANA-				
	a) Detector System Panel	-NA-	-NA-	-NA-	
	b) Flow Switch Panel	-NA-	-NA-	-NA-	
	c) PA System Panel	-NA-	-NA-	-NA-	
	d) Battery backup	-NA-	-NA-	-NA-	
	e) Building Floor Plans	-NA-	-NA-	-NA-	
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-	

Note: As per MCD Portal Application details per floor occupancy is below mentioned.

First Floor: 09 Rooms 09 Nos of Bed

The occupancy per person at per floor is less than of 10 people hence the FCD requirements under clause 7.31 of UBBL is not applicable.

The fire protection system provided in the building were randomly checked and found functional at the time of inspection.

Further, the management has complied all the observation / Shortcoming already issued &

communicated by this department vide letter of even no 318 dated 10/07/2025.

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F.6/DFS/MS/GH/NDZ/2021/501 dated 15.11.2021, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer

Name: Sh. Rajesh Kumar Design: ADO (BCP)

DO (CD)

21/6/25

CFO! Muly SAX

Principal Director

Cto 1

pitup too you

1/9/20

(olser) fetter.

fetter u

219120