



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

421

7/5
आज़ादी का
अमृत महोत्सव

No.F6/DFS/MS/School/SZ/2025/ 704

Dated: 09/09/2025

To

The Principal,
Stanford International School,
133/E-3rd Block, Molarband Extension,
Badarpur, New Delhi-44.

Sub:- Regarding renewal of Fire Safety Certificate in respect of M/s Stanford International School located at 133/E-3rd Block, Molarband Extension, Badarpur, New Delhi-44.

Sir,

With reference to the letter bearing outdoor diary no. 4482 dated 04.08.2025 on the subject cited above, it is informed that the school building was inspected by Assistant Divisional Officer (M. Road) from this department on 22.08.2025 in the presence of Mr. Gagan Kasana (Owner) and following shortcomings were observed during the inspection.

1. Fire Extinguishers are outdated and not adequate.
2. Auto start mechanism of terrace fire pump found removed.
3. Exit signages found removed.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the school management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,


6/9/2025
(Virendra Singh)
Chief Fire Officer

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.