

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE**  
**NEW DELHI**

No. F6/DFS/MS/EH/NDZ/2025/ 144

Dated: 23/04/2025

**FIRE SAFETY CERTIFICATE**

Certified that the Taste Masters, located at C-59, First, Second & Third Floor, Vikas Marg, Preet Vihar, Delhi-110092, restaurant is running at 1<sup>st</sup> Floor, 2<sup>nd</sup> Floor & 3<sup>rd</sup> Floor only, in a building comprised of Basement + Ground + 03 Upper Floors, (Basement & Ground Floor others properties/ Shop & 1<sup>st</sup> Floor to 3<sup>rd</sup> Floors= Restaurant, Owned/Occupied by Taste Masters, was issued Fire Safety Certificate vide Letter No. F6/DFS/MS/EH/NDZ/2021/316 dated 29/10/2021 for 1<sup>st</sup> floor only, The premises was inspected by officer concerned of this department on 17/04/2025 in the presence of Sh. Piyush Chadha and found that the said building/Premises have complied with the fire prevention & fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rule 2010 and found that the said building is fit for occupancy (Group - D) "Assembly" (Restaurant) (for 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floor only) valid upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010. Condition mentioned below.

Issued on 23/04/2025 at New Delhi by.

(Atul Garg)  
Director

Copy to: -

1. The Dy. Health Officer, EDMC Health Department, Shahadra (South Zone), Karkardooma, Shahadara, New Delhi. Online ID No. 2025032404411 dated 24/03/2025.
2. The Owner/occupier, Taste Masters, located at C-59, First, Second & Third Floor, Vikas Marg, Preet Vihar, Delhi-110092.

**Conditions for the validity of FSC:-**

1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
2. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
3. The trained staff should be available round the clock.
4. Any deviations w.r.t. construction etc shall be verified by the concerned building sanctioning agency.
5. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
6. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.
7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in).
9. Any flammable material for interior decoration is prohibited.
10. This NOC/FSC is valid 1<sup>st</sup> Floor, 2<sup>nd</sup> Floor & 3<sup>rd</sup> Floor only.
11. Basement & ground floor are not checked as it is being used by others.

# INSPECTION REPORT

1.	Name & address of the building	Taste Masters, located at C-59, First, Second & Third Floor, Vikas Marg, Preet Vihar, Delhi-110092.		
2.	Type of Occupancy	Restaurant (Assembly) restaurant is running at 1 <sup>st</sup> Floor, 2 <sup>nd</sup> Floor & 3 <sup>rd</sup> Floor only, in a building comprised of Basement + Ground + 03 Upper Floors, [Basement= Storage, Ground Floor= Shop (both others property)] & 1 <sup>st</sup> Floor to 3 <sup>rd</sup> floors= Restaurant.		
3.	Type of Case	New Additional/Alteration		
4.	Details of previous NOC	F6/DFS/MS/EH/NDZ/2021/316 dated 29/10/2021. For 1 <sup>st</sup> Floor only		
5.	Fire Safety directives letter No	NBC Part IV		
6.	Date of inspection	17/04/2025		
7.	Name of the Inspecting Officers	Sarabjeet Singh ADO (MN)		
8.	Name and designation of officers from the building side	Sh. Piyush Chadha		
9.	Year of Construction	1993(As per online application)		
10.	Applicant's letter No.	Online Application No.2025032404411 dated 24/03/2025		
S. No	Minimum Standards on fire prevention and fire safety U/R 33	As per NBC part IV/UBBL	Provided at site	Remarks MR/NMR
1	<b>Access to building</b>			
	• Road width	9.0 mtrs	12 mtrs	MR
	• Gate width	NA	NA	NA
	• Width of internal road	NA	NA	NA
2	<b>Number, Width, Type &amp; Arrangement of Exits</b>			
	a. Number of staircases			
	• Upper Floors	02 nos.	02 nos.	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.5 mtrs	2.0 nos. 1.5 mtrs, 01 nos. 1.10 mtrs	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	Required	Provided	MR
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	NA	NA
	e. Width of Corridor	NA	NA	NA
	f. Door Size	1.5 mtrs	1.5 mtrs	MR
3	<b>Compartmentation.</b>			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	<b>Smoke Management System.</b>			
	• Basements	NA	NA	NA
	• Upper floors	Required	Provided	MR
5	<b>Fire Extinguishers</b>			
	• Total numbers	12 nos.	12 nos.	MR
	• Types	CO <sub>2</sub> , ABC type	Provided	MR
	• IS marking	ISI marked	Provided	MR

2



MIS.				
6	<b>First-Aid Hose Reels.</b>			
	• Total numbers on each floor	01	Provided	MR
	• Length of hose reel hose	30 mtrs	Provided	MR
	• Nozzle diameter	05 mm	Provided	MR
7	<b>Automatic fire detection and alarming system.</b>			
	• Type of detectors	Smoke & Heat	Provided	MR
	• Location of Main Panel	Required	Provided	MR
	• Location of Repeater Panel	Required	Provided	MR
	• Alternate source of power	Required	Provided	MR
	• Hooters' Location	Required	Provided	MR
8	<b>MOEFA</b>			
9	<b>Public Address System.</b>			
		NA	NA	NA
10	<b>Automatic Sprinkler System.</b>			
	• Basement	NA	NA	NA
	• Upper Floor	Required at 3 <sup>rd</sup> floor	Provided	MR
	• Sprinkler above false ceiling	NA	NA	NA
11	<b>Internal Hydrants</b>			
	• Size of riser/down-comer	100 mm	Provided	MR
	• Number of hydrants per floor	01 no.	Provided	MR
	• Hose Box	01 no.	Provided	MR
12	<b>Yard Hydrants.</b>			
	• Total number of hydrants	NA	NA	NA
	• Hose Box	NA	NA	NA
13	<b>Pumping Arrangements.</b>			
	• Ground Level			
	➤ Discharge of main Pump	2280 LPM	Provided	MR
	➤ Head of Main pump	40 mtrs	Provided	MR
	➤ Number of main pumps	02 no.	Provided	MR
	➤ Jockey Pump out put	180 LPM	Provided	MR
	➤ Jockey pump head	40 mtrs	Provided	MR
	➤ Standby Pump out put	2280 LPM	Provided (Instead of D.G pump alternate electric pump provided connected with D.G set)	MR
	➤ Standby Pump Head	40 mtrs	Provided	MR
	➤ Auto Starting/ Manual stopping	Required	Provided	MR
	➤ Pump House Access	Required	Provided	MR
	• Terrace level			
	➤ Discharge of pump	NA	450 LPM	NA
	➤ Head of the pump	NA	NA	NA
	➤ Power Supply	NA	NA	NA
	➤ Auto Starting of pump	NA	NA	NA
14	<b>Captive Water Storage for fire fighting.</b>			
	• Underground tank capacity	1,00,000 ltrs	Provided on Terrace	MR
	➤ Draw-off connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	➤ Access to tank	Required	Provided	MR
	• Overhead Tank capacity	10,000 ltrs	Provided	MR

15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	NA	NA	NA
	• Pressurization of Lift lobby	NA	NA	NA
	• Communication In lift Car	NA	NA	NA
	• Fireman's Grounding Switch	NA	NA	NA
	• Lift Signage	NA	NA	NA
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	➤ Total Area	NA	NA	NA
	➤ Location	NA	NA	NA
19	Fire Control Room			
	• Detector System Panel	NA	NA	NA
	• Flow Switch Panel	NA	NA	NA
	• PA System Panel	NA	NA	NA
	• Batter backup	NA	NA	NA
	• Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

Note:- In pumping arrangements, one electric driven stand by pump of capacity 2280 LPM instead of D.G pump is provided connected with D.G set & it may be accepted if permitted.

Earlier all the shortcomings issued by this department have been complied by restaurant/eating house management.

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of minimum standards of fire prevention and fire safety measures as required under the rules, grant of Fire Safety Certificate under the rule 35 of the Delhi Fire Service rules 2010 is recommended please.

DO (ED) ?

~~Dy C.R. (N.D.2)~~

~~22/04/25~~

Signature of the Inspecting Officer  
Name: Sarabjeet Singh  
Designation: Assistant Divisional Officer

Received  
on 23/4/25  
at 1200 hrs

C.F.O.

1- Both staircases should run up to terrace as per plans. clarify.

2- Re examine point no. 13 & 14. ob I/R at N/15

3- why file not routed through DO (ED) through

~~Dy C.F.O. (N.D.2)~~

23/4/2025

P.T.O.