

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

No. F6/DFS/MS/School/SZ/2025/ | | o 8

08/09/2025

## **FIRE SAFETY CERTIFICATE**

Certified that the Vidya Memorial School located at Molarband Extension, Badarpur Border, New Delhi-44, School building comprised of Ground + 02 upper floors, was granted Fire Safety Certificate by this department vide letter no.- F.6/DFS/MS/School/SZ/2022/865 dated 08.05.2022. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 25.08.2025 in the presence of Sh. R. K. Sharma (Owner) and found that the school building has deemed complied with the fire prevention and fire safety requirements in accordance with the Circular no. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Directorate of Education and the school building (Ground + 02 upper floors) is fit for occupancy of Group B "Educational Building" with effect from a strong in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire service Rules, 2010 printed below.

Issued on O.S. Co. S. Land at New Delhi by

(Virendra Singh) Chief Fire Officer ofc 19/25.

Copy to:-

1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.

2. The Principal, Vidya Memorial School located at Molarband Extension, Badarpur Border, New Delhi-44.

## Conditions for the validity of Fire Safety Certificate

1. All the means of escape shall be kept free of all the type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.

5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.

6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub Rule (1) of Rule 37] along with a copy of this certificate, six months prior to its expiry.

1/0 m/1

<u> </u>	Nar	me & address of the building	PECTION REPORT	School located at	Molarband			
•	1741	ne & address of the building	Vidya Memorial School located at Molarband Extension, Badarpur Border, New Delhi-44.					
2	Bui	lding is comprised of	Ground + 02 upper floors					
3		pe of occupancy Education, Group-B						
4	1000	pe of case	Renewal F.6/DFS/MS/School/SZ/2022/865 dated 08.05.2022					
5		tails of previous NOC						
6	Fire safety direction letter no.		F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011					
150								
7	Dat	te of inspection	225.08.2025					
8	Naı	me of the inspecting officers						
9	Name of the designation of		Sh. R. K. Sharma (Owner)					
		icer from the building side	2004 2 2009					
10		ar of construction	2006 & 2008					
11	Applicant's letter no.		Outdoor Diary no. 4461 dated 04.08.2025  Requirement as per   Provided at site   Re					
S.No	12.10	nimum standard of fire evention and fire safety U/R	Requirement as per Rules 35 (6)	Provided at site	MR/NMR			
1	Ac	cess to Building:		***	MR			
	A	Road width	Accessibility	Accessible	NA NA			
	В	Gate width	NA	NA NA	NA			
	C	Width of internal road	NA	14/1				
2	Number, Width, Type and Arrangement of Exits:  A Number of staircases							
	A	T 0	02 nos.	02 nos.	MR			
		b Basement	NA	NA	NA			
	В	Width of staircases		1.20 mtrs & 0.80 -	MR			
		a Upper floor	1 staircase of 1.5 mtrs or if main staircase width is < 1.5 mtrs an additional staircase of 0.75 mtrrs width	0.95 mtrs.				
		1 Dont	is required.	NA	NA			
	C	b Basement Protection of exits	Te later		NA			
		a Fire check door	NA	NA	NA NA			
		b Pressurization	NA	NA 01 no.	MR			
	D	No. of continuous	01 no.	or no.				
	T	staircases to terrace Width of corridor	NA	NA	NA			
	F	Door size	1.0 mtrs.	1.0 mtrs. (class	MR			
	.=.			room)				
3	Co	ompartmentation:	Lari	NA	NA			
	A	Fire check door	NA NA	NA NA	NA			
	B	Sealing of electrical shafts	NA NA	NA	NA			
	D	Fire rating of shaft door Water curtain	NA NA	NA	NA			
	E	Fire dampers	NA	NA	NA			
4		noke Management System:			₩ ₩ 2029/411			
1170	A	Basement	NA	NA	NA NA			
	В	Upper floor	NA	NA	NA			
5.	Fir	re Extinguisher:		Tax				
	A	Total numbers	09 nos.	09 nos.	MR			
	В	Types	CO <sub>2</sub> & ABC	Provided	MR			
	C	ISI marking	Required	Provided	MR			
6	Fir	rst-Aid-Hose Reel:	, Al	No.				
	A	Total numbers of each floor	01 no.	01 no.	MR			
		Length of hose reel hose	30 mtrs.	30 mtrs.	MR			
	В	Deligar of hose reer hose			MR			

7	Automatic Fire Detection and Alarming System:							
	A	Type of detectors	NA NA	NA	NA			
	B	Location of main panel  Location of repeater panel	NA NA	NA NA	NA			
		Alternate source of power	NA NA	The second second	NA			
	D	3	NAMES OF STREET	NA	NA			
	E	Hooters	NA	NA	NA			
8	700000	OEFA:	NA	NA	NA			
9		blic Address System:	NA	NA	NA			
10	Automatic Sprinkler System:							
Į.	A	Basement	NA	NA	NA			
	В	Upper floor	NA	NA	NA			
	C	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants:							
	A	Size of riser/down-comer	NA	NA	NA			
	В	Number of hydrants per floor	NA	NA	NA NA			
	C	Hose box	NA	NA				
12	Yard Hydrants:							
12	A	Total number of hydrants	NA	NA	NTA			
	В	Hose box	NA	NA	NA			
13		mping Arrangements:			NA			
A	Ground level							
	a	Discharge of main pump	NA	NA	150			
	b	Head of main pump	NA	NA NA	NA			
	c	Number of main pumps	NA	NA NA	NA			
	d	Jockey pump out put	NA NA	NA NA	NA			
	e	Jockey pump head	NA NA	NA NA	NA			
	f	Standby pump out put	NA NA	NA NA	NA NA			
	-	Standby pump head	NA	NA NA	NA			
	g h	Auto starting /manual	NA NA	NA NA	NA			
		stopping	10.37E	IVA	NA			
	i	Pump house access	NA	NA	NA			
В	Terrace Level							
	a	Discharge of pump	450 LPM	450 LPM	MR			
	b	Head of the pump	40 mtrs.	40 mtrs.	MR			
	C	Power supply	Required	Provided	MR			
	d	Auto starting of pump	Required	Provided	MR			
14	540	ptive Water Storage for Fire		REAL CHARLES				
	A	Underground tank capacity	NA	NA	NA			
	B	Draw-off connection	NA	NA	NA			
	C	Fire service inlet	NA	NA	NA			
	D	Access to tank	NA	NA	NA			
15	E	Overhead tank capacity it Signage:	10,000 ltrs	10,000 ltrs	MR			
16		ovision of Lifts:	Required	Provided	MR			
10	A	The second secon	Tss.		NTA			
	B	Pressurization of lift shaft Pressurization of lift lobby	NA	NA NA	NA NA			
	C	Communication in lift car	NA NA	NA NA	NA NA			
	D	Firemen's grounding switch	NA NA	NA NA	NA			
	E	Lift signage	NA NA	NA NA	NA			
17	Sta	andby Power Supply:	NA	NA NA	NA			
18	Re	fuge Area:	- AND COLOR	portion (Control of Control of Co				
	A	Total area	NA	NA	NA			
	В	Location	NA	NA	NA			
19	Fir	e Control Room:						
	A	Detector system panel	NA	NA	NA			
	В	Flow switch panel	NA	NA NA	NA			
	C	PA system panel	NA	NA	NA			
	D	Battery backup	NA	NA	NA NA			
	E	Building floor plans bya Memorial School located at Molar	N	NA				

AL

N/8

Vidya Memorial School located at Molarband Extension, Badarpur Border, New Delhi-44.

Special Fire Protection systems for NA NA Protection of special Risks, if any:

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire safety provisions provided in the building were randomly tested, checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter no. F.6/DFS/MS/School/SZ/2022/865 dated 08.05.2022 is recommended to be renewed under Rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

DO (SD)

2 91 2005

Principal Director

Ofo to Do

CFO

619.

ASO (MRd)

Fi is few up ple

06/1/25

CPO .

8 91 2025

Ms