

c-6

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: F.6/DFS/MS/Educational/SZ/2025/06

Dated: - 10/01/2025

To,

The Principal/HOO,
World Class Skill Centre,
ITI, Jail Road, New Delhi.

Sub: - Regarding issuance of FSC from fire safety point of view in r/o World Class Skill Centre at ITI (Industrial Training Institute), Jail Road New Delhi.

Sir,

Please refer to your letter No. F.No.1(29)/PWD/MISC/JR/2022/Pt.File-II/1091-97 dated 31.12.2024, on the subject cited above. In this connection it is to inform you that the above said ITI building have been inspected by the officer concerned of this department, in presence of Sh. Sanjay Panday on dated 06.01.2025, to check the status of the shortcomings already pointed out by this department vide letter No. F6/DFS/MS/2019/SZ/6356 dated 23.10.2019. During the course of inspection, it was observed that the shortcomings are not fully complied except shortcoming No. 05, 06, 07 & 08.

In view of the above, issuance of 'Fire Safety Certificate' cannot be considered at this stage. You are requested to rectify the above-mentioned shortcomings under intimation to this department for taking further necessary action in this matter.

Yours faithfully

(Atul Garg)
Director

Delhi Fire Service

Copy to: -

1. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054.

-for necessary action

2/3

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No: F.6/DFS/MS/2019/SZ / 6356
To,

Dated: 23/10/19

Sh. Pawan Kumar (Ex. Engineer JP),
Delhi Tourism & Transportation Dev. Corp.,
Office of the Executive Engineer (JP), Dilli Haat Janakpuri Project Site,
Behind DTC Bus Depot, Hari Nagar, Janakpuri, New Delhi-110058

Sub: - Regarding issuance of Fire Safety Certificate in r/o World Class Skill Centre at ITI (Industrial Training Institute), Jail Road New Delhi.

Sir,

This has reference to your Letter No. F.No.DTTDC/Engg./EE(JP)/ITI Jail road/2019-20/282 dated 28.08.2019 on the subject cited above. In this connection, it is to inform you that the inspection of above said school building has been carried out by officer concerned of this department on 21.09.2019 to see the requisite fire safety measures. Sh. Goel (A.E DTTDC) was present at the time of inspection.

During the course of inspection it was observed that the building comprised of ground plus two upper floors. The upper floors are served by two staircases having width 155 cms & 150 cms without grills. The building is approachable to the fire fighting vehicles. The electrical wiring was seen concealed and the electric supply was passing through MCB's. The following shortcoming was observed:-

1. The building is not approachable through 4.5 meter wide main gate.
2. The upper floors are served by two staircases having width 155 cms & 150 cms without grills against required two staircases having width 150 cms each clear cut width after finishing from ground floor to terrace.
3. Door width is 105 cms & 120 cms without doors against required 120 cms each clear cut width after installation of doors.
4. Required fire extinguishers are not provided. Seven fire extinguishers of DCP type/CO₂ type 2.5 Kg Capacity each are require to be provided
5. Hose reel system not provided.
6. Fire pump having capacity 450 LPM not provided.
7. Overhead water storage tank of 10,000 ltrs capacity not provided for hose reel system.
8. Exit signs are not provided.

- If student capacity is more than 45 in any class room then double door having width 120 cms is required.

You are advised to rectify the above-mentioned shortcomings for taking further action as necessary for grant of Fire Safety Certificate.

Yours Faithfully,

(ATUL GARG)
CHIEF FIRE OFFICER

Copy to:-

The Chief Project Manager (Tourism),
DTTDC Ltd., Lajpat Nagar, New Delhi
(With a request to take further action as school does not have fire NOC)