

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2025/Canteen/ 21 355

Dated: 26/08/2025

To

The Commissioner MCD, HQ, Civic Centre, Minto Road, Delhi.

Sub: Regarding issuance of fire safety certificate in r/o A. R. Kitchen located at Ground Floor, Sir Ganga Ram Hospital, Delhi-110060.

Please refer to your online MCD Portal ID No-2025073012050 dated: 31/07/2025 on the subject cited above. In this connection this is to inform you that the above mentioned site was visited by the officer concerned of this department on 13/08/2025 in the presence of Sh. Ankit Khanna and kitchen premises comprised of ground floor only to verify the compliance of the shortcomings/ observations already communicated by this department vide letter of even no.F6/DFS/MS/2018/3610 dated 23/08/2048 and observed that the shortcomings have not been removed so far, (Copy enclosed).

Keeping in view of above, issuance of Fire Safety Certificate cannot be considered at this stage.

Yours faithfully

Virendra Singh
Chief Fire Officer
Delhi Fire Service

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

No: P6/DFS/as/2018/3610

Dated: - 23/8/18

To

The Additional Commissioner of Police, Licensing Unit, 1st floor, Police Station Defence Colony, New Delhi.

Sub.:- Regarding issuance of Fire Safety Certificate in r/o M/s. Kanwar Singh Yadav Canteen located at Ground Floor, Sir Ganga Ram Hospital, Rajinder Nagar, Delhi- 60.
Sir,

Please refer to your letter No. 2536/Addl. CP/Lic/EH (DA-IV) dated, New Delhi, the 02.07.2018 on the subject cited above. In this connection, it is to inform you that the aforesaid canteen has been inspected by the officer concerned of this department on 01.08.2018 in presence of Sh. Kanwar Singh Yadav, to check the status of the shortcomings already issued by this department vide letter No. F.6/DFS/MS/Assembly/2017/SZ/1014 dated 20.04.2017 and status is as under: -

| S. No. | Shortcomings | Status |
|--------|--|--------------|
| 1. | The width of the door is 170 cms & 90 cms against required with of | Not Provided |
| | 200 cms (02 no.'s) | |
| 2. | Hose reel system not provided | Not Provided |
| 3. | MOEFA system not provided | Not Provided |
| 4. | Internal hydrant system not provided | Not Provided |
| 5. | Fire pump having capacity 450 LPM not provided | Not Provided |
| 6. | Overhead water storage tank having 10000 lts capacity not provided | Not Provided |
| | Illuminated exit signs are not provided | Not Provided |

In view of the above shortcomings, 'Fire Safety Certificate' cannot be granted at this stage. You are requested to direct the canteen owner to rectify the shortcomings under intimation to this department.

Yours faithfully,

(VIPIN KENTAL) CHIEF FIRE OFFICER

Copy to: -

 Kanwar Singh Yadav S/o Sh. Bishamber Dayal, WZ- 115, Raj Nagar Part- II, Palam Colony, New Delhi- 110045