

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001



Dated: 09/09/2025

FIRE SAFETY CERTIFICATE

Certified that the building of Fr. Agnel School at Gautam Nagar, New Delhi–110049, comprised of basement, ground + 03 upper floors, owned/occupied by Fr. Agnel School, was issued Fire Safety Certificate by this department vide letter No. F.6/DFS/MS/School/2022/SZ/823 dated 29/07/2022. The premise was re-inspected by the officer concerned of this department on 07/08/2025 in the presence of Sh. Robert Samuel (Security Incharge) and found that said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the school premise (B + G + 03 upper floors) is fit for occupancy class "Educational Group B" (School) with effect from 69/69/2025 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>09/09</u>/2025 at New Delhi by

(Virendra Singh)
Chief Fire Officer
Delhi Fire Service

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi-110054

2. The Principal, Fr. Agnel School at Gautam Nagar, New Delhi-110049

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection.

3. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

4. All the staff members must know the correct method of operation of fire-fighting system.

5. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this certificate, prior to its expiry.

7. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

	INSPECTI					
1.	Name & address of the building	Fr. Agnel School located at Gautam Nagar, New Delhi-110049				
2.	Type of Occupancy	Educational (Group B)				
3.	Building Comprised of	There are three blocks interconnected through corridor two blocks are basement, ground + 3 and other Ground + 03 upper floors				
4.	Type of Case	Renewal				
5.	Details of previous NOC No.	F.6/DFS/M	S/Sc	hool/2022/SZ/823 Dt. 2	9.07.2022	
6.	Fire Safety directives Letter No.	DOE Circular/NBC Part IV				
7.	Date of inspection	07/08/2025				
8.	Name of the Inspecting Officer	ADO (SJ)				
9.	Name and designation of Officer from the building side	Mr. Robert Samuel (Security Incharge)				
10.	Year of Construction	1986				
11.	Applicant's letter No.	FASD/SO/ADM-IV/908 dated 17/07/2025 Outdoor Diary No. 3892 dated 18/07/2025				
S.	Minimum standards on fire	Old NOC		Provided at site	Remarks	
No.	prevention and fire safety U/R 33	Requirement MR/NN				
1,-	Access of building			4	_	
	Road width	Accessib	le	09 mtr	MR	
	Gate width	N/A		09 mtr two nos.	N/A	
	Width of internal road	N/A		N/A	N/A	
2.	Number, width, Type & Arrangemen	ts of exits		TO-MANAGE.	. I senting the	
Z.		I OT CALLS	-			
1	AND INVESTMENT COLD PROPERTY CONTROL OF COLD	02 Nos (each)		Provided	MR	
	Upper floors			Block 1: 01no.	MR	
	Basements	02 Nos (each)		Block 2: 1 + 1 ramp	(Old case)	
	b. Width of staircases		T reserve		T	
W	 Upper floors 	Required	1999	1 & 2: 1.50m x 2 in each ck 3: 1.50m & 0.70m	MR (Old case)	
	Basements	Required B		lk 1: 1.50m & Blk 2: .83m & 1.45m ramp	MR	
	c. Protection of exits			E		
	Fire check door	N/A		N/A	N/A	
	Pressurization	N/A		N/A	N/A	
	d. No of continuous staircase to terrace	Required		One in each	MR	
	e. Width of Corridor	N/A		N/A	N/A	
İ	f. Door Size	1.0 mtr		Provided	MR	
3.	Compartmentation	1.0 1110		11071000		
٥.		N/A		N/A	N/A	
F.	Fire check door Seeling of electrical shafts	N/A N/A		N/A	N/A	
	Sealing of electrical shafts Fire Pating of shaft door.	N/A		N/A	N/A	
	Fire Rating of shaft doorWater Curtain	N/A		N/A	N/A	
	water CurtainFire Dampers	N/A		N/A	N/A	
4.	Smoke Managements System	两次公司。因		A		
7.	Basements	30 ACPI	1	Exh. Fan provided	MR	
	Upper floors	12 ACPI		Exh. Fan provided	MR	
5.	Fire Extinguishers			•		
049.45	Total numbers	Required	ΙŢ	50 Nos	MR	
1	Types	ABC / CC		Provided	MR	
1	ISI marking	ISI Marke	_	Provided	MR	
6.	First-Aid Hose Reels					
1 333	Total numbers on each floor	05 Nos		05 Nos	MR	
1	Length of hose reel hose	30m		30m	MR	
	Nozzle diameter	5mm	- 1	5mm	MR	
L		V		F-27-77-27-2		

gr

N-21

7.	Automatic fire detection and alarming system					
	Type of detector	N/A	N/A	N/A		
	Location of Main Panel	N/A	N/A	N/A		
	Location of Repeater Panel	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
0	Hooters' Location	N/A	Provided	N/A		
8.	MOEFA		M. COMMICTATIONS	N/A		
9.	Public Address System	N/A Provided		IN/A		
10.	Automatic Sprinkler System		D! d. d	MD		
	Basements	Required	Provided	MR N/A		
	Upper Floor	N/A	N/A	2011/00/2011		
	Sprinkler above false ceiling	N/A	N/A	N/A		
11.	Internal Hydrants					
	Size of riser/down- comer	100 mm	Provided	MR		
	Number of hydrants per floor	05 Nos	Provided	MR		
	Hose Box	05 Nos	Provided	MR		
12.	Yard Hydrants		3711	27/4		
	 Total number of hydrants 	N/A	· N/A	N/A		
	Hose Box	N/A	N/A	N/A		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main pump	N/A	N/A	N/A		
	Head of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	> Jockey pump out put	N/A	N/A N/A	N/A N/A		
	Jockey pump headStandby Pump out put	N/A N/A	N/A N/A	N/A		
	> Standby Pump Head	N/A	N/A	N/A		
	> Auto Staring/Manual stopping	N/A	N/A	N/A		
	> Pump House Access	N/A	N/A	N/A		
	Terrace level					
	Discharge of pump	450 & 180 LPM		MR		
	➤ Head of the pump	40 mtr each	Provided	MR		
	Power supply	Required	Provided	MR		
	Auto starting of pump	Required	Provided	MR		
14.	Captive water storage for firefighting					
127 1171	Underground tank capacity	N/A	N/A	N/A		
	> Draw of connection	N/A	N/A	N/A		
	> Fire service inlet	N/A	N/A	N/A		
	> Access to tank	N/A	N/A	N/A		
	Overhead Tank capacity	5,000 Ltr	15,000 Ltr (02 Blks)	MR		
15.	Exit Signage	Required	Provided	MR		
16.	Provision of Lifts	-				
10.	> Pressurization of Lift Shaft	N/A	N/A	N/A		
	> Pressurization of lift lobby	N/A	N/A	N/A		
	Communication in lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
	➤ Lift Signage	N/A	N/A	N/A		
17.	Standby Power Supply	N/A	N/A	N/A		
	Refuge Area	# 10 E E				
18.	> Total area	N/A	N/A	N/A		
	- I Utai al Ca	N/A	- 1900 (MARKATA)	N/A		



19. Fire Control Room ➤ Detector system panel	N/A	N/A	N/A	
> Flow Switch Panel	N/A	N/A	N/A	
> PA System Panel	N/A	N/A	N/A	
> Battery backup	N/A	N/A	N/A	
n :Iding Floor Plans	N/A	N/A	N/A	
Building Systems for	Special Fire Protection Systems for Protection of Special Risks, if any;			

The fire protection systems provided in the building were test checked and found functional at the time of inspection. The shortcomings communicated by this department vide letter No. F.6/DFS/MS/School/2025/SZ/527 dated 17/06/2025 have been complied, from fire safety point of view.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety required under the rules, the fire safety certificate issued vide letter No. F.6/DFS/MS/School/2022/SZ/923 dated 29/07/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval & signature please.

Signature of the Inspecting Officer Name: Santosh Kumar

Designation: ADO (SJ)