

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI – 110001

No. F6/DFS/MS/GH/NDZ/2025/ 182

Dated: 04/04 /2025

FIRE SAFETY CERTIFICATE

Issued on 0.4 0.4 2025 at New Delhi by

Delhi Fire Service

Tel: 011-23414000

Copy to:-

- 1. The Commissioner, MCD:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Joint Commissioner of Police (Licensing), 1st Floor, Police Station Defence Colony, New Delhi. w.r.to ID No. 2025031103347 dated 11.03.2025.
- 3. The Licensee, M/s Aira Xing situated at Plot No. 5, Block No. 1, Municipal No. 10086, Desh Bandhu Gupta Road, Pahar Ganj, New Delhi.

Conditions for the validity of fire safety certificate

- 1. This FSC is valid for 1st & 2nd floor only.
- All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 4. The trained fire fighting staff should be available round the clock.
- 5. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction,
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".

9. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto

10. The occupancy of above 2nd floor not allowed as per clause 7.31 in UBBL-2016.

1	NI	ma & add	CTION REPOR				
		me & address of the building	M/s Aira Xing located at Plot No. 5, Block No. 1, Municipal No. 10086, Desh Bandhu Gupt Road, Pahar Ganj, New Delhi.				
2	Bu	ilding is comprised of	(B + Gr. + mez	zanj, new Deini.			
			(B + Gr. + mezzanine + 04 upper floors) Basement - (storage)				
			Ground & mea	Zanino (-L			
			1st & 2nd floor	Ground & mezzanine – (shops) is other property			
			1 st & 2 nd floor – (09 guest rooms at each floor) 2 nd floor – (06 guest rooms) 3 rd & 4 th floor – (not in use as per affidavit date 26.03.2025)				
3		pe of occupancy	Residential Sub Division-A-1				
4	Ту	pe of case	Renewal	DIVISION-A-1			
5	De	tails of previous FSC		(NID7/2022/22 4	10 01 01-1		
6		e safety direction letter no.	F6/DFS/MS/GH/NDZ/2022/23 dated 12.01.2022 Nil				
7	Da	te of inspection	22.03.2025				
8		me of the inspecting officers	ADO (SPM)				
0				na			
*	off	ficer from the building side	Mr. Gopal Khanna				
10	Ye	ar of construction	Old				
11	Ap	pplicant's letter no.					
			Online application no. 2025031103347 dated				
S.No	M	inimum Standards on fire	Requirement/	Provided at Site	Remarks		
	Prevention and fire safety		Existing fire	Trovided at Site	MR/		
	re	quirements U/R 33	safety		NMR		
1	Ac	cess To Building:	arrangements				
•		ad width	Toc.	11.00			
	_	te width	06 mtr.	10 mtr.	MR		
	_	idth of internal road	NA NA	NA	NA		
2		ımber, Width, Type and Arra		NA	NA		
	A	Number of staircases					
		a Upper floor	01 no.	01 no.	MR		
		b Basement	02 nos.	02 nos.	MR		
	В	Width of staircases		- Carantangon			
		a Upper floor	1.25 mtr.	Provided	MR		
	_	b Basement	1.25 mtr.	Provided	MR		
	С	Protection of exits					
		a Fire check door b Pressurization	NA	NA	NA		
	D	No. of continuous staircases	NA 01 no.	NA	NA		
		to terrace	or no.	01 no.	MR		
	E	Width of corridor	1.30 m	Provided	MR		
	F	Door size	1.0 mtr.	1.0 mtr.	MR		
3	Co	mpartmentation:		1	1711		
	A	Fire check door	NA	NA	NA		
	В	Sealing of electrical shafts	NA	NA	NA		
	C	Fire rating of shaft door	NA	NA	NA		
	D	Water curtain	NA	NA	NA		
4	E	Fire dampers	NA	NA	NA		
4	_	oke Management System:					
	A	Upper floors	12 ACPH	Provided/	MR		
	В	Basements	NA	exhaust NA	NA		

5.		Extinguisher:		and the second s				
	A	Total numbers	10 nos.	10 nos.	MR			
	В	Types	CO ₂ & ABC	Provided	MR			
	C	ISI marking	Required	Provided	MR			
6	First-	First-Aid-Hose Reels:						
	A	Total numbers of each floor	01 no.	01 no.	MR			
	В	Length of hose reel hose	30 m	30 m	MR			
	C	Nozzle diameter	05 mm	05 mm	MR			
7	Autor	natic Fire Detection And Alarr	ning System:		C PACO C			
	A	Type of detectors (CO type)	Required	Provided	MR			
	В	Location of main panel	Required	Provided at 1 st floor	MR			
	С	Location of repeater panel	NA	NA	NA			
	D	Alternate source of power	Required	Provided	MR			
_	E	Hooters	Required	Provided	MR			
8	MOE	17/7/2K	Required	Provided	MR			
9	the state of the s	Address System:	Required	Provided	MR			
10		natic Sprinkler System:	T-0	In the	N.ETT			
	A	Basement	Required	Provided	MR			
	В	Upper floor	NA	NA	NA			
	С	Sprinkler above false ceiling	NA	NA	NA			
1	Internal Hydrants:							
	A	size of riser/down-comer	100 mm	100 mm	MR			
	В	Number of hydrants per floor	01	01	MR			
	C	Hose box	01	01	MR			
2	Yard H	lydrants:						
	A	Total number of hydrants	NA	NA	NA			
1	В	Hose box	NA	NA	NA			
3		OHARD ROSANS CARRESTS						
<u>'</u>	Pumping Arrangements: A Ground level							
ŀ	A	Discharge of main pump	NA	NA	NA			
ŀ	a)	Head of main pump	NA	NA	NA			
L	b)		NA	NA	NA			
	c)	Number of main pumps	NA	NA	NA			
	d)	Jockey pump out put	(Principle Inti	NA NA	NA			
	e)	Jockey pump head	NA NA	NA NA	NA			
	f)	Standby pump out put		NA NA	NA			
	g)	Standby pump head	NA NA	NA NA	NA			
	h)	Auto starting /manual stopping		NA NA	NA			
	i)	Pump house access	NA	INA	INA			
	B	Terrace level		450 0 100	MR			
ε	a)	Discharge of pump	Required	450 & 180 LPM				
-	o)	Head of the pump	30 m	30 m	MF			
1 1	<i>,</i> ,		Dagwinad	Provided	MF			
	;)	Power supply	Required	Tiovided				

14

14	Captive Water Storage For Fire Fighting:					
	A	Underground tank capacity	NA NA	Twi		
	B	Draw-off connection	NA	NA	NA	
	C	Fire service inlet	NA NA	NA	NA	
	D	Access to tank	NA NA	NA	NA	
	E	Overhead tank capacity		NA	NA	
15	Ex	it Signage:	10,000 ltrs.	Provided	MR	
16	Provision of Lifts:		Required	Provided	MR	
10	A SAME AND A SAME AND					
	A	Pressurization of lift shaft	NA	NA	NA	
	B	Pressurization of lift lobby	NA	NA	NA	
	С	Communication in lift car	NA	NA	NA NA	
	D	Firemen's grounding switch	NA	NA	NA NA	
	E	Lift signage	NA	NA NA		
17	Sta	andby Power Supply:	Required	Provided	NA	
18						
	A	Total area	NA	NA	NA	
	B	Location	NA	NA	NA	
19	Fire Control Room:					
	A	Detector system panel	NA	NA	NA	
	B	Flow switch panel	NA	NA	NA	
	C	Pa system panel	NA	NA	NA	
	D	Battery backup	NA	NA	NA	
	E	Building floor plans	NA	NA	NA	
20	Spe	Special Fire Protection Systems For Protection of Special Risks, If Any:		NA	NA	

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection.

The owner has submitted an affidavit on 26.03.2025 stating not to use any floor above 2nd floor for any purpose.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No F6/DFS/MS/GH/NDZ/2022/23 dated 12.01.2022 is recommended to be renewed upto 2nd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar

Designation ADO (SPM)

DOCD

(A) 27/3

Djefo (0052)

27/03/25

DO (CD) 274
Apply