

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001 Dated: 07/05/2025



No F 6/DFS/MS/2025/EH/NDZ/ 172

FIRE SAFETY CERTIFICATE

Certified that the M/s Allure Restro Bar located at Plot No. 65, Ground Floor, Desh Bandhu Gupta Road, Pahar Ganj, Delhi-110055 in a building comprised of Basement (L-Store), Ground plus Four upper floors was issued FSC by this department vide letter No F6/DFS/MS/EH/NDZ/2022/144 dated 30.05.2022. The premise was re-inspected by the officer concerned of this department on 25.04.2025 in the presence of Sh. Mohit Sharma (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have therefore deemed complied with fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premise is fit for occupancy "Assembly (Restaurant)" Group D (for Ground floor only) with effect from . 0.7. 05. 2.025. And valid up to 31/03/2028 in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule, 2010.

Issued on 0.7. 0.5. 202 Jat New Delhi, by

Copy to: -

- 1. M/s Allure Restro Bar located at Plot No. 65, Ground Floor, Desh Bandhu Gupta Road, Pahar Ganj,
- 2. The Commissioner, MCD, Civic Centre, New Delhi- to ensure the occupancy as detailed above.
- 3. MCD Portal, ID No. 2025041206259.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate through MCD portal (https://www.mcdonline.nic.in) along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

			/	V-17			
	o address	of the building . A	INSPECTION REP	14)			
	ne & add	anding : N	Gunta Restro Bar lo	ORT			
	Type of Occupar	icy	Assembly Pahar Gan	cated at Plot No. 65, Ground	Floor, Desh Bandhu		
	Type of Case	sed of	Basement (Restauran	INSPECTION REPORT I/s Allure Restro Bar located at Plot No. 65, Ground Floor, Desh Bandhu Assembly (Restaurant) at Ground Floor. Renewal F6/DES a comparison of the state			
	5. Details of Previo	us NOC	- Cite Wal	rour upper moors			
	7. Date of		F6/DFS/MS/ELLA	Z/2022/144 Dated 30/05/2022			
1	O NI-	11	Nil Nil Nil	Z/2022/144 Dated 30/05/2023	2		
	8. Name of Inspectio 9. Name and design From the building	ng Officer	~3/04/2025				
	From the	ation of occ	R.K.Sinha, ADO (BV	W)			
	· · · · · · · · · · · · · · · · · · ·	-146					
S.	11. Applicant's letter	No :	Sh. Mohit Sharma (M	lanager)			
No.	Minimum Standa prevention and for	rds on C			12/04/2025		
1.	prevention and fi	re safety Luc	As per inspection	No. 2025041206259 dated	Remarks		
	Access to building Road width	K 33	report dated 19/05/2	Provided at site	MR/NMR		
	Gate width						
	Width act		6 m	Provided	MR		
2.	Width of internal re	oad	NA	NA	NA NA		
	Width, Type & Arrange		NA	NA	INA		
	Number, Width, Type & Arrangement of Exits Number of staircases						
	Upper El	es	Restaurant	- J Floor only			
	Upper Floors		Restaurant at Groun		NA		
	Basements		NA	NA NA	NA		
	Width of staircases		NA	NA			
	Upper Floor				NA		
	Basements		NA	NA NA	NA		
	Protection of exits		NA	NA NA	NA		
	Fire check door		NA	NA	NA		
	Pressurization		NA	NA	NA		
			NA	NA	+		
	No. of continuous terrace	staircases to		NA NA	NA		
			NA	INA			
	Width of Corridor		NA	NA	NA		
	Door Size	2000	2 m & 1.5 m	Provided	MR		
3.	Compartmentation						
	Fire check door			NA	NA		
			NA	NA			
	Sealing of electrical		NA	NA	NA		
	Fire Rating of shaft	door	NA	NA	NA		
	Water Curtain		NA	NA	NA		
	Fire Dampers		NA	NA	NA		
1.	Smoke Managemen	nt System					
	Basements		NA	NA	NA		
	Ground floor		Required	Provided	MR		
				TOVIGOU	IVIK		
5.	Fire Extinguishers						
	Total numbers		08 Nos.	Provided	100		
	Types			0 - 10000000	MR		
	IS marking		ABC/Co2 Type	Provided	MR		
j.	First-Aid Hose Reel	S	Required	Provided	MR		
	Total numbers on each	ch floor	01	P			
	Length of hose reel h			Provided	MR		
	Nozzle diameter		30 m	Provided	MR		
	101		5 mm	Provided	MR		
	Automatic fire detec	tion and alarmin	T evetom				
	Automatic fire detection and alarming s Type of detectors		system NA				
	Location of Main Panel			NA	NA		
	Location of Repeater		NA	NA	NA		
	Alternate source of po	ranei	NA	. NA			
	Hooters' Location	wer	NA	NA	NA		
	MOEFA		NA	NA NA	NA		
	- JOHA		Required	Provided	NA		
			2	Depriver	MR		

2		1	Q
Ν	•	,	0

9.	Public Address System	Required	Provided	MI	
10					
	Basement (Less than 200 sqm)	NA	NA Provided	NA	
	Ground Floor	Required	Provided	MR	
	Sprinkler above false ceiling	NA	NA	NA	
11.	11. Internal Hydrants				
-	Size of riser/down-comer	100 mm	Provided	MR	
	Number of hydrants per floor	01	Provided	MR	
	Hose Box	01	Provided	MR	
12.	12. Yard Hydrants				
	Total number of hydrants	NA	NA	NA	
	Hose Box	NA	NA	NA NA	
13.	Pumping Arrangements				
	Ground Level				
	Discharge of main Pump	NA	NA	NA	
	Head of Main pump	NA	NA	NA NA	
	Number of main pumps	NA	NA	77.	
	Jockey Pump out put	NA NA	NA	NA NA	
	Jockey pump head	NA NA	NA	NA	
	Standby Pump out put	NA NA	NA	NA NA	
	Standby Pump Head	NA	NA	NA NA	
	Auto Starting/Manual Stopping	NA	NA	NA NA	
	Pump House Access	NA	NA	NA NA	
+					
_	Terrace level				
1	Discharge of pump	450 lpm	Provided	MR	
	Head of the pump	30 m	Provided	MR	
P	ower Supply	Required	Provided	MR	
A	uto Starting of pump	Required	Provided	MR	
_	Captive Water Storage for fire fighting (Common)				
	nderground tank capacity	NA	NA	NA	
D	raw-off connection	NA	NA	NA	
Fi	re service inlet	NA	NA	NA NA	
A	ccess to tank	NA	NA NA		
0	verhead Tank capacity	20,000 ltrs		NA	
	kit Signage.	Required	Provided	MR	
		resquired	Provided	MR	
Pı	rovision of Lifts.	2			
_	essurization of Lift Shaft	NA	NA	NA	
	essurization of Lift lobby	NA	NA	NA	
Co	ommunication In lift Car	NA	NA	NA	
Fi	reman's Grounding Switch	NA	NA	NA	
_	ft Signage	NA	NA	NA	
St	andby power supply	NA	NA	NA	
Re	Refuge Area.				
To	otal Area	NIA	N TA		
	ocation	NA NA	NA NA	NA	
-	re Control Room	INA	NA	NA	
De	etector System Panel	NA			
	ow Switch Panel		NA	NA	
	ow Switch Faller	NIA I			
Fle	A System Panel	NA NA	NA NA	NA	

V July	NA	
Floor Plans	NA NA	NA
Protection System for Protection System for Special Risks, if any:	NA NA	NA
of special Risks, if any:	NA	NA

The fire protection systems provided in the building were tested, checked and found

Keeping in view of deemed compliance of the minimum standards of fire prevention and issued vide letter number F6/DFS/MS/EH/NDZ/2022/144 dated 30/05/2022 under rule 37 of Delhi Fire Service Rules, 2010.

Signature of Inspecting Officer Name: Rajeev Kumar Sinha Designation: ADO/B.W.

F (41 2/2 8/01/4 for 272 G74 Buddwell Stydl Nuc & 441