

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No.F6/DFS/MS/2025/GH/17

Dated 08/01/2025

## FIRE SAFETY CERTIFICATE

(Atul Garg)
Director

Ph: 011-23414000

Copy to:-

 The Commissioner, Municipal Corporation of Delhi, to ensure the occupancy as detailed above deviation and if any.

2. Online ID No- 2024121718100 dated: 20.12.2024.

 The Owner, M/s Almondz Guest House located at 4/3,2,1, East Patel Nagar, New Delhi-110008.

## Conditions for the validity of Fire Safety Certificate:

 No occupancy above third floor & basement as storage purpose, shall be adhered by Owner/occupier.

2. All the means of escape shall be kept free from any type of obstruction all the time.

- All the employees shall be acquainted with the use and maintenance of all fire equipment and method of smooth and speedy safe evacuation of occupants in case of emergency
- 4. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seem during inspection. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
- 5. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities. This Fire Safety Certificate is valid only for permanent building structure as per plan.

 Basement shall not be used for any other purpose except as specified in UBBL, subject to permission from concerned local authority.

- This fire safety certificate may not be treated in any case of regularizations of unauthorized construction/unauthorized use of land or activities, if any.
- The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on the official website of Delhi Fire Service i.e. www.dfs.delhigovt.nic.in.
- 9. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MHA portal along with a copy of this Certificate, six months prior to its expiry".

10. No temporary shed is allowed on terrace.

The Fire Safety Certificate is valid only for guest rooms. In case of any violation, this FSC will be treated as null & void.

## INSPECTION REPORT

Name & address of the building

: M/s Almondz Guest House at 4/3, 2,1, East Patel Nagar, New Delhi-08.

Type of Occupancy

: Residential (Lodging House)

2. Composition of building

: Basement, stilt, ground & 03 upper floors

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/GH/SZ/2021/424 dated 24.09.2021

6. Fire Safety directives letter No

7. Date of inspection

: 02.01.2025

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. King Kakar (Owner)

10. Year of Construction

: Before 2010

11. Applicant's letter No.

: Online MHA Portal ID No-2024121718100 dated: 20.12.2024

	Minimum Standards on fire prevention and fire safety U/R 33	Fire safety arrangements as per FSC dt. 01.08.2017	Provided at s	ite Remarks MR/NMR			
	Access to building						
1	Road width	06m	Provided	MR			
	Gate width		Directly accessibl	e MR			
	<ul> <li>Width of internal road</li> </ul>	NA	NA	NA			
	Number, Width, Type & Arrangement of Exits	<b>.</b>					
	a. Number of staircases	02	02	MR			
	Upper Floors	02	02	MR			
	Basements						
	b. Width of staircases  Upper Floors	Old case	1.25m, 85cm & 76cm	MR (being old case			
	Basements	Old case	1.20m & 84cm	MR (being old cas			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	Pressurization	NA	NA	NA			
	d. No. of continuous staircases to terrace	01	01	MR			
	e. Width of Corridor	Old case	1.38m	MR (being old cas			
	f. Door Size	Old case	78cm	MR (being old cas			
3	Compartmentation.						
,	Fire check door	NA	NA	NA			
	Sealing of electrical shafts	NA	NA	NA			
	Fire Rating of shaft door	NA	NA	NA			
	Water Curtain	NA	NA	NA			
	Fire Dampers	NA	NA	NA			
4	Smoke Management System.		n 11.1	MR			
	Basements	Required	Provided	MR			
	Upper floors	Required	Provided	1111			
5	Fire Extinguishers		Provided	MR			
	Total numbers	20nos	Provided	MR			
7	• Types	ABC & Co2 Yes	Provided	MR			
	ISI marking	Yes	Fiovided				

F	irst-Aid Hose Reels.	N-30					
	Total numbers on each floor	01	Provided	M			
-	Length of hose reel hose	30m	Provided	M			
The second	Nozzle diameter	5mm	Provided	M			
1	Automatic fire detection and alarming system.						
+	Type of detectors	Carbon monoxide	Provided	MI			
	Location of Main Panel	Required	Provided	MI			
	Location of Repeater Panel	NA	NA	NA NA			
	Alternate source of power	Required	Provided	MR			
	Hooters' Location	Every floor	Provided	MR			
1	MOEFA	Required	Provided	MR			
1	Public Address System.	Required	Provided	MR			
0	Automatic Sprinkler System.						
	Basement	Required	Provided	MR			
	Upper Floor	NA	NA	NA			
	Sprinkler above false ceiling	NA NA	NA	NA			
1	Internal Hydrants						
r	Size of riser/down-comer	NA	NA	NA			
	Number of hydrants per floor	NA NA	NA	NA			
	Hose Box	NA NA	NA	NA			
12	Yard Hydrants.			1			
ł	Total number of hydrants	NA NA	NA	NA			
	Hose Box	NA NA	NA	NA			
13	Pumping Arrangements.						
	Ground Level						
	<ul> <li>Discharge of main Pump</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Head of Main pump</li> <li>Number of main pumps</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Number of main pumps</li> <li>Jockey Pump out put</li> </ul>	N/A	N/A	N/A			
	> Jockey pump head	N/A	N/A	N/A			
	<ul> <li>Standby Pump out put</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Standby Pump Head</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Auto Starting/ Manual stopping</li> </ul>	N/A	N/A	N/A			
	➤ Pump House Access  • Terrace level	N/A	N/A	N/A			
	Terrace level     Discharge of pump	900 LPM	900 LPM	MR			
	> Head of the pump	40m	40m	MR			
	➤ Power Supply	Required	Provided	MR			
	➤ Auto Starting of pump	Required	Provided	MR			
14	Captive Water Storage for firefighting.						
	Underground tank capacity	NA	NA	NA			
	> Draw-off connection	NA NA	NA	NA			
	➤ Fire service inlet	NA	NA	NA			
	> Access to tank	NA NA	NA	NA			
	Overhead Tank capacity	10,000ltr	Provided	MR			
15	Exit Signage.	Required	Provided	MR			

	•	Pressurization of Lift Shaft	N/A	N/A	N/A		
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>	N/A Required Required	N/A Provided Provided	MR MR			
					Lift Signage	Required	Provided
7		Standby power supply		Required	Provided	MR	
8	Refuge Area.						
		Total Area	N/A	N/A	N/A		
		Location	N/A	N/A	N/A		
19	Fire Control Room						
		Detector System Panel	N/A	N/A	N/A		
		Flow Switch Panel	N/A	N/A	N/A		
			N/A	N/A	N/A		
		PA System Panel	N/A	N/A	N/A		
		Batter backup     Building Floor Plans	N/A	N/A	N/A		
20	Sp	ecial Fire Protection Systems for otection of special Risks, if any:	NA	NA	NA		

Note:notification gazette per contained provision the of compliance The F.5(189)/AD/LB/2016/4053-67 dated 27.05.2019 has been complied.

The fire protection systems provided in the building were tested/ checked and found some in

working order at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate issued vide this department letter of even no. F6/DFS/MS/GH/SZ/2021/424 dated 24.09.2021 under rule 37 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name: - C.L. Meena

Designation: Asst. Div. Officer (RN)

P.T.O .