

No. F.6/DFS/MS/GH/2025/SZ/199

Dated: 11 04 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Amrit Villa Guest House at 15/10169, Gurudwara Road, Karol Bagh, New Delhi- 110005, comprised of, basement (storage), stilt (parking & reception), ground, 1st, 2nd & 3rd floor each having 04 guest rooms respectively (total 16 guest rooms only), was issued FSC by this department vide letter No. F.6/DFS/MS/GH/SZ/2022/411 dated 07.09.2022. The premises was re-inspected by the officer concerned of this department on dated 04.04.2025 in the presence of Sh. Manoj, and found that the guest house have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class "Residential" (Guest house) (16 guest rooms only upto 3rd floor) w.e.f. 11 ou 2020 for a period of three years, in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

(Virendra Singh)
Chief Fire Officer
(For Director)
Delhi Fire Service

Copy to: -

1 The Commissioner, MCD, Delhi: to ensure the occupancy as detailed above and deviation, if any.

2 Online application Id 2025031203390 dated 12.03.2025.

3 The Executive Engineer (Bldg.), MCD, Civic Centre, New Delhi.

: - for information regarding use of basement.

Conditions for the validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape arrangements shall be kept unlocked & unobstructed for speedy evacuation of occupants in case of an emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. Basement shall be used as per the building bye laws. Presently basement used for storage only



INSPECTION REPORT

1. Name & address of the building : Amrit Villa guest house at 15/10169, Gurudwara Road, Karol

Bagh, New Delhi- 110005.

2. Building is comprised of : Basement (storage), stilt (parking & reception) ground floor (04 guest rooms), 1st,

2nd & 3rd floor each having 04 guest rooms respectively (total 16 guest rooms only)

3. Type of Occupancy : Residential (Guest House)

4. Type of Case : Renewal

5. Details of Previous FSC letter : F.6/DFS/MS/GH/SZ/2022/411 dated 07.09.2022.

6. Fire Safety direction letter No : N/A

7. Date of Inspection : 04.04.2025

8. Name of the Inspecting officers : ADO R.K. Yadav (JKP)

9. Name and designation of officer

from the building side : Sh. Manoj

10. Year of construction : Before 2010

11 Applicant's letter No : ID No. 2025031203390 dated 12.03.2025

Sr. No.	Minimum Standards on Fire Prevention and Fire Safety U/R33	Requirement as per FSC dt. 07.09.2022	Provided at Site	Remarks MR/NMR			
1	Access to Building.						
	Road width	Accessible	04 m	MR, Old Case			
	Gate width	N/A	Directly Accessible	N/A			
	Width of internal road	N/A	N/A	N/A			
2	Number, Width, Type and Arrang	ement of Exits.					
	a. Number of Staircases						
	Upper floor	01 Nos.	01 Nos.	MR, Old Case			
	Basement	01 Nos.	01 Nos.	MR, Old Case			
	B. Width of Staircases						
	Upper floor	Old Case	1.25 m	MR, Old Case			
	Basement	Old Case	1.25 m	MR, Old Case			
	c. Protection of Exits						
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of Continuous Staircases to Terrace	01	01	MR			
	e. Width of Corridor	N/A	N/A	N/A			
	f. Door Size	N/A	N/A	N/A			
3	Compartmentation.						
	Fire check door	N/A	N/A	N/A			
_	Sealing of electrical shafts	N/A	N/A	N/A			
	Fire rating of shaft door	N/A	N/A	N/A			
	Water curtain	N/A	N/A	N/A			
	Fire dampers	N/A	N/A	N/A			
4	Smoke Management System.						
	Basement	30 ACPH	Exhaust fan provided	MR			
	Upper floor	12 ACPH	Natural Ventilation provided	MR			
5.	Fire Extinguishers.						
	Total numbers	12 nos.	Provided	MR			
	Types	ABC /CO ₂	Provided	MR			
11	IS marking	ISI marked	Provided	MR			

JE'	<u>*</u>				
S.					
on each floor	01 No	Provided	MR		
e reel hose	30 m	Provided	MR		
ter	05 mm	Provided	MR		
ection, CO detecti	ion and Alarming	System.			
	Required	C@/Smoke type	MR		
etectors	Required	Ground floor	MR		
ain panel	NA	NA NA	NA		
peater panel	Required	Provided	MR		
ce of power	Required	Provided	MR		
	Required	Provided	MR		
em.	Required	Provided	MR		
	Required		4		
r System.		Provided	Area less than		
Stilt	N/A		200 sq. m		
22	N/A	N/A	N/A		
e false ceiling	N/A	N/A	N/A		
Internal Hydrants					
	N/A	N/A	N/A		
own-comer	N/A N/A	N/A	N/A		
drants per floor	N/A N/A	N/A	N/A		
	N/A	1071			
Yard Hydrants.					
ydrants	N/A	N/A N/A	N/A N/A		
m1 D	N/A	IV/A	1021		
ents.	y_	V 4			
nain pump	37/1	NI/A	N/A		
pump	N/A	N/A N/A	N/A		
nin pumps	N/A		N/A		
out put	N/A	N/A N/A	N/A		
head	N/A	N/A	N/A		
out put	N/A	N/A	N/A		
head	N/A	N/A N/A	N/A		
manual –	N/A	N/A	N/A		
	N/A	N/A	IVA		
ccess	•				
	450 LPM	450 LPM	MR		
oump	40 m	40 m	MR		
ımp	Required	Provided	MR		
of numn	Required	Provided	MR		
of pump					
Captive Water Storage for Fire Fighting.					
ank capacity	N/A	N/A	N/A		
ection	N/A	N/A	N/A		
let _	N/A	Provided	N/A		
<u> </u>	N/A	N/A	N/A		
k capacity	5,000 ltrs	5,000 ltrs	MR, old cas		
	Required	Provided	MR		
			Required Provided		

N 29

μ.							
6	Provision of Lifts.						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of Lift lobby	N/A	N/A	N/A			
	Communication in lift car	Required	Provided	MR			
	Firemen's grounding switch	Required	Provided	MR			
	• Lift Signage	Required	Provided	MR			
,	Standby power supply	Required	Provided	MR			
18	Refuge Area.						
	Total area	N/A	N/A	N/A			
	Location	N/A	N/A	N/A			
19	Fire Control Room						
	Detector system panel	N/A	N/A	N/A			
	Flow switch panel	N/A	N/A	N/A			
	PA system panel	N/A	N/A	N/A			
	Battery backup	N/A	N/A	N/A			
	Building Floor Plans	N/A	N/A	N/A			
	Special Fire Protection systems for protection of special Risks, if any:	Required	02 ABC type fire extinguishers found provided near elect. panel	MR			

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - As per undertaking given by guest house management (placed at C-75) that the building comprised of basement, stilt, ground plus three upper floors, using basement as storage, stilt as pariking & reception ground floor having 04 guest rooms, 1st, 2nd & 3rd floor each having 04 guest rooms respectively (total 16 guest rooms only).

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules the FSC issued vide letter No. F.6/DFS/MS/GH/SZ/2022/411 dated 07.09.2022, renewal under rule 37 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting

Name: - R.K. Yadav Designation: - ADO (JKP)

DO (SD)

Ctol Stuff 2000

Director/ My

Mosphr