

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001

गणादी व अगृत महोत्सव

No.F6/DFS/MS/School/SZ/2025/ 730

Dated: 06 | 06 | 25

FIRE SAFETY CERTIFICATE

Certified that the Anand Vidya Bharti Education Society School located at F-II/476, Sangam Vihar, New Delhi-80, building comprised of two blocks (both block are interconnected at each floor level) having Basement (in one block only – sealed) + Ground + 02 upper floors was granted Fire Safety Certificate by this department vide letter no. F.6/DFS/MS/School/SZ/2022/684 dated 22.06.2022. The school building was re-inspected by Assistant Divisional Officer (M. Road) from this department on 02.06.2025 in the presence of Mrs. Manju (HOS) and found that the school building has deemed complied with the fire prevention and fire safety requirements in accordance with the circular no. 262-232 dated 17/01/2005 issued by the Director of Education and the building is fit for occupancy of Group B" Educational Building" with effect from Of Color 25.00 renewed for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to conditions under Rule 38 of Delhi Fire Service Rules, 2010 printed below.

Issued on 06/06/25 at New Delhi by

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to:-

- 1. The Dy. Director of Education, GNCT of New Delhi DISST. South Block-C, Defence Colony, New Delhi-24.
- 2. The Principal, Anand Vidya Bharti Education Society School, located at F-II/476, Sangam Vihar, New Delhi-80.

Conditions for the validity of Fire Safety Certificate

- 1. All the means of escape shall be kept free of all the type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 5. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 7. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub Rule (1) of Rule 37] along with a copy of this certificate, six months prior to its expiry.

01/0

1]	Name & address of the building	· · · · · · · · · · · · · · · · · · · ·	Anand Vidya Bharti Education Society School located at F-II/476, Sangam Vihar, New Delhi-80 Comprised of two block: -Basement (sealed) + Ground + 02 upper floors			
2	I	Building is comprised of	Comprised of				
		and to comprised of					
			Cround 1 02	alea) + Ground + 02 u	pper floors		
			-Ground + 02		an Calant		
3	17	ype of occupancy		Both block interconnected at each floor level			
4		ype of case		Educational" Group B"			
5		etails of previous FSC		hool/SZ/2022/684 date			
6	_	ire safety direction letter no.		62-362 dated-17/01/20	05		
7	_	ate of inspection	02.06.2025				
8		ame of the inspecting officers		hukla, ADO (M. Road)		
9		ame of the designation of office	cer Mrs. Manju (HO	S)			
	12 15 15 15 15	om the building side					
10		ear of construction		2001			
11		pplicant's letter no.		. 2068 dated 26.05.202	Remarks		
S.No	3 1 122		re Requirement as	All controls and the second se	MR/NM		
	p	evention and fire safety U	/R per Rules 35 (6)		MICHIA		
-1	33						
1	A	ccess to Building:			MR		
	A	Road width	Required	Accessible	NA		
	В	Gate width	NA	NA	NA		
	C	Width of internal road	NA	NA	INA		
2	N	ımber, Width, Type and Arra	ingement of Exits:				
	A	Number of staircases	A TOTAL	Walter of the state of the stat	MR		
		a Upper floor	2 nos.	3 nos.	NA		
		b Basement	NA	NA	INZ		
-	В	Width of staircases	With the	102 8	MR		
		a Upper floor	Required	1.07 m, 1.03 m &	IVIIC		
	J.		in the second	0.93 m	NA		
		b Basement	NA	NA	112.1		
	C	Protection of exits			NA		
		a Fire check door	NA	NA	NA		
		b Pressurization	NA	NA	MR		
	D	No. of continuous staircase	s Required	2 nos.	IVIIC		
		to terrace	all ment plane		MR		
	E	Width of corridor	1.5 m	Provided	MR		
	F	Door size	1.0 m	1.0 m (class room)	IVIIX		
		mpartmentation:	AND THE SECOND	Will be a second	NA		
1	A	Fire check door	NA	NA	NA NA		
	B	Sealing of electrical shafts	NA	NA	NA NA		
	C	Fire rating of shaft door	NA	NA	III Y ZANTON NES		
	D	Water curtain	NA	NA	NA		
1	E	Fire dampers	NA	NA	NA		
	E C	ke Management System:	AK Jalyin	port want	LNIA		
	A	Basement	NA	NA	NA		
-	B	Upper floor	NA	NA	NA		
					1		
		Extinguisher:	08 nos.	09 nos.	MR		
_		Total numbers	CO ₂ & ABC	CO ₂ & ABC	MR		
	(2000)	Гуреѕ	ISI Marked	Provided	MR		
		SI marking	151 Iviai keu	ALEXANDER TO SECTION			
	First	-Aid-Hose Reel:		01 nos	MR		
1	A	Total numbers of each floor	01 nos.	01 nos.	MR		
_	В	ength of hose reel hose	30m	1027700 2000 T			
	C	Nozzle diameter	05mm	05mm	MR		

7	A	tomatic Fire Detection and Al		NA	NA		
	B	Type of detectors Location of main panel	NA	NA NA	NA		
	C	Location of main panel Location of repeater panel	NA NA	NA NA	NA NA		
	D	Alternate source of power	NA NA	NA NA	NA		
	1 1			15-4-17-00 to 12-5	Para P		
•	E	Hooters	ŇA	NA	NA		
8		OEFA:	NA	NA	NA		
9	Public Address System:		NA	NA	NA		
10		tomatic Sprinkler System:	£		70100000		
	A	Basement	NA	NA	NA		
	В	Upper floor	NA	NA	NA		
	C	Sprinkler above false ceiling	NA	NA	NA		
11	Internal Hydrants:						
	A	Size of riser/down-comer	NA	NA	NA		
	В	Number of hydrants per floor	NA	NA	NA		
	C	Hose box	NA	NA	NA		
12							
	A	Total number of hydrants	NA	NA	NA		
	B	Hose box					
13	1110000		NA	NA	NA		
		mping Arrangements:	Incl. 1				
A	-	round level	4350				
	a)	Discharge of main pump	NA	NA	NA		
	b)	Head of main pump	NA	NA	NA		
	c)	Number of main pumps	NA	NA	NA		
	d)	Jockey pump out put	NA	NA	NA		
	e)	Jockey pump head	NA	NA	NA		
	f)	Standby pump out put	NA	NA	NA		
	g)	Standby pump head	NA	NA	NA		
	h)	Auto starting /manual stopping	NA	NA	NA		
	i)	Pump house access	NA	NA	NA		
3	Ter	race Level	Jan 1 a -		- 14.2		
	a)	Discharge of pump	225 LPM	Provided	MR		
	b)	Head of the pump	30 mtrs	30 mtrs	MR		
	c)	Power supply	Required	Provided	MR		
	d)	Auto starting of pump	Required	Provided	MR		
14	Cap	tive Water Storage for Fire F	ighting:				
	A	Underground tank capacity	NA	NA	NIA		
	В	Draw-off connection	NA	NA NA	NA		
	C	Fire service inlet	NA	NA NA	NA		
	D	Access to tank	NA	NA NA	NA NA		
	E	Overhead tank capacity	5,000 Litr	Provided			
5	Exit	Signage:	Required	Provided	MR MR		
6	Prov	vision of Lifts:	40.00	Tiovided	NIK		
	A	Pressurization of lift shaft	NA	NIA	137.		
	В	Pressurization of lift lobby	NA	NA NA	NA		
	C	Communication in lift car	NA	NA NA	NA NA		
	D	Firemen's grounding switch	NA	NA NA	NA NA		
	E	Lift signage	NA	NA NA	NA NA		
7	Stan	dby Power Supply:	NA	NA NA	NA NA		
8	Refu	ige Area:	10.1	. 12 1	INA		
	A	Total area	NA	NA	***		
-	В	Location	NA	NA	NA		

Anand Vidya Bharti Education Society School located at F-II/476, Sangam Vihar, New Delhi-80

10/12

19	Anand Viaya Bharti Education Society School located at F-11/476, Sangam Vihar, New Delhi-80 Fire Control Room:					
	A	Detector system panel	Tara			
	В	Flow switch panel	NA	NA	NA	
	С	PA system panel	NA	NA	NA	
	D		NA	NA	NA	
	_	Battery backup	NA	NA	NA	
	E	Building floor plans	NA	NA	NA NA	
20	Spe	ecial Fire Protection systems for	NA			
	protection of special Risks, if any:		TVA		NA	

Meeting Requirement (MR), Not Meeting Requirement (NMR), Not Applicable (NA), Provided but Not Functional (PNF), Not Provided (NP).

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required in Directorate of Education Circular 262-232 Dated-17/01/2005, the FSC issued vide letter no. F.6/DFS/MS/School/SZ/2022/684 dated 22.06.2022 is recommended to be renewed.

Signature of the Inspecting Officer
Name Rajesh Kumar Shukla
Designation ADO (M. Road)

Marshol Mars Steps

ADO (MRd)