## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No F6/DFS/MS/2025/WZ/GH/ 128

Dated: 12 03 2025

## FIRE SAFETY CERTIFICATE

Certified that the M/s New Anand Niwas, located at Plot No-40, Ram Nagar, Gali No.1, Pahar Ganj, Delhi-110055, comprised of ground + 03 upper floors, Guest house running at ground, 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floors only, (ground floor-04 guest rooms + reception + 02 staff rooms, 1<sup>st</sup> floor-05 guest rooms, 2<sup>nd</sup> floor-06 guest rooms, 3<sup>rd</sup> floor-05 guest rooms) and terrace floor kitchen for staff + 02 rooms, given an affidavit dated 24.10.2019 regarding not to use any floor above third floor was earlier granted FSC by this department vide letter No. F.6/DFS/MS/GH/NDZ/2021/532 dated 17.12.2021. The premises was re-inspected by the officer concerned of this department on 27.02.2025 in the presence of Mr. Gaurav Aggarwal (Partner) and found that the said building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Residential, Sub-Division-A-1 (Gr. + 1<sup>st</sup>, 2<sup>nd</sup> & 3<sup>rd</sup> floor total 20 guest rooms only) with effect from 12 03 2025 and valid up to 31.03.2028 in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010

Issued on ... 12 03 2025 at New Delhi by

DIRECTOR Ph; 011-23414000

Copy to:-

1. MCD Portal Id- 2025022002106 dated 20.02.2025.

2. The commissioner MCD, Civic Centre, New Delhi, to ensure the occupancy s detailed above.

3. The Joint Commissioner of Police (Lic.) 1<sup>st</sup> floor, Licensing unit, Police Station, Defence Colony, New Delhi-

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management/occupier.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

9. Standby power supply shall be provided within 6 months from data of issue of till certificate, failing which FSC shall be considered null & void

http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit\_fire/FIRE/Home/Forms

ype of Oc	dress of the building	M/s No			Ram Nagar, G		
ype of Oc		M/s No	ew Anand Niwas,		Ram Nagar, G		
	0						
		110.1, 1	M/s New Anand Niwas, located at Plot No-40, Ram Nagar, Ga No.1, Pahar Ganj, Delhi-110055.				
	2. Type of Occupancy Re			Residential, Sub Division-A-1			
3. Comprised of building			Ground + 03 upper floors, 3 <sup>rd</sup> floor terrace kitchen for staff + 0				
Type of Con-		rooms					
Tot Gro			Renewal (Guest house running at Ground + 03 upper floor				
		Ground	Ground floor-04 guest rooms + reception + 02 staff rooms				
		1st floo	1st floor 05 guest room 2nd floor-06 guest rooms, 3" floor-0				
		guest re	ooms and terrace f	loor –kitchen for staff	+ 02 rooms n		
	1 1100	in use	as per affidavit dat	22/117 dated 23 02 2022	2.		
			S/MS/GH/NDZ/202	22/11/ dated 25.02.2022			
		07/2/07/2/2	27.02.2025				
		Sh Aia					
AND AREA OF THE PROPERTY OF TH		Mr. Ga	Gauray Aggarwal (Partner)				
	7.0	2001 or	2001 on MCD Portal				
. Tour or conduction		ne application No.2025022002106 dated 20.02.2025.					
Minimum	Standards on fire prev	ention	Rule 35 (6)	Provided at site	MR/NMR		
					AMATRIC		
Access to	building		N/A	30 feet	-NA		
• Ro	ad width		20240	270.500.600.40.5	-NA-		
• Ga	te width				-NA-		
• Wi				-NA-			
Number,	Width, Type & Arrang	ement of	Exits				
l. Numbe	r of staircases			01nos	MR		
			WEST STATE OF THE	D. F. Charles Co. Co.	-NA-		
•	Basements		-NA-	-1111	35,000		
. Width	of staircases		0.90	0.84m	MR		
•	Upper Floor		[1002] [2002] [2002] [2002]		-NA-		
ARI •	Basements		-NA-	-NA-	• " •		
. Protec	tion of exits		NA	NA-	-NA-		
	Fire check door			22474.40	-NA-		
•	Pressurization				-NA-		
d. No. of continuous staircases to terrace		ALL STATES		-NA-			
e. Width	of Corridor				MR		
THE SHADOW STATE OF	SHID.		Olmtr	Offita	7.5		
			NIA	-NA-	-NA-		
					-NA-		
				-NA-			
					-NA-		
					-NA-		
	e Dampers		-11//-	,,,,			
The state of the s	anagement System		-NA-	-NA-	-NA-		
100 mm	nome om to		-14V-				
a) Ba			12 ale per hour	Natural ventilated	MR		
	per floors		12 a/c per hour	Natural ventilated	MR		
	Date of ins Name of Ir Name and From the b Year of Co Applicant' Minimum and fire sa Access to  Ro  Ro  Ro  Win Number, I. Number  Width  Protect  No. of co Width  The Door S Comparts  A) Fire b Sec C Fire d War Sec C Fire co Fire co C Fire co C Fire co C Fire d War Sec C Fire co C Fir	and fire sa fety U/R 33  Access to building  Road width  Gate width  Width of internal road  Number, Width, Type & Arrang  Number of staircases  Upper Floors  Basements  Upper Floor  Basements  Fire check door  Pressurization  No. of continuous staircases to  Width of Corridor  Door Size  Compartmentation  a) Fire check door  b) Sealing of electrical shafts  c) Fire Rating of shaft door  d) Water Curtain	Details of Previous NOC Fire Safety directives letter No Date of inspection Name and designation of officers Name and designation of officers From the building side Year of Construction Applicant's letter No. Minimum Standards on fire prevention and fire safety U/R 33 Access to building Road width Gate width Width of internal road Number, Width, Type & Arrangement of Number of staircases Upper Floors Basements Upper Floor Basements Fire check door Pressurization A No. of continuous staircases to terrace Width of Corridor Door Size Compartmentation a) Fire check door b) Sealing of electrical shafts c) Fire Rating of shaft door d) Water Curtain	Total-20 rooms) Ground floor-04 guest room, guest rooms and terrace of in use as per affidavit dain use as per affidavit d	Total-20 rooms) Ground floor-04 guest rooms + reception + 02 staf 1st floor-05 guest room, 2nd floor-06 guest roo guest rooms and terrace floor -kitchen for staff in use as per affidavit dated 24.10.2019 F.6/DFS/MS/GH/NDZ/2022/117 dated 23.02.2022 Sire Safety directives letter No -NA- Date of inspection 27.02.2025 Name of Inspecting Officer Sh. Ajay Kumar Sharma (ADO Rohini) Name and designation of officers From the building side Year of Construction 2001 on MCD Portal Applicant's letter No. Online application No.2025022002106 dated 20.02 Minimum Standards on fire prevention and fire safety U/R 33 Access to building Road width -NA- 30 feet Road width -NANANA- Width of internal road -NANANA- Number, Width, Type & Arrangement of Exits Number of staircases Upper Floors -NANANA- Width of staircases Upper Floor -NANANA- Protection of exits -NANANA- Protection of exits -NANANA- No. of continuous staircases to terrace -NANANA- No. of continuous staircases to terrace -NANANA- Door Sze Compartmentation -NANANA- Compartmentation -NANANA- Selling of electrical shafts -NANANA- Compartmentation -NANANANA- Compartmentation -NANANANA- Compartmentation -NANANANANANANANA		

M

_	T : -	angines I				
	a) Types	ABC/CO2	ABC/CO2	MR		
_	b) IS marking	ISI marked	Yes	MR		
6.	First-Aid Hose Reels		_			
	a) Total numbers on each floor	01nos.	Provided	MR		
	b) Length of hose reel hose	30mm	Provided	MR		
	c) Nozzle diameter	5m	Provided	MR		
7.						
	a) Type of detectors	Required	Provided	MR		
	b) Location of Main Panel	Gr. floor	Provided	MR		
	c) Location of Repeater Panel	Required	Provided	MR		
	d) Alternate source of power	Required	Provided	MR		
	e) Hooters' Location	Gr. floor	Provided	MR		
8.	MOEFA	-NA-	-NA-	-NA-		
9.	Public Address System	Required	Provided	MR		
10.	Automatic Sprinkler System					
	a) Basement	-NA-	-NA-	-NA-		
	b) Ground & Upper Floors	-NA-	-NA-	-NA-		
	c) Sprinkler above false ceiling	-NA-	-NA-	-NA-		
11.	Internal Hydrants					
l.	a) Size of riser/down-comer	-NA-	-NA-	-NA-		
	b) Number of hydrants per floor	-NA-	-NA-	-NA-		
	c) Hose Box	-NA-	-NA-	-NA-		
12.	-					
	a) Total number of hydrants	-NA-	-NA-	-NA-		
	b) Hose Box	-NA-	-NA-	-NA-		
13.	Pumping Arrangements					
	Ground Level					
	Discharge of main Pump	-NA-	-NA-	-NA-		
j	> Head of Main pump	-NA-	-NA-	-NA-		
	> Number of main pumps	-NA-	-NA-	-NA-		
	> Jockey Pump out put	-NA-	-NA-	-NA-		
	> Jockey pump head	-NA-	-NA-	-NA-		
9	Standby Pump out put	-NA-	-NA-	-NA-		
	Standby Pump Head	-NA-	-NA-	-NA-		
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-		
	> Pump House Access	-NA-	-NA-	-NA-		
7	Towns and the second se	-IVA-	-147			
	Terrace level 225lpm 225lpm					
	> Discharge of pump	225lpm		MR MR		
	➤ Head of the pump	30m	30m	MR		
1	> Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	NIK		
1.	Captive Water Storage for fire fighting					
	Underground tank capacity	-NA-	-NA-	-NA-		
		-NA- ''.	-NA-	-NA-		
	> Draw-off connection		-NA-	-NA-		
1	> Fire service inlet	-NA- ,	17.000	-NA-		
1	> Access to tank	-NA-	-NA-			
F	The second secon	2500ltr	2500ltr	MR		
1	Overhead Tank capacity	Required	Provided	MR		
	Exit Signage.		-			

	a) Pressurization of Lift Shaft	-NA-	-NA-	-NA-			
	b) Pressurization of Lift lobby	-NA-	-NA-	-NA-			
	c) Communication In lift Car	-NA-	-NA-	-NA-			
	d) Fireman's Grounding Switch	-NA-	-NA-	-NA-			
	e) Lift Signage	-NA-	-NA-	-NA-			
17.	Standby power supply	Required	Shall be Provided with in 6\( \) month	MR			
	Refuge Area.						
	a) Total Area	-NA-	-NA-	-NA-			
19.	b) Location	-NA-	-NA-	-NA-			
	Fire Control Room						
	a) Detector System Panel	-NA-	-NA-	-NA-			
	b) Flow Switch Panel	-NA-	-NA-	-NA-			
	c) PA System Panel	-NA-	-NA-	-NA-			
	d) Battery backup	-NA-	-NA-	-NA-			
	e) Building Floor Plans	-NA-	-NA-	-NA-			
20.	Special Fire Protection System for Protection of special Risks, if any:	-NA-	-NA-	-NA-			

Accordingly, the fire protection systems provided in the building were tested/ checked

randomly and found in working condition at the time of inspection.

In view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures as required under the rules the NOC issued vide letter no. F.6/DFS/MS/GH/NDZ/2022/117 dated 23.02.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

of letty to put and signature of s.