

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

1002025

No. F6/DFS/MS/2025/WZ/EH/ 340

FIRE SAFETY CERTIFICATE

M/s Anardana Hospitality Pvt. Ltd. located at Shop No.FO-7, 4th floor, One Elegant Neta Ji Subash Palace Metro Station, Opp. Wazirpur District Centre Pitampura, Delhi-110034, comprised of 02 tire basement, ground + 04 upper floors and Restaurant is running at Shop No.FO-7, 4th floor only was inspected by the officer concerned of this department on 19.09.2025 in the presence of Mr. Anil Giri and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with Rule 33 of the Delhi Fire Service Rules,2010 and that the premise is fit for occupancy class D "Assembly Building" for (Restaurant) Shop No.FO-7, 4th floor only with effect from 01 10 2025 for a period of 03 (Three) years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 01 10 2025 at New Delhi by

(Virendra Sungh) Chief Fire Officer Delhi Fire Service

Copy to: -

1. MCD Portal ID-2025090113064 dated 01.09.2025.

2. The Manager, M/s Anardana Hospitality Pvt. Ltd. located at Shop No.FO-7, 4th floor, One Elegant Neta Ji Subash Palace Metro Station, Opp. Wazirpur District Centre Pitampura, Delhi-110034.

Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

- 4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
- 5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/ http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

-							
			INSPE	CTION REPORT	(9)		
1.	Name	& address of the building	M/s Anardana Hospitality Pvt. Ltd. located at Shop No.FO-7, 4				
2.	Type	of Occupancy	Wazirpur District Centre Pitampura, Delhi-110034. Assembly Building				
3.	Assem		iro Posseranto C				
	Ly T		One	Elegant	und + 04 upper floors. Commercial Commercial		
	1.14				025/SZ/353 dated 30.0	omplex FS	
4.	Туре	of Case	No.F.6/DFS/MS/Mixed/2025/SZ/353 dated 30.06.2025. New Case (Anardana Hospitality Restaurant is running				
5.	Detail	s of Previous NOC	Shop No.FO-7, 4 th floor only) NBC Part-IV				
6.	Fire S	afety directives letter No	N/A				
7.	Date	of inspection	19.09.2025.				
	Name of Inspecting Officer A. K. S		Sharma, ADO (Rohini)				
9.				nil Giri			
10	. Year	of Construction	2025		7		
	. Appli	cant's letter No.	Online	application No.202	5090113064 dated 01.	09 2025	
S. No	Mini and f	num Standards on fire prev ire safety U/R 33	ention	UBBL/NBC Requirement	Provided at site	Remarks	
1.			Comm	Requirement	CN E (DEGREES	MR/NMR	
	dated	ss to building (One Elegant 1 30.06.2025)	Сошще	ercial Complex RS	C No.F.6/DFS/MS/M	ixed/2025/SZ/3	
		7-0 E 500 E					
		Gate width		The second second		4 4 7	
		2000 0 7	_	Restaurant within	As Above	MR	
		width of internal road		Mall	X07	1815925	
2	Num	ber, Width, Type & Arrange	ement of	Exits [Provided &	Maintained by Mall 1	nanagementl	
	a. Number of staircases		-147	•	9 1		
	Upper Floors			Restaurant in mall	As Above	NA	
	Basements			Restaurant in mall	As Above	NA	
	b. Width of staircases		min#				
	W .	Upper Floor	per la sun i	Restaurant in mall	As Above	NA	
		Basements	un III.	Restaurant in mall	As Above	NA	
	c. P	rotection of exits	iir ii iu	[Provided &	Maintained by Mall n	10411040000	
		Fire check door	nimi	Required	Provided	MR	
		Pressurization		Restaurant in mall	As Above	NA NA	
	d. No	. of continuous staircases to	terrace	Restaurant in mall	As Above	NA NA	
		dth of Corridor		Restaurant in mall	As Above	NA NA	
	COLUMN TO SERVICE STATE OF THE PERSON SERVICE STATE SERVICE STATE SERVICE STATE OF THE PERSON SERVICE STATE SERVICE STATE SERVICE STATE SERVIC	or Size		2 x 1.5m	Provided	MR	
	100000	partmentation		- A LIVIII	Tiovided	IATIC	
	a) Fire check door			Required	Provided	MR	
	b) Sealing of electrical shafts			Restaurant in mall	As Above	NA NA	
	c)	Fire Rating of shaft door		Restaurant in mall	As Above	NA NA	
	d) Water Curtain			Restaurant in mall	As Above As Above	NA NA	
	e)	Fire Dampers	111	Restaurant in mall	As Above	NA NA	
	Smoke Management System				& Maintained by Mall	P. 1970	
4.				Restaurant in mall	As Above	Management) NA	
	A CHARLEST CONTROL CON			Restaurant in mall		2000	
	b)	Upper floors		Acotaurant in mall	As Above	NA	
5.	Fire Extinguishers			07		M	
	a) Total numbers			07nos.	Provided	MR	
	b) Types			ABC/CO2	ABC/CO2	MR	

	c) IS marking	ISI marked	Yes	Mit
6.	First-Aid Hose Reel	[Provided & M	[Provided & Maintained by Mall managen	
	a) Total numbers on each floor	Near to restaurant	Provided	MR
	b) Length of hose reel hose	30mm	Provided	MR
	c) Nozzle diameter	5m	Provided	MR
7.	Automatic fire detection and alarming sys	stem [Provided & M	faintained by Mall manage	ment]
	a) Type of detectors	Smoke/Heat	Provided.	MR
	b) Location of Main Panel	Restaurant in mall	As Above	NA
	c) Location of Repeater Panel	Restaurant in mall	As Above	NA
	d) Alternate source of power	Restaurant in mall	As Above	NA
	e) Hooters' Location	Common area's	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Restaurant in mall	As Above	NA
10.	Automatic Sprinkler System	[Provided & Main	tained by Mall managemen	nt]
	a) Basement	Restaurant in mall	As Above	NA
	b) Ground & Upper Floors	Restaurant in mall	As Above	NA
	c) Sprinkler above false ceiling	Restaurant in mall	As Above	NA
11.	Internal Hydrants	THE PART OF THE		
	a) Size of riser/down-comer	Restaurant in mall	As Above	NA
	b) Number of hydrants per floor	Restaurant in mall	As Above	NA
	c) Hose Box	Restaurant in mall	As Above	NA
12.	Yard Hydrants	[Provided & Main	tained by Mall manageme	
	a) Total number of hydrants	Restaurant in mall	As Above	NA
	b) Hose Box	Restaurant in mall	As Above	NA
13.	Pumping Arrangements	and a Market of the A		
	Ground Level	Restaurant in mall	As Above	NA
	Discharge of main Pump	Restaurant in mall	Hyd=2850 LPM Sprk=2850 LPM	NA
	Head of Main pump	Restaurant in mall	90m	NA
	Number of main pumps	Restaurant in mall	02nos.	NA
	Jockey Pump out put	Restaurant in mall	180lpm	NA
	Jockey pump head	Restaurant in mall	90m	NA
	Standby Pump out put	Restaurant in mall	2850lpm	NA
	Standby Pump Head	Restaurant in mall	90m	NA
	Auto Starting/Manual Stopping	Restaurant in mall	As Above	NA NA
	Pump House Access	Restaurant in mall	As Above	-
	Terrace level		AS AUUVE	NA
	Discharge of pump	Restaurant in mall	A - A1	In OV.
-	➤ Head of the pump	Restaurant in mall	As Above	NA
	➤ Power Supply	Restaurant in mall	As Above	NA
	Auto Starting of pump	Restaurant in mail	As Above	NA
14.	Captive Water Storage for fire fighting	The second secon	As Above	NA
	Underground tank capacity	[Provided & Maintained by Mall management]		
	> Draw of	Restaurant in mall	2,00,000 Ltrs	NA
	> Draw-off connection	Restaurant in mall	As Above	NA NA
	➤ Fire service inlet	Restaurant in mall	1 E WZ	
	Access to tank	Restaurant in mall	As Above	NA
	Overhead Tank capacity	Restaurant in mall	As Above	NA
				NA
15.	Exit Signage.	Required	20,000 ltrs Provided	MR

		novie Stiegle	Restaurant in mall	As Above	NA	
	a)	Pressurization of Lift Shaft	Restaurant in mall .	As Above	. NA	
	b)	Pressurization of Lift lobby	A CONTRACTOR OF THE PARTY OF TH	As Above	NA	
Ì	c)	Communication In lift Car	Restaurant in mall			
ł	4)	Fireman's Grounding Switch	Restaurant in mall	As Above	NA	
1		Lift Signage	Restaurant in mall	As Above	NA	
	Standby power supply		Restaurant in mall	As Above	NA	
17.			[Provided & Maintained by Mall management]			
18.	Refuge Area.		Restaurant in mall	As Above	NA.	
	a)		Restaurant in mall	As Above	NA	
	b)	Location	Restaurant in man			
19.	Fire (control Room		As Above	NA	
AUS N	a)	Detector System Panel	Restaurant in mall		NA	
	b)		Restaurant in mall	As Above	NA	
	c)		Restaurant in mall	As Above	251,409,1423	
			Restaurant in mall	As Above	NA	
	ď		Restaurant in mall	As Above	NA	
	e)		Restaurant in mall	As Above	NA	
20.	Spec	ial Fire Protection System for ection of special Risks, if any:	Lean Land	a building were teste	d/ checked	

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

> Signature of the Inspecting Officer Name: - Ajay Kumar Sharma Designation:- ADO/Rohini

DO(W)- M

Principal Director