



**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001**

C-16

ATUL GARG

No. F.6/DFS/MS/School/2025/NDZ/ 472

Dated 30/5/25

To,

The Manager,
Ankur Shiksha Sadan Public School,
Near Post Office, Ram Nagar, Shahdara,
Delhi-110032.

Sub:- Regarding Issuance of Fire Safety Certificate r/o Ankur Shiksha Sadan Public School at Near Post Office, Ram Nagar, Shahdara, Delhi-110032.

Sir,

With reference to your letter no. ASSPS/20-25/04//00135 dated 08/04/2025 on the subject cited above. In this connection, it is to inform you that the officer concerned of this department has carried out the inspection on dated 19/05/2025 of the above mentioned School from fire safety point of view in presence of the Mrs. Sunita, Headmistress of the school. The building comprised of ground plus two upper floors. Following shortcomings were observed during the time of inspection.

1. An additional staircase width of 0.80 meter (Iron) found removed.
2. First aid hose reels not provided.
3. Terrace pump capacity 450 lpm head 40 meter shall be required.
4. An overhead tank capacity 10,000 liters shall be required.
5. Exit Signage not provided.

In view of the above, the building cannot be considered for issuance of Fire Safety Certificate at this stage. Therefore, you are requested to rectify the above mentioned shortcomings under intimation to this office for further course of action.

Yours faithfully

(ATUL GARG)
DIRECTOR

DELHI FIRE SERVICE

Copy to:-

The Dy. Director of Education
B-Block, Yamuna Vihar, Delhi-110053