

0/98

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE
NEW DELHI- 110 001

No.F.6/DFS/MS/EH/2025/SZ/ 289

Dated: 13/06/2025

To,

The Joint Commissioner (Lic.)
1st floor Police Station Defence Colony,
New Delhi

**Subject:-Regarding renewal of Fire Safety Certificate in r/o M/s Anutham Guest House,
located at E-147, FF, SF & TF, Saket, New Delhi-110017.**

Sir,

This has a reference to MCD online application ID No. 2025052308958 dated 23/05/2025 on the subject cited above. In this connection, it is to inform you that the side was visited by officer concerned of this department on dated 09/06/2025 in presence of Manager and observed that the management has still not complied the shortcoming by this department vide letter No. F.6/DFS/MS/GH/2025/SZ/30 dated 15/01/2025 (copy enclosed).

In view of the above, Fire Safety Certificate cannot be considered at this stage. You are requested to rectify the shortcomings communicated vide above mentioned letter under intimation to this office for further action.

Yours faithfully

Encl. As above

(ATUL GARG)
DIRECTOR
DELHI FIRE SERVICE

2.

c



2/92 75
Azadi Ka
Amrit Mahotsav

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001

No. F.6/DFS/MS/GH/2025/SZ/ 30

Dated: 15/01/2025

To

The Joint Commissioner of Police (Lic.),
1st Floor, P.S. Defense Colony
New Delhi-110049

Sub: Renewal of Fire Safety Certificate in r/o M/s Anutham Guest House located at E-147, FF, SF & TF, Saket, New Delhi-110017

Sir,

This has reference to online application No. 2024122318309 dated 24/12/2024. In this connection, it is to inform you that the said premise was inspected by the officer concerned of this department on dated 06/01/2025 in the presence of Mr. Himanshu Sharma of the guest house, from fire safety point of view. During the inspection, the shortcomings observed are as below.

1. Smoke management system provided not integrated with MCPs at upper floors.
2. First-aid hose-reel provided found non-functional.
3. CO. Monoxide detector & alarm found removed.

In view of the above, the application for renewal of fire safety certificate is rejected. The occupancy of the premises in the absence of requisite fire safety certificate/arrangements shall be at the risk and liability of the owner/occupier. The local/licensing authority may take suitable necessary action as deemed fit.

Yours faithfully,

(ATUL GARG)
DIRECTOR
T. No. 011-23414000

Copy to: -

1. Sh. Akshay M/s Anutham Guest House at E-147, FF, SF & TF, Saket, New Delhi-110017