

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6 /DFS/MS/Industrial/SZ/2025/ 531

Dated://///2025

To,

The Authority Signatory, Arun Hosiery Mill Shed No. 151, Okhla Industrial Estate, Phase – III, New Delhi – 110020.

Subject: - Regarding grant of Fire Safety Certificate in r/o M/s Arun Hosiery Mill located at Shed No. 151, Okhla Industrial Estate, Phase – III, New Delhi – 110020.

Sir,

This has a reference to your outdoor dairy No. 6731 dated 06/10/2025, on the subject cited above. In this connection, it is to inform you that premises was inspected by the officer concerned of this department on 27/10/2025 in the presence of Mr. S. K Sharma and observed that building comprised of Basement, Stilt, Ground plus two upper floors and following shortcomings were observed during time of inspection:

- 1. Fire Check Door found removed.
- Smoke Management System found removed.
- 3. Automatic Sprinkler System provided but not functional.
- 4. Fire pump of capacity 900 LPM provided but not functional.
- 5. Overhead water storage tank of capacity 20,000 liters is provided against requirement of 25,000 liters.
- 6. Exit & floors Signage's not provided at strategic location in the building.

In view of above shortcomings, the application for issuance for Fire Safety Certificate is rejected. The occupancy of the building/premises in absence of requisite fire safety arrangements shall be at the risk and liability of the management. The Authority/Statutory Authority may take suitable necessary action as deemed fit.

Yours faithfully,

(A.K.Malik) Dy. Chief Fire Officer

**Delhi Fire Service** 

Copy to: -

1. The Executive Engineer (Building), South DMC, Jal Vihar, Lajpat Nagar, New Delhi - 110024.