्राजादी म DFA + F7

No. F6/DFS/MS/School/NDZ/2025/886

Dated: [] /07/2025

FIRE SAFETY CERTIFICATE

Certified that the Arvind Bharti Public School located at H- Block, New Ganga Vihar, Delhi - 110094. Comprised of ground plus one upper floors, owned / occupied by Arvind Bharti Public School was issued FSC vide letter No. F6/DFS/MS/School/2018/1419 dated 18/06/2018. The School building have complied with the fire prevention and fire safety requirements in accordance with the Circular No.F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated01/03/2011 issued by the Director of Education and re-inspected by the officer concerned of this department on 02/07/2025 in presence of Mr. Arvind Sharma (Manager) of the school and that the school building is fit for occupancy class "Educational Building" (Group-B) with effect from 11/0-7/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010 & also conditions printed bellow.

Issued on 1107 2025 at New Delhi by.

(ATVL GARG) DIRECTOR O DELHI FIRE SERVICE

Copy to: -

- 1. The Dy. Director of Education, D Block, Anand Vihar, Delhi 110092.
- 2. The Principal, Arvind Bharti Public School located at H- Block, New Ganga Vihar, Delhi 110094.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- All the means of escape shall be kept free of all the type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipment's and method
 of smooth and speedy safe evacuation of occupants in case of emergency.
- All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

Nlos

| T | | | ECTION REPORT | | | | | |
|-------|--|---------------------------------|------------------|--|---------|--|--|--|
| 01. | Na | me & address of the building | | Arvind Bharti Public School located at H- Block, New Ganga Vihar, Delhi - 110094. | | | | |
| 2. | Bu | ilding is comprised of | | Ground plus one upper floor only | | | | |
| 3. | Ту | pe of occupancy | Educational | Educational | | | | |
| 4. | Ty | pe of case | Renewal | Renewal | | | | |
| 5. | Details of previous FSC | | F6/DFS/MS/Sch | F6/DFS/MS/School/2018/1419 dated | | | | |
| | | | 18/06/2018 | 18/06/2018 | | | | |
| 06. | Fir | e safety directives letter no. | F.16/Estate/CC/ | F.16/Estate/CC/Fire Safety/2011/3298 to 3398 | | | | |
| | | • | dated 01/03/2011 | | | | | |
| 7. | Da | Date of inspection 02/07/2025 | | | | | | |
| 8. | Name of the inspecting officers Yashwant Singh Meena ADO (L.N) | | | 1) | | | | |
| 09. | - | me of the designation of office | | | | | | |
| | | om the building side | | 1994 | | | | |
| 10. | | ear of construction | 1994 | | | | | |
| 11. | 1 - | oplicant's letter no. | Outdoor dairy n | o.2868 dated 19/0 | 6/2025 | | | |
| S.No | | inimum standard of fire | Circular | Provided at | Remarks | | | |
| J. 10 | | evention and fire safety U/R 33 | Requirement | site | MR/NMR | | | |
| | | | | | | | | |
| | | | | | | | | |
| 01. | A | ccess to Building: | | | MR | | | |
| | A | Road width | 6.0 mtrs. | 10 mtrs. | N/A | | | |
| | В | Gate width | N/A | N/A | N/A | | | |
| | C | C Width of internal road N/A | | | | | | |
| 02. | Number, Width, Type and Arrangement of Exits: | | | | | | | |
| | A | Number of staircases | 01 no. | 02 nos. | MR | | | |
| | _ | a Upper floor C Basement | N/A | N/A | N/A | | | |
| | В | C Basement Width of staircases | 1022 | | | | | |
| | В | a Upper floor | 1.50 mtrs. | 01 mtrs each | MR | | | |
| | - | C Basement | N/A | N/A | N/A | | | |
| | C | Protection of exits | | * | | | | |
| | | a Fire check door | N/A | N/A | N/A | | | |
| | \vdash | b Pressurization | N/A | N/A | N/A | | | |
| | D | No. of continuous | 01 no. | 01 no. | MR | | | |
| | | staircases to terrace | | | | | | |
| | E | Width of corridor | 1.50 mtrs. | 1.50 mtrs | MR | | | |
| | F | Door size | 1.0 mtr | 1.0 mtr. | MR | | | |
| 03. | Co | mpartmentation: | | | | | | |
| | A | Fire check door | N/A | N/A | N/A | | | |
| | В | Sealing of electrical shafts | N/A | N/A | N/A | | | |
| | C | Fire rating of shaft door | N/A | N/A | N/A | | | |
| | D | Water curtain | N/A | N/A | N/A | | | |
| | E | Fire dampers | N/A | N/A | N/A | | | |
| 04. | Sn | oke Management System: | | 1071 | IN/A | | | |
| | A | Basement | N/A | N/A | NIA | | | |
| | В | Upper floor | N/A | N/A | N/A | | | |
| | | | | IVA | N/A | | | |

| Arvind Bharti Public School located at H- Block, New Ganga Vihar, Delhi - 110094. | N |
|---|---|
| Arving bildi a 1 22.10 | |

| 05. | F | ire Extinguisher: | 04- | | | |
|-----|---|-------------------------------|---------------------|---------------------|------|--|
| - | A | T 1hare | 04 nos. | 06 nos. | M | |
| | В | + | ABC/CO ₂ | ABC/CO ₂ | M | |
| | C | ISI marking | ISI Marked | ISI Marked | M | |
| 06. | + | irst-Aid-Hose Reel: | | | | |
| 00. | A | Total numbers of each floor | N/A | N/A | N | |
| | В | 1 Class real base | N/A | N/A | N | |
| | C | Nozzle diameter | N/A | N/A | N | |
| 07. | Automatic Fire Detection and Alarming System: | | | | | |
| - | A | T = 01 + -4-m | N/A | N/A | N/A | |
| | В | Location of main panel | N/A | N/A | N/A | |
| | C | Location of repeater panel | N/A | N/A | N/A | |
| | D | Alternate source of power | N/A | N/A | N/A | |
| | E | Hooters | N/A | N/A | N/A | |
| 08. | _ | OEFA: | N/A | N/A | N/A | |
| 9 | _ | iblic Address System: | N/A | N/A | N/A | |
| 0. | At | tomatic Sprinkler System: | | | 10/1 | |
| | A | Basement | N/A | N/A | N/A | |
| | В | Upper floor | N/A | N/A | N/A | |
| Ì | C | Sprinkler above false ceiling | N/A | N/A | N/A | |
| 1. | Int | ternal Hydrants: | | IVA | N/A | |
| | A | Size of riser/down-comer | N/A | N/A | NI/A | |
| 1 | В | Number of hydrants per floor | N/A | N/A | N/A | |
| Ī | C | Hose box | N/A | | N/A | |
| 2. | Ya | rd Hydrants: | 1071 | N/A | N/A | |
| | A | Total number of hydrants | N/A | N/A | 7 | |
| | B | Hose box | N/A | N/A | N/A | |
| 3. | Pu | mping Arrangements: | N/A | N/A | N/A | |
| | G | round level | | | | |
| | A | Discharge of main pump | NI/A | | | |
| | В | Head of main pump | N/A | N/A | N/A | |
| | C | Number of main pumps | N/A | N/A | N/A | |
| 1 | D | Jockey pump out put | N/A | N/A | N/A | |
| - | E | Jockey pump head | N/A | N/A | N/A | |
| - | F | Standby pump out put | N/A | N/A | N/A | |
| - | G | Standby pump head | N/A | N/A | N/A | |
| - | H | Auto starting /manual stonnia | N/A | N/A | N/A | |
| 1 | | 1 uitip nouse account | N/A | N/A | N/A | |
| 1 | Terrace Level | | N/A | N/A | N/A | |
| A | 4 | Discharge of nume | | | -T | |
| - | 3 | riead of the nump | N/A | N/A | N/A | |
| (| | Power supply | N/A | N/A | N/A | |
| I |) | Auto starting of pump | N/A | N/A | N/A | |

N/A

| Arvind Bharti Public School located at H- Block, New Ganga Vihar, Delhi – 110094. | 1114 |
|---|------|
|---|------|

| 14. | Ça | ptive Water Storage for Fire Fight | ing: | | |
|-----|--------------|------------------------------------|------|-----|-----|
| | A | Underground tank capacity | N/A | N/A | N/A |
| | В | Draw-off connection | N/A | N/A | N/A |
| | C | Fire service inlet | N/A | N/A | N/A |
| | D | Access to tank | N/A | N/A | N/A |
| 1 | E | Overhead tank capacity | N/A | N/A | N/A |
| 15. | Ex | it Signage: | N/A | N/A | N/A |
| 16. | Pre | ovision of Lifts: | | | |
| | A | Pressurization of lift shaft | N/A | N/A | N/A |
| | В | Pressurization of lift lobby | N/A | N/A | N/A |
| | C | Communication in lift car | N/A | N/A | N/A |
| | D | Firemen's grounding switch | N/A | N/A | N/A |
| | E | Lift signage | N/A | N/A | N/A |
| 17. | | andby Power Supply: | NA | N/A | N/A |
| 18. | Refuge Area: | | | | |
| | A | Total area | N/A | N/A | N/A |
| | В | Location | N/A | N/A | N/A |
| 19. | Fir | re Control Room: | | | N/A |
| | A | Detector system panel | N/A | N/A | N/A |
| | В | Flow switch panel | N/A | N/A | |
| | C | PA system panel | N/A | N/A | N/A |
| | D | Battery backup | N/A | N/A | N/A |
| | E | Building floor plans | N/A | N/A | N/A |
| 20. | | ecial Fire Protection systems for | NA | N/A | N/A |
| 20. | | otection of special Risks, if any: | | | |

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/2018/1419 dated 18/06/2018 under the Circular no F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended to be renewed.

Signature of the Inspecting Officer

Name: - Yashwant Singh Meena

Designation: - ADO (L.N)