## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

ण्याचीना अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2025/ 554

Dated: 29 /04/2025

## FIRE SAFETY CERTIFICATE

Certified that the ASN Sr. Sec. School located at Mayur Vihar Phase-1, Delhi - 110091, comprised of Ground plus three upper floors, owned/occupied by ASN Sr. Sec. School was issued Fire Safety Certificate vide letter No. F6/DFS/MS/School/NDZ/2022/507 dated 12/05/2022. The School building was re-inspected by the officer concerned of this department on 15/04/2025 in presence of Mr. Swarnima Luthra (Principal) and observed that all the fire prevention and fire safety arrangements provided in the premises found in good working condition. The premises have therefore deemed complied with the Fire Prevention and Fire Safety requirements in accordance with Circular No. F16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by Director of Education and that the building is fit for occupancy class "Educational Building" (Group-B) as above Ground + 03 upper floors only with effect from [2] /04/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS rule 2010. Subject to conditions printed below.

Issued on 29/04/2025 at New Delhi by.

(ATUL GARG)
DIRECTOR
OCDELHI FIRE SERVICE

## Copy to:-

- 1. The Director of Education, (GNCT), Old Secretariat, Civil lines, New Delhi 110054.
- 2. The Principle, ASN Sr. Sec. School, Mayur Vihar Phase-1, Delhi 110091.

## **Conditions for the validity of Fire Safety Certificate**

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule(1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities concerned.
- 6. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on <a href="www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>.

N/23

			10/23					
		INSP	ECTION REPORT					
1	N	ame & address of the building	ASN Sr. Sec. School at Mayur Vihar Phase-1					
			Delhi-110091.					
2	В	uilding is comprised of	Ground plus thr	avoort 4th a				
			addition/ alternat	tion as per guideli	na isawal law			
			No.F6/DFS/MS/	BP/2020/42 dated	d 04/02/2020			
			but 4 <sup>th</sup> floor still	not constructed	04/02/2020			
3	Т	ype of occupancy	Educational Buil					
1	-	ype of case	Renewal	ung				
1	_	etails of previous FSC		10107/0000/505				
7	ool/NDZ/2022/507	dated						
_	-			12/05/2022.				
6	_	re safety directives letter no.		2020/42 dated 04.0	2.2020			
7	-	ate of inspection	15/04/2025.	15/04/2025.				
8	N	ame of the inspecting officers	Yashwant Singh	Yashwant Singh Meena ADO (L.N)				
9	N	ıthra (Principal)						
	of	ficer from the building side						
10	Y	ear of construction	2001					
11	A	oplicant's letter no.	Email dated 11/03	Email dated 11/03/2025				
		Minimum standard of fire	Circular	Provided at	Remarks			
s.No		safety requirements as per	Requirement	site	MR/NMR			
	c	ircular no.3298 to 3398 dated			52.7.1. (0.10.7.6) and 0.170.600.1326.9.2			
		01.03.2011	1					
	Access to Building:							
	A	Road width	12 mtrs.	24 mtrs.	MR			
	B	Gate width	4.5 mtrs.	5 mtrs.	MR			
ĺ	C	Width of internal road						
	_		N/A	5 mtrs.	MR			
2	Number, Width, Type and Arrangement of Exits:							
1	A	Number of staircases						
1		a Upper floor	02 no.	02 nos.	MR			
		c Basement	N/A	N/A	N/A			
	B	Width of staircases						
		a Upper floor	1.50 mtrs	1.5 m each	MR			
		b Basement	N/A	N/A	N/A			
	C	Protection of exits						
		a Fire check door	N/A	N/A	N/A			
	_	b Pressurization	N/A	N/A	N/A			
3	D	No. of continuous staircases	01 no.	02 no.	MR			
	10	to terrace						
	E F	Width of corridor	1.50 mtrs.	1.68 mtrs.	MR			
		Door size	1.0 mtr.	1.2 mtr.	MR			
		mpartmentation:		r				
	A B	Fire check door	NA	NA	NA			
	C	Sealing of electrical shafts	N/A	N/A	N/A			
	D	Fire rating of shaft door Water curtain	N/A	N/A	N/A			
	E	Fire dampers	N/A	N/A	N/A			
			N/A	N/A	N/A			
	_	oke Managamant S	14/21					
	Sm	oke Management System:	1					
	_	oke Management System:  Basement Upper floor	N/A N/A	N/A N/A	N/A N/A			

1211

ASN Sr. Sec. School at Mayur Vihar Phase-1, Delhi-110091.

5.	\ \mathrea{I}								
	A	Total numbers	18 nos.	24 nos.					
	В	Types	CO <sub>2</sub> & ABC	CO <sub>2</sub> & ABC	M. M.				
	C	ISI marking	ISI Marked	Marked Provided					
6	First-Aid-Hose Reel:								
	A	Total numbers of each floor	03 nos.	03 nos.	MR				
	В	Length of hose reel hose	30 mtrs.	30 mtrs.	MR				
	C	Nozzle diameter	05 mm	05 mm	MR				
7	Automatic Fire Detection and Alarming System:								
_	A	Type of detectors	N/A	N/A	N/A				
	В	Location of main panel	N/A	N/A	N/A				
	C	Location of repeater panel	N/A	N/A	N/A				
	D	Alternate source of power	N/A	N/A	N/A				
	E	Hooters	N/A	N/A	N/A				
3	M	OEFA:	N/A	N/A	N/A				
)	Pu	blic Address System:	N/A	N/A	N/A				
10	+	itomatic Sprinkler System:							
	A	Basement	N/A	N/A	N/A				
	В	Upper floor	N/A	N/A	N/A				
	C	Sprinkler above false	N/A	N/A	N/A				
		ceiling	14/21	1771					
1	Internal Hydrants:								
	A	Size of riser/down-comer	N/A	100 mm	N/A				
	В	Number of hydrants per	N/A	03 nos.	N/A				
		floor							
	C	Hose box	N/A	03 nos.	N/A				
2	Yard Hydrants:								
	A	Total number of hydrants	N/A	N/A	N/A				
	В	Hose box	N/A	N/A	N/A				
3	Pumping Arrangements:								
	Ground level								
	A	Discharge of main pump	N/A	N/A	N/A				
	В	Head of main pump	N/A	N/A	N/A				
	C	Number of main pumps	N/A	N/A	N/A				
	D	Jockey pump out put	N/A	N/A	N/A				
	E	Jockey pump head	N/A	N/A	N/A				
	F	Standby pump out put	N/A	N/A	N/A				
	G	Standby pump head	N/A	N/A	N/A				
	H	Auto starting /manual	N/A	N/A	N/A				
2	<b>T</b>	stopping							
	I Pump house access Terrace Level		N/A	N/A	N/A				
-			·						
-	A B	Discharge of pump	450 LPM	450 LPM	MR				
-	C	Head of the pump Power supply	40 mtrs.	40 mtrs.	MR				
-	D	Auto starting of pump	Required	Provided	MR				
	<i>D</i>	rate starting of pump	Required	Provided	MR				



14	Ca	ptive Water Storage for Fire Fighting:						
	A	Underground tank capacity	50,000 ltr.	50,000 ltr.	MR			
	В	Draw-off connection	Required	Provided	MR			
	C	Fire service inlet	Required	Provided	MR			
	D	Access to tank	Required	Provided	MR			
	E	Overhead tank capacity	10,000 ltr.	25,000 ltr.	MR			
15	Ex	t Signage:	Required	Provided	MR			
16	Provision of Lifts:							
	A	Pressurization of lift shaft	N/A	N/A	N/A			
	В	Pressurization of lift lobby	N/A	N/A	N/A			
	C	Communication in lift car	N/A	N/A	N/A			
	D	Firemen's grounding switch	N/A	N/A	N/A			
	E	Lift signage	N/A	N/A	N/A			
17	Sta	ndby Power Supply:	N/A	N/A	N/A			
18	Re	Refuge Area:						
	A	Total area	N/A	N/A	N/A			
	В	Location	N/A	N/A	N/A			
19	Fire Control Room:							
	A	Detector system panel	N/A	N/A	N/A			
	В	Flow switch panel	N/A	N/A	N/A N/A			
	C	PA system panel	N/A	N/A N/A	N/A			
	D	Battery backup	N/A	N/A N/A	N/A			
	E	Building floor plans	N/A N/A	N/A N/A	N/A			
20	Sr	ecial Fire Protection systems for protection	N/A	IN/A	11//1			

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspection. (Guideline issued vide letter No. F6/DFS/MS/BP/2020/42 dated 04/02/2020 for addition of 4<sup>th</sup> floor on existing building of ground plus three upper floors. 4<sup>th</sup> floor still not constructed.)

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/DFS/MS/School/NDZ/2022/507 dated 12/05/2022 under the Circular no F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01/03/2011 is recommended.

Signature of the Inspecting Officer

Name: - Yashwant Singh Meena

Designation: - ADO (L.N)

D.O./EAST DFA blease

by cto (MSZ)

1 22/04/245

CF.0/ Mys

Directer My My

Bolth P.T.O