

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI **HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001**

No. F6/DFS/MS/Hotel/2025/SZ/ BN &T 09

Dated: 07/03/2025

FIRE SAFETY CERTIFICATE

Certified that the Astir Hall Orana Aurnum at A-15, Rewari Line Industrial Area, Phase-I, New Delhi comprised of 02 tier basements, ground floor plus five upper floors using basement as Storage & Services, ground floor, first floor & second floor as banquet hall, third floor 13 guest rooms, fourth floor 15 guest rooms & fifth floor 15 guest rooms (Total 43 rooms), owned/occupied by M/s A unit of Friendship time Company Pvt. Limited, was issued FSC vide letter No. F6/DFS/MS/Hotel/2022/SZ/07 dated 03.02.2022. The premises was re-inspected by the officer concerned of this department on dated 03.03.2025 in presence of Sh. Karan Kapoor (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service Rules 2010 and that the building/premises is fit for occupancy class "Mixed Occupancy" (Residential & Assembly Building) w.e.f. 07/03/2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule-38 of the Delhi Fire Service Rules, 2010 printed below.

Copy to: -

1 The Commissioner, MCD, Civic Centre, New Delhi: for information regarding use of basement and to ensure the occupancy as detailed above.

2 Online application Id 2024122518379 dated 15.12.2024.

Conditions for validity of Fire Safety Certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.

4. The trained staff should be available round the clock.

- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.

7. Basement shall be used as per the building bye laws.

8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.

9. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior

to its expiry.

427

INSPECTION REPORT

1. Name& address of the building : Astir Hall Orana Aurnum located at A-15, Rewari Line Industrial

Area, Phase-I, New Delhi.

2. Building comprised of : Two basement, ground plus five upper floors

3. Type of Occupancy : Assembly Building (Banquet Hall & Guest House) Mixed

4. Type of Case : Renewal

Details of Previous NOC : F6/DFS/MS/Hotel/2022/SZ/07 dated 03.02.2022
 Fire Safety directives letter No : F6/DFS/MS/BP/2015/297 dated 13/11/2015 & F6/DFS/MS/BP/2019/5209 dated 28/08/2019

7. Date of inspection : 03.03.2025 8. Name of Inspecting Officer : A.D.O. R.K.Yadav

9. Name and designation of officers

From the building side : Sh. Karan Kapoor (Manager)

10. Year of Construction : 2018

	11. Applicant's letter No. Minimum Standards on fire	NBC-2005/2016	Provided at site	Remarks		
0.	prevention and fire safety U/R 33	Requirement		MR/NMR		
	Access to building					
	Road width	12 m	Provided	M/R		
	Gate width	06m	Provided	M/R M/R		
	Width of internal road	06/09 m	Provided	WER		
_	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases			M/R		
	Upper Floors	03 No's GF to TF & 02	Provided	M/K		
	орре: 11001	no.'s IV floor to terrace	Provided	M/R		
	Basements	03 No's	Provided	1727		
	b. Width of staircases	×		14/D		
	Upper Floor	1.50 m each	2.0 m each	M/R		
	Basements	1,50 m each	2.0 m each	M/R		
			The second second second	M/R		
	c. Protection of exits	Required	Provided	- ASSACE		
	Fire check door	Required	Provided	M/R		
	Pressurization d. No. of continuous staircases to	02 Nos.	Provided	M/R		
	terrace	1.50	Provided	M/R		
	e. Width of Corridor	1.50 m	2.0 m each	M/R		
	f. Exit Door Size	1.50 m				
3.	Compartmentation		- 14m			
		Required	Provided	M/R		
	• Fire check door	Required	Provided	M/R		
	Sealing of electrical shafts Fire Rating of shaft door	Required	Provided	M/R		
			Provided	M/R		
	Water Curtain Fire Dampers	Required N/A	N/A	N/A		
	Print to Colon a word in releases to Colonia.	****				
5.	Smoke Management System	Required	Provided	M/R		
	Basements	Required	Natural ventilation	M/R		
	Upper floors	Kequiive	4			
	Fire Extinguishers					
	Total numbers	05 no's/at each floor	Provided	MR MR		
	• Types	W/CO ₂ / CO ₂ type	Provided	MR		
	IS marking	ISI marked	Provided	IVIK		
6.	First-Aid Hose Reels					
	Total numbers are at C	Three	Provided	M/R		
	Total numbers on each floor Length of hose reel hose	30 m	Provided	M/R M/R		

	Automatic fire detection and alarming s	Vstem				
		ystem		M/R		
	Type of detectors (Smoke/Heat)	Required	Provided	MR		
	Location of Main Panel	Required	Provided	N/A		
	 Location of Repeater Panel 	N/A	N/A	MR		
	Alternate source of power	Required	Provided	MR		
	Hooters' Location	Near exits	Provided)4/B		
y.	MOEFA	Required	Provided	M/R		
ie.	Public Address System	Required	Provided	MR		
0.	Automatic Sprinkler System					
	Basement	Required	Provided	M/R M/R		
		Required	Provided	N/A		
	Ground Floor & upper floors Sprinkler above false ceiling	N/A	N/A	N/A		
_						
1.	Internal Hydrants	HOLES IN	Provided	M/R		
	Size of riser/down-comer	100 MM	Provided	M/R		
	Number of hydrants per floor	Three Three	Provided	M/R		
	Hose Box	Three	e a contratado o			
2.	Yard Hydrants		7	M/R		
70	Total number of hydrants	Four	Provided	M/R M/R		
	Hose Box	Four	Provided	IVII K		
13.	Pumping Arrangements		and the same of the same of			
	Ground Level	2280 LPM	Provided	M/R		
	Discharge of main Pump	THE STATE CALLS	Provided	M/R		
	 Head of Main pump Number of main pumps 	80 mtrs Two	Provided	M/R		
	➤ Number of main pumps ➤ Jockey Pump out put	180 LPM (Two)	Provided	M/R		
	> Jockey pump head	80 mtrs	Provided	M/R		
	> Standby Pump out put	2280 LPM	Provided	M/R		
	> Standby Pump Head	80 mtrs	Provided	M/R		
	> Auto Starting/Manual	Required	Provided	M/R		
	Stopping	WY T	Provided	MR		
	> Pump House Access	Required	Provided	MIK		
	Terrace level Discharge of pump	900 LPM	Provided	M/R		
	➤ Head of the pump	40 mtrs	Provided	M/R		
	> Power Supply	Required	Provided	M/R		
	➤ Auto Starting of pump	Required	Provided	M/R		
14.	Captive Water Storage for fire fighting		1127			
7,000	Underground tank capacity	1,00,000 ltrs	1,35,000 ltrs	M/R		
	> Draw-off connection	Required	Provided	M/R		
	> Fire service inlet	Required	Provided	M/R		
	> Access to tank	Required	Provided	M/R		
	Overhead Tank capacity	20,000 ltrs	Provided	M/R		
5.	Exit Signage.	Required	Provided	MR		
				- 1		
6.	Provision of Lifts.					
	Pressurization of Lift Shaft	Required	Provided	MR		
	Pressurization of Lift lobby	Required	Provided	MR		
	Communication In lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	Provided	MR		
7.	Standby power supply	Required	Provided	MR		

Refuge Area.	N/A	N/A	N/A
Total	N/A	N/A	N/A
Location			
Fire Control Room	Required	Provided	MR
19. Detector System Panel	N/A	N/A	N/A
Detector System Panel	Required	Provided	MR
PA System Panel	Required	Provided	MR
Battery backup Building Floor Plans	Required	Provided	MR
O. Special Fire Protection System for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested, checked and found functional at the time of inspection.

Note: - Earlier this department issued FSC dated 05.04.2019 (placed at C-82) for Industrial building occupancy & issued FSC dated 03.02.2022 (placed at C-23) for Residential Building Occupancy but now the building running as Assembly building (Banquet Hall & Guest Rouse)

Keeping in view of the above substantial compliance of the minimum standards of fire prevention and fire safety measures under rules, the FSC was issued vide letter no. F6/DFS/MS/Hotel/2022/SZ/07 dated 03.02.2022, renewal under the rule 35 of the Delhi Fire Service Rules 2010 is recommended.

Signature of Inspecting Officer Name: - R.K. Yadav

Designation: - ADO (JKP)

DO (8W)

4/4/25

Denecter

ADD) WY

PTZ