

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: NEW DELHI-110001

्वयम् पारत एक करन स्वयक्ता की और

No. F.6/DFS/MS/Audi/2025/SZ/ 460

Dated: 03/09/2025

FIRE SAFETY CERTIFICATE

Certified that the Auditorium Building located at Rail Museum, Chanakyapuri, New Delhi–110021, comprised of Ground + Mezzanine + Open-Air Theater at Terrace Floor, owned/occupied by National Rail Museum (Indian Railway) was issued Fire Safety Certificate vide letter No. F6/DFS/MS/Assembly/SZ/2022/126 dated 23/03/2022. The premise was re-inspected by the officer concerned of this department on dated 19/08/2025 in the presence of Sh. Mohinder Singh (SSE–Works) and found that the said premises have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the said building is fit for occupancy class "Assembly Group D" (Auditorium) with effect from the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03/09 /2025 at New Delhi by

(Virendra Singh) Chief Fire Officer Delhi Fire Service

Copy to: -

 Sh. Mohinder Singh (SSE-Works), Northern Railway, San-Martin Marg, Chanakyapuri, New Delhi-110021

Conditions for the validity of Fire Safety Certificate:

- 1. All the means of escape/entry/exit shall be kept free from any obstruction.
- 2. All the fire safety arrangement provided therein shall be maintained in good working conditions at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.
- 3. All the staff members must know the correct method of operation of fire-fighting system.
- 4. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if any.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule37] along with a copy of this certificate, prior to its expiry.

1.	Name & address of the building	Auditorium Bu	ilding a	t Rail Museu	m.
2.	Towns of O	Chanakyapuri, New Delhi-110021.			
3.	Type of Occupancy	Assembly Building Group 'D'			
	Building Comprised of	Ground + Mezzanine + Open-Air Theater at Terrace Floor.			
4.	Type of Case	Renewal			
5.	Details of previous NOC No.	F6/DFS/MS/Assembly/SZ/2022/126 Dt. 23/03/2022			
6.	Fire Safety directives Letter No.	F6/DFS/MS/BP/2001/38 dated 08/01/2001			
7.	Date of inspection	19/08/2025			
8.	Name of the Inspecting Officer	ADO (SJ)			
9.	Name and designation of Officer from the building side	Sh. Mohinder Kumar (SSE-Works)			
10.	Year of Construction	2003			
11.	Applicant's letter No.	Through outdoor dairy No. 4382 dated 31/07/2:			
S.	Minimum standards on fire	Old NOC Provided at site Ren		Remarks	
No.	prevention and fire safety U/R 33	Requirements		8	MR/NMI
1.	Access of building				
	 Road width 	09 mtr		rovided	MR
	Gate width	05 mtr	P	rovided	MR
2	Width of internal road	N/A		N/A	N/A
2.	Number, width, Type & Arrangement	ts of exits			
	a. Number of staircases				
	Upper floors	2 Nos for terrace, 01 l projector & 01 for AF			MR
	Basements			N/A	
	b. Width of staircases		28		
	Upper floors	2m for terrace, 90cm for projector & AHU room 5.85m & 1.50m (Iron) for terrace & 90 cm for mezzanine		MR	
	Basements	N/A		N/A	N/A
	c. Protection of exits	3 4550		790,000,000	52.44.24.25
	Fire check door	N/A	N/A		N/A
	Pressurization	N/A	N/A		N/A
	d. No of continuous staircase to terrace	02 Nos	Provided		MR
	e. Width of Corridor	N/A	N/A		N/A
	f. Door Size	1.50 mtr	P	rovided	MR
3.	Compartmentation	1.00 IIII	» f	1011404	31,120
٥,	Fire check door	N/A		N/A	N/A
	Sealing of electrical shafts	N/A		N/A	N/A
	Fire Rating of shaft door	N/A	· N/A		N/A
	Water Curtain	N/A		N/A	N/A
	Fire Dampers	N/A		N/A	N/A
4.	Smoke Managements System				
	Basement	N/A		N/A	N/A
	Upper floors	12 ACPH	Ex	haust Fan	MR
5.	Fire Extinguishers			Server States	4
	Total numbers	Required		12 Nos	MR
	Types	ABC/CO ₂ /W CO ₂	- 1111	CO ₂ /W CO ₂	MR
- 4	ISI marking	ISI marked	F	rovided	MR
6.	First-Aid Hose Reels		3		
	Total numbers on each floor	06nos.	P	rovided	MR
	Length of hose reel hose	30 mtr	P	rovided	MR
	Nozzle diameter	05 mm	р	rovided	MR

N	-	2	0
13			

7.	Automatic fire detection and alarming	system.	Provided	MR
	Type of detector	Smoke & Heat	Ground Floor	MR
	Location of Main Panel	Required N/A	N/A	N/A
	Location of Repeater Panel	Required	Provided	MR
	Alternate source of power		All Floors	MR
	Hooters' Location	Required Required	Provided	MR
8.	MOEFA		Provided	MR
9.	Public Address System	Required	110	
10.	Automatic Sprinkler System	37/4	N/A	N/A
	Basements	N/A	N/A	N/A
	Upper Floor	N/A		N/A
	 Sprinkler above false ceiling 	N/A	N/A	1112
11.	Internal Hydrants		D 11.4	MR
	Size of riser/down- comer	100 mm	Provided	MR
	Number of hydrants per floor	03 Nos in Audi. & 01 No at Terrace	Provided	32/72
	Hose Box	03 Nos in Audi. & 01 No at Terrace	Provided	MR
12.	Yard Hydrants	10		27/4
	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13.	Pumping Arrangements			
13.	Ground Level			
	Discharge of main pump	1650 LPM	Provided	MR
	> Head of main pump	40 mtr	Provided	MR
	> Number of main pumps	Two	Provided	MR
	> Jockey pump out put	180 LPM	Provided	MR
	Jockey pump head	40 mtr	Provided	MR
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	➤ Auto Staring/Manual stopping	Required	Provided	MR
	Pump House Access	Required	Provided	MR
	Terrace level			
	Discharge of pump	900 LPM	900 LPM	MR
	➤ Head of the pump	40 mtr	40 mtr	MR
	➤ Power supply	Required	Provided	MR
	> Auto starting of pump	Required	Provided	MR
14.	Captive water storage for firefighting			
	 Underground tank capacity 	50,000 Ltr	Provided	MR
	> Draw of connection	Required	Provided	MR
	➤ Fire service inlet	Required	Provided	MR
	> Access to tank	Required	Provided	MR
	Overhead Tank capacity	5,000 Ltr	Provided	MR
15	Exit signage	Required	Provided	7.5387-03581
16.	Provision of lifts	required	Deprivor	MR
- meretii	> Pressurization of Lift Shaft	NT/A T	NOV 1 to	700
	> Pressurization of lift lobby	N/A	N/A	N/A
	Communication in lift Car	N/A	N/A	N/A
		N/A	N/A	N/A
	Fireman's Grounding Switch	N/A	N/A	N/A
	➤ Lift Signage	N/A	N/A	N/A
7.	Standby power supply	Required	Provided (DG)	
8.	Refuge area	1	Trovided (DG)	MR
	> Total area	N/A		
	► Location	1/2	N/A	N/A
	2000/06/01/2003 2 10/01/01	N/A	N/A	N/A

gr

10	Fire Control Room			
19.	> Detector system panel	N/A	N/A	N/A
3	> Flow Switch Panel	N/A	N/A	N/A
	> PA System Panel	N/A	N/A	N/A
	➢ Battery backup	N/A	· N/A	N/A
	➢ Building Floor Plans	N/A	N/A	N/A
20.	Special Fire Protection Systems for Protection of Special Risks, if any;	N/A	N/A	N/A

The fire protection systems provided in the building were checked, tested at random and found functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards on fire prevention and fire safety as required under the rules, the fire safety certificate issued vide letter No. F6/DFS/MS/Assembly/SZ/2022/126 dated 23/03/2022, renewal under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Accordingly, DFA is put up for approval & signature please.

Signature of the Inspecting Officer

Name: Santosh Kumar Designation: ADO (SJ)

O(so) Mulimeter

Cho | Mulimeter

Principal Director

CFO + Som.

A 20 (\$5)

Siri f. T water is putup for your birg.

CFO + 19 | 11 8