

حى GOVERNMENT OF NATIONAL CAPITAL TERRITOTY OF DELH HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F.6/DFS/MS/WZ/School/2025/ 8 1 8

Dated 25/06/2025

Director

FIRE SAFETY CERTIFICATE

Certified that the Bal Bharti Public School, located at Parwana Road, Pitampura, Delhi110034. comprised of basement + ground + 03 upper floors, was already issued FSC vide letter
No.F6/DFS/MS/School/WZ/2022/467 dated 28/04/2022, Owned/occupied by Bal Bharti Public
School. The premises was re-inspected by officer concerned of this department on 13/06/2025 in the
presence of Smt Sonia Chopra (Principal) and observed that all the fire prevention & fire safety
arrangements provided in the premises found in good working condition. That the building/premises
have deemed complied with fire prevention and fire safety requirements in accordance with rule 33
of the Delhi Fire service Rules 2010 & D.O.E. Circular No. 3298-3398 dated 01/03/20211 and that
the building/premises is fit for occupancy class "Educational" Group-B, (for ground + 03 upper
floors only) with effect from ... 25... 06. 2025.... for a period of three years and subject to
compliance of the conditions mentioned below.

Issued on 25 06 2025 at New Delhi by

Copy to: -

- 1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi.
- 2. The principal/Incharge, Bal Bharti Public School, located at Parwana Road, Pitampura, Delhi-110034.

Conditions for the validity of FSC:-

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- 2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional if fire safety measures, management shall be responsible.
- 4. Any deviations w.r.t. construction, ventilation, occupation, electric installation etc. may be got verified from the concerned authorities.
- 5. The fire safety certificate may not be treated in any case for the regularization of the unauthorized construction/unauthorized use of land, if any.
- 6. All comments/directions of licensing department shall always be permitted and followed.
- 7. The owner/ occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry.
- 8. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 9. The basement shall be used as per BBL.

	_			J 17	7				
		IN	SPEC	TION	REPORT				
1.	Nam					ool, located at Pa	arwana	Road	
						ooi, iocaica ai i	a wala	itoud	
2	Tyme	of Occupancy	Pitam	ipura, D	elhi-110034.	Cound + 02 Unner F	loors onl	v)	
					Basement + C	Ground + 03 Upper F	10013 0111	"	
	.5.5		Rene			200467 1 . 120/04	2022		
4. Details of previous NOC					Control of the Contro	022/467 dated 28/04/	2022		
5.					ated 01/03/20	11 & NBC Part-IV			
6.			251.52	/2025					
_					gh ADO (MN				
8.	. Nam		Smt S	Sonia Cl	nhabra (Princi	pal)			
		cers from the building side					2/04/202	2)	
9	. Yea	r of Construction	2000	(As per	previous insp	pection report dated 1	3/04/202	4)	
1	-		Letter no. 15339/BBPS/2025/ 21/04/2025 Required as par Pule 35(6) Provided at site Remai					-le	
S.	1	inimum Standards on fire				Provided at site	MR/N		
No	prev	ention and fire safety U/R 33		of DFS I	Rule 2010		MININ	VIIX	
	Acce	ss to building		1.27		Provided	MR	,	
	•	Road width		1937	essible	Provided	MR		
	•	Gate width		74(2:0:0)	essible	NA	NA	<u></u>	
	•	Width of internal road			NA	INA		8	
2		ber, Width, Type & Arranger	ment	of Exits					
	a. Nu	mber of staircases				Provided	MR		
	•	Upper Floors		04		Provided		MR	
	•	Basements		0	8	Tiovided			
	b. W	idth of staircases	-	1.5	- 13	30 cm x 3 &126 cm x	I M	R	
	•	Upper Floors	-		***	ed in 3 parts B(1)=1.25		MR	
		Basements	- 20	.5 L	1.68n	1 x 1 & 130 cm x 1		ì	
			B(2)=1.23m x 1 & 1.71 m x 1						
			-		B(3)=	=111 cm & 143 cm			
	c. Pr	otection of exits		N.	Α -	NA	NA NA		
	•	Fire check door	-	N.		NA NA	NA NA		
	. •	Pressurization	-	0		Provided MI			
	e. No	. of continuous staircases to terrac	e	1.5		Provided	MR		
	1.550	dth of Corridor	-			Provided	MI		
		or Size		11	in	11071404	(8)		
3	Com	partmentation.		×**	Tri0 1 0:	basement sealed wi	th heigh	N/	
		Fire check door		NA	LITT SNATT IF	NA	ui blick	NA NA	
	•	Sealing of electrical shafts	-	NA		NA NA		N/	
	•	Fire Rating of shaft door		NA		NA NA		N/	
	1	Water Curtain	-	NA		NA NA	- 1	N/	
	•	Fire Dampers		NA		INA		147	
4	Smol	ke Management System.	71						
		Basements		Re	quired	Provided	M	R	
		Upper floors		j	NA	NA	N/	A	
5	Pina	Extinguishers					1		
5	FIFE	Total numbers		20	Nos.	Provided	M	R	
	I	Types	14		ABC type	Provided	M		
		IS marking		in comme	marked	Provided	M		
6	Firet	-Aid Hose Reels.		101	umou	Tiovided	IVI		
	T. II St	Total numbers on each floor			04	Provided	1 14	D	
		Length of hose reel hose		-	04 30 m	Provided	M M		
		Nozzle diameter			mm	Provided			
		- IOZZIO GIUIICIOI		3	111111	riovided	M	ĸ	

7	Automatic fire detection and alarming system.					
	Type of detectors	NA NA	NA	NA.		
	 Location of Main Panel 	NA	NA NA	NA		
	 Location of Repeater Panel 	NA	NA.	NA		
	 Alternate source of power 	NA	NA	NA		
	Hooters' Location	NA	NA	NA		
8	MOEFA	NA	Provided	NA		
9	Public Address System.	NA	Provided	NA		
10	Automatic Sprinkler System.					
	Basement	Required	Provided	MR		
	 Upper Floor 	ÑΛ	NA	NA		
	 Sprinkler above false ceiling 	NA	NA	NA		
11	Internal Hydrants					
	Size of riser/down-comer	Required	Provided	MR		
	 Number of hydrants per floor 	Required	Provided	MR		
	Hose Box	Required	Provided	MR		
12	Yard Hydrants.					
	Total number of hydrants	NA	Provided	NA		
	Hose Box	NA	Provided	NA		
13	Pumping Arrangements.					
	Ground Level			NA		
	 Discharge of main Pump 	NA	NA NA	NA NA		
	Head of Main pump	NA	NA NA	NA NA		
	Number of main pumps	NA	NA NA	NA NA		
	Jockey Pump out put	NA NA	NA NA	NA		
	Jockey pump headStandby Pump out put	NA NA	NA NA	NA		
	Standby Pump Head	NA NA	NA NA	NA		
	> Auto Starting/ Manual stopping	NA NA	NA NA	NA		
	➤ Pump House Access	NA NA	NA	NA		
	Terrace level					
-	Discharge of pump	2 x 450 LPM	Provided	MR		
	➤ Head of the pump	40 m	Provided	MR		
	Power Supply	Required	Provided	MR		
	➤ Auto Starting of pump	Required	Provided	MR		
4	Captive Water Storage for fire fighting	3.				
	Underground tank capacity	NA	NA	NA		
	Draw-off connection	NA	NA	NA		
ē,	➤ Fire service inlet	NA	NA	NA		
	Access to tank	NA	NA	NA		
	 Overhead Tank capacity 	10,000ltrs	Provided	MR		
E	xit Signage.	Required	Provided	MR		
P	rovision of Lifts.		* II - L III			
	Pressurization of Lift Shaft	NA	NA	NA		
	Pressurization of Lift lobby	NA	NA	NA		
	Communication In lift Car	Required	Provided	_		
	Fireman's Grounding Switch	Required	Provided	MR		
	Lift Signage	Required	riovided	MR		

		NYI		
1	Standby power supply	NA	NA	NA
	Refuge Area.			
18	Total Area	NA	NA	NA
	Location	NA	NA	NA
19	Fire Control Room			
_	Detector System Panel	NA	NA	NA
	Flow Switch Panel	NA	NA	NA
	PA System Panel	NA	NA	NA
	Batter backup	NA	NA	NA
	Building Floor Plans	NA	NA	NA
20	Special Fire Protection Systems for Protection of special Risks, if any:	NA	NA	NA

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the rules, the NOC vide letter no F6/DFS/MS/School/WZ/2022/467 dated 28/04/2022, renewal under the rule 35 of the Delhi Fire Service rules 2010 is recommended.

1mn

Bucealepu)

Signature of the Inspecting Officer

Name: - Sarabjeet Singh Designation: - ADO (MN)

Director

my form

Sir, F. T is

out up for your

Kind persual

23/6/00