

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001



No F 6/DFS/MS/2025/School/WZ/5/14

Dated: 22/04/2025

FIRE SAFETY CERTIFICATE

Certified that the Bal Bharti Nursery School, Pocket-7, Sector-25, Rohini, Delhi-85, comprised of Ground + One upper floor owned/occupied by Bal Bharti Nursery School was granted FSC by this department vide letter No. F.6/DFS/MS/2022/School/WZ/393 dated 06.04.2022. The premises was re-inspected by the officer concerned of this department on 04.04.2025 in the presence of Miss. Anjana (Headmistress) and observed that all the fire prevention and fire safety arrangements as provided in the premises found in good working condition. The premises have deemed complied with requirements of circular issued by Director of Education letter no 3298-3398 dated 01.03.2011 and the building/ premise is fit for occupancy Group B Educational with effect from 22/04/2025 for a period of three years, subject to compliance of the conditions mentioned below:

Issued on 22/04/2025 at New Delhi

(Atal Garg) IMRECTOR Ph; 011-23414000

Copy to: -

1. The Director, Education, Government of N.C.T of Delhi. Old Sect. Delhi - 54.

2. The Principal, Bal Bharti Nursery School, Pocket-7, Sector-25, Rohini, Delhi-85.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.

Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

INSPECTION REPORT

1. Name & address of the building: Bal Bharti Nursery School, Pocket-7, Sector-25, Rohini, Delhi-85.

2. Type of Occupancy : Educational

3. Comprise of building : Ground + 01 upper floor & 2^{nd} floor under construction 4. Type of Case

: Renewal (Ground + 01 upper floors)

5. Details of Previous NOC : F.6/DFS/MS/2022/School/WZ/393 dated 06.04.2022 & F.6/DFS/MS/School/2022/BP/307 dated 28.06.2022.

6. Fire Safety directives letter No : Director of Education Cir. dated 01.03.2011

7. Date of inspection : 04.04.2025

8. Name of Inspecting Officer : A.K.Sharma ADO(Rohini)

9. Name and designation of officers

From the building side : Miss. Anjana (Headmistress)

10. Year of Construction : 2005 & 06

11. Applicant's letter No.

S. No.	Applicant's letter No. : Online e-mai		Dir. of	Provided at site	Remarks		
	and fi	re safety U/R 33	- CON (PENNS)	Provided at site	MR/NMF		
	Access to building						
	•	Road width	Accessible	Accessible	MR		
	•	Gate width	Direct Accessible	Direct Accessible	MR		
	•	Width of internal road	-NA-	-NA-	-NA		
2.	Number, Width, Type & Arrangement of Exits						
	a. N	umber of staircases					
		Upper Floors	01nos.	02nos.	MR		
		Basements	-NA-	-NA-	-NA		
	b. Wi	dth of staircases					
		Upper Floor	1.5m	1.50m & 0.85m	MR		
		Basements	-NA-	-NA-	-NA		
		tection of exits					
		e check door	-NA-	-NA-	-NA		
	•	Pressurization	-NA-	-NA-	-NA		
		o. of continuous staircases to terrace	-NA-	-NA-	-NA		
		dth of Corridor	-NA-	-NA-	-NA		
	100000	oor Size	1.0m	1.10m	MR		
3.		artmentation		73.5			
	•	Fire check door	-NA-	-NA-	-NA		
		Sealing of electrical shafts			10, 15, 125		
		Fire Rating of shaft door	-NA-	-NA-	-NA		
		Water Curtain	-NA-	-NA-	-NA		
		Fire Dampers	-NA-	-NA-	-NA		
4.	S-mali	e Management System	-NA-	-NA-	-NA		
4.		Basements					
	•		-NA-	-NA-	-NA		
	•	Upper floors	12 a/c per hour	Natural ventilated	MR		
5	Fire Extinguishers						
	•	Total numbers	03nos.	11nos.	MR		
	•	Types	ABC/CO2	ABC-11	MR		
	Tri-	IS marking	ISI marked	Yes	MR		
6.	rirst-	Aid Hose Reels	NYA I	44	11		
	•	Total numbers on each floor	-NA-	-NA-	-NA		
		Length of hose reel hose Nozzle diameter	-NA-	-NA-	-NA		
7.	100	natic fire detection and alarming syste	-NA-	-NA-	-NA		
	ALUIUI	Type of detectors	-NA-	NA I			
-		-) Po or detectors	-11//	-NA-	-NA		

MIN

	T di Odi P I	NTA	37.				
	Location of Main Panel Location of Bonnata Bonnal	-NA-	-NA-	-NA			
	Location of Repeater Panel	-NA-	-NA-	-NA			
	Alternate source of power	-NA-	-NA-	-NA			
	Hooters' Location	-NA-	-NA-	-NA			
	MOEFA Dublic Address System	-NA-	-NA-	-NA			
).	Public Address System Automatic Sprinkler System	-NA-	TVA	-NA			
J	Basement	-NA-	-NA-	-NA			
		-NA-	-NA-	-NA			
	Ground & Upper Floors Sprinkler above false ceiling	-NA-	-NA-	-NA			
	Internal Hydrants						
1	Size of riser/down-comer	-NA-	-NA-	-NA			
	Number of hydrants per floor	-NA-	-NA-	-NA			
	Hose Box	-NA-	-NA-	-NA			
,	Yard Hydrants						
2.	Total number of hydrants	-NA-	-NA-	-NA			
		-NA-	-NA-	-NA			
,	Hose Box Pumping Arrangements						
3.	Ground Level			1			
		-NA-	-NA-	-NA			
		-NA-	-NA-	-NA			
	> Head of Main pump	-NA-	-NA-	-NA			
	Number of main pumps	-NA-	-NA-	-NA			
	➤ Jockey Pump out put	-NA-	-NA-	-NA			
	Jockey pump head	-NA-	-NA-	-NA			
	Standby Pump out put	-NA-	-NA-	-NA			
	Standby Pump Head		-NA-	-NA			
	 Auto Starting/Manual Stopping 	-NA-		-NA			
	> Pump House Access	-NA-	-NA-	-NA			
	Terrace level			NIA			
	> Discharge of pump	-NA-	-NA-	-NA			
	> Head of the pump	-NA-	-NA-	-NA			
	> Power Supply	-NA-	-NA-	-NA			
	> Auto Starting of pump	-NA-	-NA-	-NA			
14.	Captive Water Storage for fire fighting						
14.	Underground tank capacity	-NA-	-NA-	-NA			
	> Draw-off connection	-NA-	-NA-	-NA			
	Fire service inlet	-NA-	-NA-	-NA			
	> Access to tank	-NA-	-NA-	-NA			
	Overhead Tank capacity	-NA-	-NA-	-NA			
		-NA-	-NA-	-NA			
15.	Exit Signage.	ACTUAL CO.					
16.	Provision of Lifts.	NIA	-NA-	-NA			
	Pressurization of Lift Shaft	-NA-	-NA-	-NA			
_	Pressurization of Lift lobby	-NA-	-NA-	-NA			
	Communication In lift Car		-NA-	-NA			
	Fireman's Grounding Switch	-NA-	-NA-	-NA			
	Lift Signage	-NA-		-NA			
17.	Standby power supply	-NA-	-NA-	-11/1			
18.	Refuge Area.			- X7.			
10.	> Total Area	-NA-	-NA-	-NA			
	> Location	-NA-	-NA-	-NA			
19.	Fire Control Room						
	Detector System Panel	-NA-	-NA-	-NA			
	- Detector by steller and	-NA-	-NA-	-NA			

1	Flow Switch Panel	-NA-	-NA-	-NA
	PA System PanelBattery backup	-NA-	-NA-	-NA
		-NA-	-NA-	-NA
_	Building Floor Plans Special Fire Protection System for	-NA-	-NA-	-NA
20.	Protection of special Risks, if any:		test shacked	-1 found

The fire protection systems provided in the building were test checked and found

functional at the time of inspection.

Keeping in view of the deemed compliance of the minimum standards of the fire prevention and fire safety measures required stipulated in Director of Education Circular, the FSC issued vide letter no. F.6/DFS/MS/2022/School/WZ/393 dated 06.04.2022 is recommended for renewal under rule 37 of the Delhi Fire Service rules 2010.

> Signature of the Inspecting Officer Ajay Kumar Sharma Name Designation ADO(Rohini)

DCFO! ///S-INID Dated 11/04/25...

FT dettu is fort up for kind pennsal and Signature please.