

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

F.6/DFS/MS/EH/2025/SZ/ 73

Dated. 28./.2/2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the name & Style of M/s Barcode located at Plot No 228, 3rd Floor, Sector-9, Dwarka, New Delhi 110075 in the building comprised of Basement, Ground plus Three upper floor owned/occupied by A unit of The Vintage Boulevard was issued Fire Safety Certificate by this department vide letter No. F6/DFS/MS/SZ/2022/EH/68 dated 14/03/2022. The restaurant premise was re-inspected by the officer concerned of this department on 25/02/2025 in the presence of Mr. Sanjay Pal and found that the said premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (Restaurant running at 3rd Floor only) and validity upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 28 / 02 / 2025 at New Delhi by

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch, 1st Floor, PS Defence Colony, New Delhi 110049 (Ref. MCD Portal ID 2025013101297 dated 31/01/2025)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to nonfunctional fire safety measures shall be at the responsibility of the management.

3. The basement shall be used as per the provisions of BBL-/NBC Part- IV.

4. All the staff members must know the correct method of operation of fire fighting system.

5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is www.dfs.delhigovt.nic.in

6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of UBBL-2016), if

7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to



1	4		4			
1.74	Name & Address - 5:1	CTION REPORT				
2	radicss of the Building	M/s Barcode (unit of The Vintage Boulevard) located a Plot No 228, 3 rd Floor, Sector-9, Dwarka, New Delhi -75				
	Type of Occupancy	Assembly Duilding "Groups D"				
3	Building Comprised of	Basement, Ground + 03 upper floors (Restt. at 3 rd Flo				
		only)				
4	Type of Case	Renewal				
5	Details of Previous NOC	F6/DFS/MS/SZ/2022/EH/68 dated 14/03/2022				
6	Fire Safety Directives Letter No	Nil				
7	Date of Inspection	25/02/2025				
8	Name of the Inspecting Officers	ADO (BCP)		Diego President		
9	Name & Designation of Officers from the building side	Mr. Sanjay Pal				
10	Year of construction	2009				
11	Applicant letter No.	MCD Portal ID 2025013101297 dated 31/01/2025				
S. No.	Minimum standards on Fire Prevention and Fire Safety U/R 33	Old NOC Provided at Site Remarks Requirement MR/NMR				
1	Access to Building.		STRUMENT THE EXPLICATION			
	Road width	06 mtr	Provided	MR		
	Gate width	4.5 mtr	Directly accessible	MR		
	Width of internal road	NA	N/A	N/A		
2	Number, width, type and arrangements of	f exits.	MINISTER OF STREET			
	a. Number of Staircase	-	Signature research			
	Upper floors	02 Nos	Provided	MR (old case		
	Basement floor	01 No	01 No	Old Case		
	b. Width of Staircase	- Levis	and the second state of	1		
	Upper floors	1.50 mtr each	1.50 mtr & 1.50 mtr (iron)	MR (old case		
	Basement floor	1.50 mtr	1.50 mtr	Old case		
	c. Protection of exits		Spenial Consti			
-	Fire check door	N/A	N/A	MR		
30	Pressurization	N/A	N/A	N/A		
	d. No. of continuous staircase to terrace	One	Provided	MR		
	e. Width of corridor	N/A	N/A	N/A		
	f. Door size	2 x 1.50m	Provided	MR		
3	Compartmentation.		Byn sawnes.			
2007	Fire check door.	N/A	N/A	N/A		
	Sealing of electrical shafts.	N/A	N/A	N/A		
	Fire rating of shaft door.	N/A	N/A	N/A		
	Water curtain	N/A	N/A	N/A		
	Fire dampers.	N/A	N/A	N/A		
4.	Smoke Management system.	0620	First Installation and I			
	Basement	N/A	N/A	N/A		
	Upper floors	12 ACPH	Natural ventilation	MR		
5.	Fire Extinguishers.		in A. I.			
174	Total numbers	Required	04 Nos.	MR		
	Types	ABC/CO2	ABC/Co2	MR		
	ISI Marking	ISI marked	Provided	MR		
6.	First Aid Hose Reels.			× E		
	Total numbers on each floor.	01 No	Provided	MR		
	Length of hose-reel hose.	30m	Provided	MR		
	Nozzle Diameter	5mm	Provided	MR		
7	Automatic Fire Detection and Alarming system.					
	Type of detectors	Required	Heat & Smoke	MR		
	Location of Main Panel	Required	3rd floor	MR		

	Location of Repeater Panel	N/A	N/A	N/A
State To	Alternate source of power	N/A	N/A	N/A
1 1	Hooter's location	N/A N/A	N/A	N/A
8.	MOEFA		Provided	MR
	Public Address System	Required	N/A	N/A
0.	Automatic Sprinkler System	N/A	177	
	Basement	37/4	Provided	N/A
	Upper floors	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
1.		N/A	NA	
1.	Internal Hydrants.	100 mm	Provided	MR
	Size of Riser/Down-comer	01 Nos	Provided	MR
	 Number of Hydrant per floor Hose box. 	01 Nos	Provided	MR
2.	Yard Hydrants.	UTIOS	Unit about the st	A.
-	Total number of hydrants.	N/A	N/A	N/A
num 3	2. Hose box.	N/A	N/A	N/A
2			marketing the color	
3.	Pumping arrangements.		1	
81/	Ground Level	2280 LPM	Provided	MR
SKR	Discharge of main pump.	50m	Provided	MR
6 M	➤ Head of main pump.	01 No	Provided	MR
-	Number of main pumps.	180 LPM	Provided	MR
	> Jockey Pump output.	50m	Provided	MR
Hites 8	> Jockey Pump head.	2280 LPM	Provided	MR
	Standby Pump output.	50m	Provided	MR
-	 Standby Pump head. Auto Starting / Manual Stopping. 	Required	Provided	MR
Allen 9	house	Required	Provided	MR
PRI TOA			Provided	MR
- out	Terrace Level Source	450 LPM	Provided	MR
	Discharge of pump.	40m	Provided	MR
-1.7	Head of pump.Power supply.	Required	Provided	MR
700	Auto starting of pump.	Required	Floridor (30 m)	(p
	Captive water storage for Fire Fighting.	40 mars and mars	Provided	MR
4.	t 1 tank capacity.	1,00,000 ltrs	Provided	MR
	Draw-off connection.	Required	Provided	MR
1	Fire Service Inlet.	Required	Provided	MR
	Access to tank.	Required	10,000 ltr	MR
	Overhead tank capacity.	10,000 ltr	Provided	MR
		Required	I TOYLOOG	
5.	Exit Signage.	37/4	N/A	N/A
6.	Provision of Lifts. Pressurization of lift shaft.	N/A	N/A	N/A
	n annigation of lift lobby.	N/A	N/A	N/A
9	Pressurization of Communication in lift car.	N/A	Provided	MR
0.00	• Communication in Fireman's switch.	Required	Provided	MR
	• Fireman s surre	Required	Provided	MR
	Lift signage. Person Supply Output Description:	Required	Fidvided	
7	Standby Power Supply		27/4	N/A
8.	Refuge Area	N/A	N/A	N/A
i Al	Total area	N/A	N/A	IN/A
	• Location	The state of the s	N/A	N/A
9.	Fire Control Room. Detector System Panel.	N/A	N/A N/A	N/A
	Detector System Flow Switch Panel.	N/A	N/A N/A	N/A
	PA system Panel.	N/A		N/A
	Dottery backup	N/A	N/A	
	Building floor plan	N/A	N/A	N/A

F



Special Fire Protection System for the N/A N/A N/A Protection of special Risk, if any: The fire protection system provided in the building were randomly checked and found functional at the time of inspection. Keeping in view of the deemed compliance of the minimum standard on fire prevention and safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/SZ/2022/EH/68 dated 14/03/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended. Accordingly, DFA is put up for approval and signature please. Signature of the Inspecting Officer Name: Sh. Rajesh Kumar Design: ADO (BCP) Director As exproved, F.t. retter in forth for your expression, Pl. retter in forth to your 1/16.