


C-66

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI**  
**HEAD QUARTERS, DELHI FIRE SERVICE, NEW DELHI - 110001**  
No.F6/DFS/MS/EH/NDZ/2025/324 Dated : 10.09.2025

**FIRE SAFETY CERTIFICATE**

Certified that the M/S BARUSH (A unit of Akshdeep Hospitality) located at C-38, First floor, Connaught place, New Delhi in a building is comprised of Ground + 02 upper floors and Restaurant running at first floor only, was earlier granted FSC by this department vide letter F6/DFS/MS/EH/NDZ/2022/244 dated 02/09/2022. Now, the premises was re-inspected by the officers concerned of this department on 27/08/2025 in the presence of Mr. Pramod, Manager and found that the said premises has deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010 and that the said premises is fit for occupancy class Assembly Building (Group D) for Restaurant at first floor only, with effect from 10.09.25 for period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules 2010, printed below.

Issued 10/09/2025 at New Delhi by.

  
( Virendra Singh )  
Chief Fire Officer

**Copy to:-**

1. The Chief Architect, NDMC, Palika Kendra, New Delhi. ID No. 2025082312786 dated 23.08.2025 & 2025081912621 dated 19.08.2025. to kindly ensure the occupancy and deviation in construction if any
2. The Manager, M/S BARUSH (A unit of Akshdeep Hospitality) C-38, First floor, Connaught Place, New Delhi.

**Conditions for the validity of Fire Safety Certificate**

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. The compliance with regards to electrical installation, structural stability, set back area, occupancy and any deviation in construction etc. shall be verified from authority concerned.
5. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
6. The means of escape shall be kept unobstructed / unlocked for unhindered evacuation in case of an emergency.
7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
8. Any flammable material for interior decoration is strictly prohibited.
9. This Fire Safety Certificate is valid for said restaurant at first floor only.



# INSPECTION REPORT

1. Name & address of the building: **M/S BARUSH** ( A Unit of Akashdeep hospitality) located at C-38, First floor, Connaught place, New Delhi. Gr+02 upper Floor.
2. Type of occupancy: -  
**Assembly Occupancy Group-D  
Restaurant at First floor only**
3. Type of case:-  
**Renewal**
4. Details of previous FSC:-  
**F6/DFS/MS/EH/NDZ/2022/244 dated 02/09/2022.**
5. Fire safety directives No.-  
**N/A**
6. Date of inspection:-  
**27/08/25**
7. Name of the inspecting officer:-  
**Sh. Ravinder Singh (ADO/CC)**
8. Name & designation of officer  
From the building side:-  
**Sh. Pramod ( Manager)**
9. Year of construction:-  
**1950( old heritage )**
10. Applicant's letter No:-  
**ID No. 2025082312786 dated 23.08.2025 &  
2025081912621 dated 19.08.2025  
Old case**

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirements as per previous FSC inspection	Provided at site	Remarks MR/NMR
<b>1.</b>	<b>Access to Building</b>			
	1) Road width	06	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
<b>2.</b>	<b>Number, Width Type &amp; Arrangement of Exits</b>			
	A. Number of staircases			
	1. Upper floors	02nos	Provided	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	1.25mtr & .75m	Provided	MR( old case )
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	2x1.5 mtr	Provided	MR
<b>3.</b>	<b>Compartmentation</b>			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
<b>4.</b>	<b>Smoke Management System</b>			
	1) Basements	N/A	N/A	N/A
	2) Upper floors	12 a/c per hour	Natural	MR
<b>5.</b>	<b>Fire Extinguishers</b>			
	1) Total numbers	02 Nos.	Provided	MR

2/20

	2) Types	ABC & CO2	ABC & CO2	MR
	3) ISI marking	Required	Provided	MR
6.	<b>First-Aid Hose Reel</b>			
	1) Total number	01	Provided	MR
	2) Length of hose reel hose	30 mtr.	Provided	MR
	3) Nozzle diameter	05 mm	Provided	MR
7.	<b>Automatic Fire Detection &amp; Alarming System</b>			
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	<b>MOEFA</b>	Required	Provided	MR
9.	<b>Public Address System</b>	N/A	N/A	N/A
10.	<b>Automatic Sprinkler System</b>			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	N/A	N/A	N/A
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	<b>Internal Hydrants</b>			
	1) Size of riser/down-comer	100mm	Provided	MR
	2) Number of hydrants per floor	01	Provided	MR
	3) Hose box	01	Provided	MR
12.	<b>Yard Hydrants</b>			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	<b>Pumping Arrangement common with hotel</b>			
	1) Ground level	N/A	N/A	N/A
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level			
	a) Discharge of pump	450 LPM	Provided	MR
	b) Head of pump	40 mtr.	Provided	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	<b>Captive Water Storage for Fire Fighting</b>			
	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A



2/21

	b) Fire service inlet	N/A	N/A	N/A
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	20,000 ltr.	Provided	MR
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply( inverter )	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A


The fire protection systems provided in the building were randomly tested, checked and found functional at the time of inspection.

In view of the deemed compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if agreed, we may renew the FSC issued vide letter no. F6/DFS/MS/EH/NDZ/2022/244 dated 02/09/2022, under rule 35 of the Delhi Fire Service rules 2010. Accordingly, **FSC is recommended for approval** & DFA is put up for kind perusal and signature please


Signature of the Inspecting Officer




Name: - Sh. Ravinder Singh  
Designation: - ADO (CC)

  
29/8/25  
Dy. C.F.O. (NDZ)  
C.F.O.

  
29/08/25

  
29/8/25  
Principal Director

  
02/09/25  
Dy. C.F.O.

  
ADO (CC)

  
Dy. C.F.O.