



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No: F6/DFS/MS/WZ/2026/ 128

Dated: 17/04/2026

To,

The Medical Superintendent,
Bhatia Global Hospital & Endosurgery Institute,
305-307-308, Ambica Vihar, Paschim Vihar
New Delhi - 110087

Sub: - Surprise inspection report in r/o M/s Bhatia Global Hospital & Endosurgery Institute,
located at 305-307-308, Ambica Vihar, Paschim Vihar, New Delhi - 110087.

Sir,

As per directions of the Competent Authority vide office order no. F6/DFS/HQ/2026/494 dated 20/03/2026, it is to inform you that the surprise inspection of above said Hospital building has been carried out by the officer concerned on 08.04.2026 to verify the compliance of the requisite fire safety measures installed in the building in the presence of Ms. Mamta (Quality Manager) was present at the time of inspection. During the visit of the following observation were noticed:-

1. Lift in basement is not segregated with fire check door.
2. Smoke management system in basement found removed at some places.
3. Detectors found removed at some places.
4. Pumping system not found in auto mode.

You are advised to rectify the above-mentioned shortcoming under intimation to this department, till than the occupancy of the Building/ Premise in absence of requisites fire safety arrangements shall be at the risk and liabilities of the Owner/ Occupier.

Yours Faithfully


S.K. Dua

Chief Fire Officer
Delhi Fire Service