

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI EADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

No.F.6/DFS/MS/EH/2025/SZ/166

Dated.al../25./2025

FIRE SAFETY CERTIFICATE

Certified that the Eating House in the Name & Style of M/s Bikanervala International located at Ground & First Floor, D-17 Defence Colony, New Delhi 110024 in the building comprised of Ground plus Two Upper Floor owned/occupied by M/s Bikanervala International was issued Fire Safety Certificate by this department vide letter no. F6/DFS/MS/EH/2022/SZ/173 dated 13/06/2022. The restaurant premise was re-inspected by the officer concerned of this department on 23/04/2025 in the presence of Mr. Kailash Panday and found that the premise have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy Class D "Assembly Building" (For Ground & First Floor only) and Validity upto 31/03/2028 in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Jule 38 of the Delhi Fire Service Rules, 2010.

Issued on <u>01/0.5</u>/2025 at New Delhi by

Delhi fire

Copy to: -

1. The Addl. Commissioner of Police, Lic/Branch 1st Floor PS Defence Colony New Delhi 110049 (Ref MCD Portal ID 2025040305392 dated 04/04/2025)

Conditions for the validity of Fire Safety Certificate: -

1. All the means of escape/entry/exit shall be kept free from any obstruction.

2. All the fire safety arrangement provided therein shall be maintained in good working condition at all time as seen during inspection. Any loss of life property due to non-functional fire safety measures shall be at the responsibility of the management.

3. All the staff members must know the correct method of operation of fire fighting

4. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on

5. This fire safety certificate may not in any way be treated as regularization (Clause UBBL-2016) of unauthorized construction or alteration (Clause 1.4.3 of

UBBL-2016), if any.

6. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six

A	
\mathbf{n}	10

	INSPECTIO	N REPORT	आजार्ट		
1	Name & Address of the Building	M/s Bikanerval	a International loc		
2	Type of Occupancy	Defence Colony, New Delhi 110024. Group—D Assembly Building. (Eating House)			
3	Building Comprised of				
4	Type of Case	Ground plus Two upper floors Renewal			
5	Details of Previous NOC				
6	Fire Safety Directives Letter No	F6/DFS/MS/EH/2022/SZ/173 dated 13/06/2022			
7	Date of Inspection	Nil 23/04/2025			
8	Name of the Inspecting Officers		* ADO (DCD)		
9	Name & Designation of Officers	Sh. Rajesh Kumar, ADO (BCP) Mr. Kailash Panday			
_	from the building side	Mr. Kallash Panday			
10	Year of construction	2007 Now R	estt. Running at GF &	FF only	
11	Applicant letter No.	MCD Portal No. 2025040305392 dated 04/04/202			
S. No.	Minimum standards on Fire Prevention	UBBL/ NBC- 2016	Provided at Site	Remark MR/NM	
1	and Fire Safety U/R 33	2010		IVIIVIAIVI	
1	Access to Building.	6 m	Provided	MR	
	Road width		N/A	N/A	
	Gate width	N/A N/A	N/A	N/A	
2	Width of internal road		IV/A	IN/A	
	Number, width, type & arrangement of ex	10.			
	a) Number of Staircase				
	Upper floors.	02 Nos	02 Nos	MR	
	Basement floor.	N/A	NA	N/A	
	b) Width of Staircase				
	> Upper floors	1.50 mtr each	1.50 mtr & 2 mtr	MR	
	> Basement floor	N/A	N/A	N/A	
	c) Protection of exits	27/4	27/4	27/4	
	Fire check door Pressurization	N/A N/A	N/A N/A	N/A	
	d) No. of continuous staircase to terrace	-	Provided	N/A	
	e) Width of corridor	Required N/A	N/A	MR N/A	
	1) Door size	1.50 mtr each	1.50 & 1.50 mtr		
3	Compartmentation.	1.50 mil cach	1.50 & 1.50 mtr	MR	
	• Fire check door.	Required	Provided	MR	
	Sealing of electrical shafts. Figure 1 and	Required	Provided	MR	
	Fire rating of shaft door.Water curtain	Required N/A	Provided	MR	
	• Fire dampers.	N/A N/A	N/A	N/A	
4	Smoke Management system.	N/A	N/A	N/A	
	Basement	NA	N/A	N/A	
	Upper floors	NA	N/A	N/A	
5	Fire Extinguishers.				
	Total numbers	06 Nos	06 Nos	MR	
	• Types	ABC/CO ₂	ABC-04 & CO ₂ -		
	ISI Marking	ISI marked	02	MR	
6	First Aid Hose Reels.	131 HISIKEO	Provided	MR	
	Total numbers on each floor.	One	D		
	 Length of hose-reel hose. 	30m	Provided Provided	MR	
	Nozzle Diameter	5mm	Provided	MR	
			riovided	MR	

\ \ \





7	Automatic fire detection & alarming system		आज़ादी अमृत	
	Type of detectors			
	Location of Main Panel	N/A	Smoke type	N/A
	 Location of Repeater Panel 	N/A	Ground floor	N/A
	• Alternate source of power	N/A	N/A	N/A
	Hooter's location	N/A	Provided	N/A
8	MOEFA	N/A	Provided	N/A
9	Public Address System	Required	Provided	MR
10	Automatic Sprinkler System	N/A	N/A	N/A
	Basement			
	Ground/ upper floors.	N/A	N/A	N/A
	Sprinkler above false ceiling	N/A	N/A	N/A
11	Internal Hydrants.	N/A	N/A	N/A
	Size of Riser/Down-comer	100		
	Number of Hydrant per floor	100 mm	Provided	MR
	Hose box.	One	Provided	MR
12	Yard Hydrants.	One	Provided	MR
	Total number of hydrants.Hose box.	N/A	N/A	N/A
13	Pumping arrangements.	N/A	N/A	N/A
	Ground Level			
	Discharge of main pump.Head of main pump.	N/A	N/A	N/A
	Number of main pumps.	N/A	N/A	N/A
	> Jockey Pump output.	N/A	N/A	N/A
	Jockey Pump head.	N/A	N/A	N/A
	Standby Pump output.	N/A	N/A	N/A
	Standby Pump head.	N/A	N/A	N/A
	Auto Starting/Manual Stopping.	N/A	N/A	N/A
	Pump house access.	N/A	N/A	N/A
		N/A	N/A	N/A
	Terrace Level		•	
	Discharge of pump.	900 LPM	Provided	MR
	Head of pump.	40m	Provided	MR
	Power supply.	Required	Provided	MR
	Auto starting of pump.	Required	Provided	
14	Captive water storage for fire fighting.		1001404	MR
	Underground tank capacity.	N/A	N/A	1
	Draw-off connection.	N/A		N/A
	Fire Service Inlet.	N/A	N/A	N/A
	Access to tank.	N/A	N/A	N/A
	 Overhead tank capacity. 		N/A	N/A
15	Exit Signage.	20,000 Ltrs	Provided	MR
	Provision of Lifts.	Required	Provided	MR
	 Pressurization of lift shaft. Pressurization of lift lobby. 	N/A	N/A	N/A
	Communication in lift car.	N/A	N/A	
	• Fireman's switch.	N/A	N/A	N/A
	• Lift signage.	N/A	N/A	N/A
7 5	Standby Power Supply	N/A	N/A	N/A
		Required	Provided	N/A
0 1	Refuge Area		riovided	MR
	Total area	27/		
		N/A	N/A	

1000	r	112	आज़ादीका अमृत महोत्सर	
		N/A	N/A	N/A
	Location	IN/A		
19	Fire Control Room.	27/4	N/A	N/A
	Detector system panel.	N/A	N/A	N/A
	Flow switch panel.	N/A	N/A	N/A
	PA system panel.	N/A	N/A	N/A
	Battery backup.	N/A	N/A	N/A
	Battery backup. Battery backup. Battery backup. Battery backup.	N/A	13/22	
	Building floor plan. Building floor plan. Building floor plan. Building floor plan. Building floor plan.	N/A	N/A	N/A
20	Special Fire Protection System for the Protection of special Risk, if any.		becked at randon	

The Fire protection systems provided in the building were test checked at random and found

Keeping in view of the deemed compliance of the minimum standard on fire prevention and fire safety measures as required under the rules, the FSC issued vide letter no F6/DFS/MS/EH/2022/SZ/173 dated 13/06/2022, renewal under rule 37 of the Delhi Fire Service rules, 2010 is recommended.

Accordingly, DFA is put up for approval and signature please.

Signature of the Inspecting Officer Name: Sh. Rajesh Kumar

Designation: ADO (BCP)

Directa

Approved. C-1. Fetter is future for Signature 01