

## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/EH/2025/ 99

Dated: 19/03/2025

## **FIRE SAFETY CERTIFICATE**

Certified that the M/s Bite Bikaner located at C-1/1, First floor, Janakpuri, New Delhi110058 in the building comprised of ground, & 03 upper floors owned/occupied by M/s Bite
Bikaner was issued fire safety certificate vide letter no. F6/DFS/MS/EH/2022/SZ/49 dated
23.02.2022. The premises was inspected by the officer concerned of this department on
07.03.2025 in the presence of Sh. Rajesh Kumar (Owner) and found that the said premises have
complied with the fire prevention and fire safety requirements in accordance with Rules 33 of
the Delhi Fire Service Rules, 2010 and building premises is fit for occupancy class "Group D
Assembly" (Restaurant) at first floor only with effect from 1903 202 for a period of
Valid up to 31.03.2027 in accordance with rule 36 unless renewed under rule 37 or sooner
cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi
Fire Service Rules, 2010.

Issued on ...1.9. 0.3. 2025 at New Delhi by

Atul Garg)
Director
Ph-011-23414000

Copy to:-

- 1. The Commissioner, North, MCD, Civic Centre, New Delhi, to ensure the occupancy as detailed above deviation and if any.
- The Addl. Commissioner of Police Lic/Branch, 1st Floor PS Defence Colony, New Delhi 110049, Online ID No- 2025021101720 dated 01.03.2025
   M/s Bite Bikaner located at C-1/1, First floor, Janakpuri, New Delhi-110058.

Conditions for the validity of Fire Safety Certificate:

 This Fire Safety Certificate is valid only for restaurant at first floor for assembly occupancy only. In case of any violation, this FSC will be treated as null & void.

2. All the means of escape/entry/exit shall be kept free from any obstruction.

- 3. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
- 4. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.

5. All the staff members must know the correct method of operation of firefighting system.

6. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="http://delhi.gov.in./wps/wcm/connect/doit">http://delhi.gov.in./wps/wcm/connect/doit</a> fire/FIRE/Home/Forms.

7. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.

8. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the MHA portal along with a copy of this Certificate, six months prior to its expiry".

## INSPECTION REPORT

1. Name & address of the building

: M/s Bite Bikaner at C-1/1, First floor, Janakpuri, New Delhi-110058.

2. Type of Occupancy

: Assembly (Restaurant)

3. Composition of building

: Ground & 03 upper floors but restaurant running at first floor only,

4. Type of Case

: Renewal

5. Details of previous NOC

: F6/DFS/MS/EH/2022/SZ/49 dated 23.02.2022

6. Fire Safety directives letter No

: Nil

7. Date of inspection

: 07.03.2025

8. Name of the Inspecting Officers

: ADO (RN)

9. Name and designation of officers

from the building side

: Sh. Rajesh Kumar (Owner)

	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per Rules 35 (6)	Provided at site	Remarks MR/NMR				
	Access to building							
	Road width	6m	06m	MR				
	Gate width	NA	NA	NA				
	Width of internal road	NA	NA	NA				
2	Number, Width, Type & Arrangement of Exits							
	a. Number of staircases							
	Upper Floors	02	02	MR				
	Basements	NA	NA	NA				
	b. Width of staircases		er an annual	2.65.5				
	Upper Floors	1.5m each	Provided	MR				
	Basements	NA	NA	NA				
	c. Protection of exits							
	Fire check door	NA	ŇΑ	NA				
	Pressurization	NA	NA	NA				
	d. No. of continuous staircases to terrace	Required	Provided	MR				
	e. Width of Corridor	NA	NA	NA				
	f. Door Size	1.50m each	Provided	MR				
	Compartmentation.							
	Fire check door	NA	NA	NA				
	Sealing of electrical shafts	Required	Provided	MR				
	Fire Rating of shaft door	NA	NA	NA				
	Water Curtain	NA	NA	NA				
	Fire Dampers	NA	NA	NA				
	Smoke Management System.	I INT						
	Basements	NA	NA	NA				
	Upper floors	Required	Provided	MR				
+	Fire Extinguishers		238230					
1	Total numbers	04nos	06nos	MR				
	Types	ABC & Co2	ABC & CO2	MR				
	ISI marking	Yes	Yes	MR				

	<ul> <li>Total numbers on each floor</li> </ul>	MIT	Provided	MR
	I enoth act	01	Provided	MR
	<ul> <li>Length of hose reel hose</li> <li>Nozzle diameter</li> </ul>	30m	30m	MR
7				
	Automatic fire detection and alarming system	1. 7		NA
	Type of detectors	NA	NA NA	NA
	Location of Main Panel	NA		NA
	Location of Repeater Panel	NA	NA NA	NA
	Alternate source of power	NA		NA
	Hooters' Location	NA	NA	MR
8	MOEFA	Required	Provided	NA
9	Public Address System.	NA	NA	Topas -
10	Automatic Sprinkler System.		214	NA
	Basement	NA	NA	NA
	Upper Floor	NA	Provided	
	Sprinkler above false ceiling	NA	NA	NA
11	Internal Hydrants			MR
11	Size of riser/down-comer	100mm	Provided	MR
	Number of hydrants per floor	01	Provided	MR
	Hose Box	01	Provided	
12	Yard Hydrants.	( m -	NA	NA
	Total number of hydrants	NA		NA
	Hose Box	NA	NA	1.35.3
13	13 Pumping Arrangements.			
	Ground Level		N/A	N/A
	➤ Discharge of main Pump	N/A		N/A
	➤ Head of Main pump	N/A	N/A	NA
	> Number of main pumps	NA	NA NA	NA NA
	> Jockey Pump out put	NA	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	> Standby Pump out put	N/A		
	> Standby Pump Head	N/A	N/A	N/A
	<ul> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N/A	N/A	N/A
	Terrace level	450lpm	Provided	MR
	➤ Discharge of pump	300 100	Provided	MR
	➤ Head of the pump	40m		* 5.50
	> Power Supply	Required	Provided	MR MR
	➤ Auto Starting of pump	Required	Provided	IVIK
14	Captive Water Storage for fire fighting.			
	Underground tank capacity,	NA	NA	NA
	> Draw-off connection	NA .	NA	NA
	> Fire service inlet	NA	NA	NA
	➤ Access to tank	NA	NA	NA
	Overhead Tank capacity	20,000 LTR	Provided	MF
15	Exit Signage.	Required	Provided	MI
16	6 Provision of Lifts.			
		-		
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/Ą	N/A	N/A

	T CITOLIN	N/A	N/A	N/A		
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> </ul>	NA NA	NA	NA		
		NA	NA	NA		
	Lift Signage	NA	NA	NA		
17	Standby power supply	NA	NA	NA		
18	Refuge Area					
	> Total Area	N/A	N/A	N/A		
	> Location	N/A	N/A	N/A		
19	Fire Control Room					
	Detector System Panel     Flow Switch Panel	N/A	N/A	N/A		
		N/A	N/A	N/A		
	PA System Panel	N/A	N/A	N/A		
	Batter backup     Building Floor Plans	N/A	N/A	N/A		
		N/A	N/A	N/A		
20	Special Fire Protection Systems for	NA	NA	NA		
20	Protection of special Risks, if any:					

The fire protection systems provided in the building were tested/ checked and found in working condition at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules. It is recommended to renew Fire Safety vide this department letter of even no. F6/DFS/MS/EH/2022/SZ/49 dated 23.02.2022, Certificate under rule 37(3) of Delhi Fire Service Rules 2010.

Do (ED)

Signature of the Inspecting Officer
Name :-C.L. Meena
Designation:- ADO/RN

ग्रिभ

1) 3 20 1

Dineta

Moder

As approved F.T. Letter is hur for your signature fl.

Director (Pir)

17/03/20 4T

19/03/25 B

[