


C-17



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI- 110001



No. F6/DFS/MS/2025/Indl./443

Dated: 08/09/2025

To

Sh. Gaurav Dutta
 Plot No. 46 at SSI, Indl. Area,
 G.T. Karnal Road, Delhi-110033.

Sub: Regarding issuance of Fire Safety Certificate in r/o Biotic Waste Solution located at Plot No. 46, SSI, Industrial Area, G.T. Karnal Road Delhi-110033.

Sir,

Please refer to your letter no. nil dated 08/07/2025 received in this department vide outdoor diary no. 4684 dated 08/08/2025 on the subject cited above. In this connection this is to inform you that the above mentioned site was jointly visited by the officers concerned of this department on 22/08/2025 to verify the fire safety arrangements installed in the building as per issued fire safety recommendations vide letter of even no. F6/DFS/MS/BP/2006/1483 dated 05.07.2006 at the time of inspection Mr. Abhishek (Manager) was also present at site. During the course of the inspection it is observed that the building is comprised of Ground floor only. Your request for FSC is rejected under Rule 37 (3) due to following shortcomings.

1. Sanctioned building plan is not matching with the existing building.
2. The main entrance gate width of 3.80m is provided against the requirement of 06m.
3. Only one exit doors is provided width of 01m against the requirement of 02 nos. of 1.25m each.

Keeping in view of above, issuance of Fire Safety Certificate cannot be considered at this stage & rejected. You are requested to rectify the above mentioned shortcomings under intimation to this department; till such time running of industry is at your own risk & responsibility.

Yours faithfully

[Signature]
 06/09/2025

Virendra Singh
 Chief Fire Officer
 Delhi Fire Service

Copy to:-

1. The Dy. Commissioner of Factory licensing, SDMC 3rd, Floor, Civic Centre Minto Road, Delhi-110002.