



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

c 32



No. F6/DFS/MS/2025/School/ 1260

Dated: 17/10/2025

FIRE SAFETY CERTIFICATE

Certified that the B. R. Tyagi Sr. Sec. School located at Budh Vihar, Phase-II, Sector-24, Rohini, Delhi-110086 comprised of Ground & 03 upper floors owned/ occupied by B.R. Tyagi Sr. Sec. School was issued Fire Safety Certificated vide this office letter no. F6/DFS/MS/2022/WZ/School/510 dated 12/05/2022. The premise was inspected by the officer concerned of this department on 03/10/2025 in the presence of Sh. B. Lakshmanan (Manager) and observed that all the fire prevention and fire safety arrangements as provided in the premise found in good working condition and there is no additional construction. The premise have therefore deemed complied with the requirements under rule 33 of the Delhi Fire Service Rules, 2010 and the building premise is fit for occupancy under "Group B Educational (School)" with effect from ...17.10.2025.. for a period of three years in accordance with the rule 36 unless renewed under rule 37 or sooner cancelled under rule 40, subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010,

Issued on ...17.10.2025... at New Delhi by.

(S.K. Dua)

Dy. Chief Fire Officer
Delhi Fire Service

Copy to :-

1. The Dy. Director of Education, Zone- XIII, District North West- B (II), Sector-9, Rohini, Delhi - 110085.
2. The Manager, B. R. Tyagi Sr. Sec. School located at Budh Vihar, Phase-II, Sector-24, Rohini, Delhi-110086.

Conditions for the validity of Fire Safety Certificate:

1. All the means of escape/entry/exit shall be kept free from any obstruction.
2. All the fire safety arrangements provided therein shall be maintained in good working condition at all time as seen during inspection.
3. Any loss of life or property due to non-functional fire safety measures shall be at the responsibility of the management.
4. All the staff members must know the correct method of operation of firefighting system.
5. The owner / occupier shall submit a declaration every year in Form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <http://delhi.gov.in/wps/wcm/connect/doi/fire/FIRE/Home/Forms>.
6. This fire safety certificate may not in any way be treated as regularization (Clause 2.8 of UBBL-2016) of unauthorized construction or Alteration (Clause 1.4.3 of UBBL-2016), if any.
7. "The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".

INSPECTION REPORT

1. Name & address of the building : B.R. Tyagi Sr. Sec. School at Budh Vihar, Ph-II, Sec-24, Rohini, Delhi-86.
2. Type of Occupancy : Educational
3. Composition of building : Ground & 03 upper floors
4. Type of Case : Renewal
5. Details of previous NOC : F6/DFS/MS/2022/WZ/School/510 dated 12/05/2022
6. Fire Safety directives letter No : Nil
7. Date of inspection : 03/10/2025
8. Name of the Inspecting Officers : ADO (Rohini)
9. Name and designation of officers from the building side : Sh. B. Lakshmanan (Manager)
10. Year of Construction : 2004 (As Per NDMC Letter dated 06/09/2018)
11. Applicant's letter No. : Letter No. Nil & DFS Dairy No.6215 dated 19/09/2025

S.No	Minimum Standards on fire prevention and fire safety U/R 33	Requirements as per Rules 35 (6)	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	Provided	MR
	• Gate width	Directly Accessible	Directly Accessible	MR
	• Width of internal road	NA	NA	NA
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	02	02	MR
	• Basements	NA	NA	NA
	b. Width of staircases			
	• Upper Floors	1.50m	1.30 & 1.33m	MR
	• Basements	NA	NA	NA
	c. Protection of exits			
	• Fire check door	NA	NA	NA
	• Pressurization	NA	NA	NA
	d. No. of continuous staircases to terrace	NA	NA	NA
	e. Width of Corridor	NA	NA	NA
	f. Door Size	01m	01m	MR
3	Compartmentation.			
	• Fire check door	NA	NA	NA
	• Sealing of electrical shafts	NA	NA	NA
	• Fire Rating of shaft door	NA	NA	NA
	• Water Curtain	NA	NA	NA
	• Fire Dampers	NA	NA	NA
4	Smoke Management System.			
	• Basements	NA	NA	NA
	• Upper floors	Required	Natural Ventilated	MR
5	Fire Extinguishers			
	• Total numbers	09nos	12nos	MR
	• Types	ABC/Co2	ABC--12	MR
	• ISI marking	ISI Marked	Yes	MR

6 *

6	First-Aid Hose Reels.			
	• Total numbers on each floor • Length of hose reel hose • Nozzle diameter	01	01	MR
		30m	30m	MR
		5mm	5mm	MR
7	Automatic fire detection and alarming system.			
	• Type of detectors • Location of Main Panel • Location of Repeater Panel • Alternate source of power • Hooters' Location	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
		NA	NA	NA
8	MOEFA	NA	NA	NA
9	Public Address System.	NA	NA	NA
10	Automatic Sprinkler System.			
	• Basement • Upper Floor • Sprinkler above false ceiling	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
11	Internal Hydrants			
	• Size of riser/down-comer • Number of hydrants per floor • Hose Box	NA	NA	NA
		NA	NA	NA
		NA	NA	NA
12	Yard Hydrants.			
	• Total number of hydrants • Hose Box	NA	NA	NA
		NA	NA	NA
13	Pumping Arrangements.			
	• Ground Level ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump	N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		N/A	N/A	N/A
		450 LPM	450 LPM	MR
		40m	40m	MR
		NA	NA	NA
		NA	NA	NA
		14	Captive Water Storage for fire fighting.	
• Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity	NA		NA	NA
	NA		NA	NA
	NA		NA	NA
	NA		NA	NA
	10,000 LTR		Provided	MR

15	Exit Signage	Required	Provided	MR
16	Provision of Lifts.			
	• Pressurization of Lift Shaft	N/A	N/A	N/A
	• Pressurization of Lift lobby	N/A	N/A	N/A
	• Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	• Lift Signage	N/A	N/A	N/A
17	Standby power supply	N/A	N/A	N/A
18	Refuge Area.			
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			
	• Detector System Panel	N/A	N/A	N/A
	• Flow Switch Panel	N/A	N/A	N/A
	• PA System Panel	N/A	N/A	N/A
	• Batter backup	N/A	N/A	N/A
	• Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	N/A	N/A	N/A

The fire protection systems provided in the building were tested/ checked randomly and found in good working condition, at the time of inspection.

Keeping in view the satisfactory compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, it is recommended for renewal of fire safety certificate issued vide this department letter of even no. F6/DFS/MS/2022/WZ/School/510 dated 12/05/2022.

Signature of the Inspecting Officer
Name :- C.L. Meena
Designation :- ADO (Rohini)

DO/WZ
DFA Done.
Approved
09/10/2025
Dy CFA (WZ)
10/10/25

Principal Director

Dy CFA to Sessone.

Dy. CFA (WZ) F.T. Pl.
14/10/25

ADO (Rohini)