

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELIII HEADQUARTERS: DELIII FIRE SERVICE: NEW DELIII- 110001

आज़ादी मा अमृत महोत्सव

No. F6/DFS/MS/School/NDZ/2025/911

Dated: 05/03/2025

FIRE SAFETY CERTIFICATE

Certified that B.S. Memorial Public School located at B-6, Rajbir Colony, Village Gharoli, Delhi-110096, building comprised of Ground plus Two upper floor only, owned/ occupied by B.S. Memorial Public School was issued Fire Safety Certificate by this department vide letter No. F6/MS/DFS/06/2553 dated 15/09/2006. The school building was re-inspected by the officer concerned of this department on 25/02/2025 in presence of Mr. Virender (Manager) of the school and found that the school building have deemed complied with the fire prevention and fire safety requirements in accordance with Circular No. 262 - 362 dated 17/01/2005 and the school is fit for occupancy class "Educational Building" (Group - B) for ground plus one upper floor only with effect from _05/03/2025 for a period of three years in accordance with rule 36 unless renewal under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the DFS Rules, 2010. Subject to conditions, printed below.

Issued on 05/03/2025 at New Delhi by.

(AZUL GARG)
DIRECTOR
DELHI FIRE SERVICE

Copy to: -

- 1. The Director of Education, 15th floor, Civic Centre, New Delhi-110001.
- 2. The Principal, B.S Memorial Public School located at B-6, Rajbir Colony, Village Gharoli, Delhi-110096.

Conditions for the validity of Fire Safety Certificate

- 1. The owner /occupier shall apply for renewal of this fire safety certificate to the Director in form J' [sub rule (1) of rule 37] along with a copy of this certificate, six months prior to its expiry
- 2. All the means of escape shall be kept free of all the type of obstruction all the time.
- 3. All the employees shall be acquainted with the use and maintenance of all fire equipment's and method of smooth and speedy safe evacuation of occupants in case of emergency.
- 4. All the firefighting equipment's shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 5. At the time of inspection second floor is being used for resident purpose only.
- 6. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc. may be got verified from the authorities concerned.
- 7. This Fire Safety Certificate cannot be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
- 8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

	No2 INSPECTION REPORT							
			INSPEC		O) SKRINGRIN			
1	Nan	ne &	address of the building	B.S Memorial Public School located at B-6, Rajveer Colony, Village Gharoli, Delhi-110096.				
2	Bui	ldin	is comprised of Ground plus two upper floors only. (School running at Ground Plus one upper floor only)					
3	Type of occupancy Educational Building					(F)		
4	Typ	Type of case Renewal						
5	Det	ails	ils of previous FSC F6/MS/DFS/06/2553 dated 15/09/2006.					
6	Fire	saf	ety directives letter no.	Circular No. 262 - 362 dated 17/01/2005				
7	Dat	e of	inspection	25/02/2025				
8	Nar	Name of the inspecting officers Yashwant Singh Meena, ADO / Laxmi Nagar						
9	Name of the designation of officer from the building side			Mr. Virendra (Manager)				
10 Year of construction 2006					salabari 6"			
11	Ap	plic	ant's letter no.	Outdoor Diary N	No12689 dated 19/0	2/2025		
S. No	pr		nimum standard of fire ation and fire safety U/R 33	Circular Requirement	Provided at site	Remarks MR/NMR		
1.	Ac	cess	to Building:	Shirt	A RESIDENCE OF THE REAL PROPERTY.	HE FEEL A		
- 1	A	R	oad width	6.0 mtrs.	6.0 mtrs.	MR		
	В	G	ate width	N/A	N/A	N/A		
	C		idth of internal road	N/A	N/A	N/A		
2.	Nu		er, Width, Type and Arrang	272.000.000.000.000.000.000.000.000.000.	1071	IVA		
	A		umber of staircases	A PARTY	SCHOOL STREET	EL 1		
			Upper floor	01 no.	01			
		a	Opper floor	or no.	01 nos.	MR		
					123 (6) 100 (10)			
		b	Basement	N/A	N/A	(Old Case)		
	В		Basement Vidth of staircases	N/A	N/A	(Old Case)		
	В			N/A 1.20 mtrs	N/A 1.20 mtrs	(Old Case) N/A MR		
	A1 21	a b	Vidth of staircases Upper floor Basement	KSO IN SEC	adipoint to a se	(Old Case) N/A MR		
	В	a b P	Vidth of staircases Upper floor Basement rotection of exits	1.20 mtrs - N/A	1.20 mtrs N/A	(Old Case) N/A MR (Old Case) N/A		
	A1 21	a b P a	Vidth of staircases Upper floor Basement rotection of exits Fire check door	1.20 mtrs N/A	1.20 mtrs N/A N/A	(Old Case) N/A MR (Old Case) N/A N/A		
	A1 21	b P a b N	Vidth of staircases Upper floor Basement rotection of exits	1.20 mtrs - N/A	1.20 mtrs N/A	(Old Case) N/A MR (Old Case) N/A		
	C	b P a b N to	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases	1.20 mtrs N/A N/A N/A	1.20 mtrs N/A N/A N/A	(Old Case) N/A MR (Old Case) N/A N/A N/A		
	C	b P a b N to	Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace	1.20 mtrs N/A N/A N/A 01 no.	1.20 mtrs N/A N/A N/A 01 no.	(Old Case) N/A MR (Old Case) N/A N/A N/A N/A N/A N/A		
3.	C D E F	b P a b N to	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace Vidth of corridor	1.20 mtrs N/A N/A N/A 01 no. N/A	1.20 mtrs N/A N/A N/A 01 no.	(Old Case) N/A MR (Old Case) N/A N/A N/A MR		
3.	C D E F	b P a b N to V	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace Vidth of corridor	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	MR (Old Case) N/A MR (Old Case) N/A N/A N/A N/A MR N/A MR		
3.	C D E F C C	b P a b N to C D D mp	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases oterrace Vidth of corridor Poor size artmentation:	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	MR (Old Case) N/A MR (Old Case) N/A N/A N/A N/A MR N/A		
3.	C D E F C A B	b P a b N to V V D D mp	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace Vidth of corridor Poor size artmentation: ire check door ealing of electrical shafts	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	MR (Old Case) N/A MR (Old Case) N/A N/A N/A MR N/A N/A N/A N/A N/A N/A		
3.	C D E F C C A	b P a b N to V D D F F S F	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace Vidth of corridor coor size artmentation: ire check door	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr.	MR (Old Case) N/A MR (Old Case) N/A N/A N/A MR N/A N/A N/A N/A N/A N/A N/A		
3.	C D E F C A B C	b P a b N to C D D mp F S S F V	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases oterrace Vidth of corridor oor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr. NA N/A N/A N/A	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr. NA N/A N/A	MR (Old Case) N/A MR (Old Case) N/A N/A N/A N/A MR N/A N/A N/A N/A N/A N/A N/A N/		
3.	C D E F C A B C D E	b P a b N to V V C C S F V V F	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases terrace Vidth of corridor Poor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door Vater curtain	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr. NA N/A N/A N/A N/A	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr. NA N/A N/A N/A N/A N/A	MR (Old Case) N/A MR (Old Case) N/A N/A N/A MR N/A N/A N/A N/A N/A N/A N/A		
	C D E F C A B C D E	b P a b N to V V C S S F V V F F mok	Vidth of staircases Upper floor Basement rotection of exits Fire check door Pressurization o. of continuous staircases oterrace Vidth of corridor Poor size artmentation: ire check door ealing of electrical shafts ire rating of shaft door Vater curtain ire dampers	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr. NA N/A N/A N/A N/A	1.20 mtrs N/A N/A N/A 01 no. N/A 1.0 mtr. NA N/A N/A N/A N/A N/A	MR (Old Case) N/A MR (Old Case) N/A N/A N/A N/A MR N/A N/A N/A N/A N/A N/A N/A N/		

A W

B.S Memorial Public School located at B-6, Rajveer Colony, Village Gnaroll, Deini-110096

5.	Fire Extinguisher:		00 200	10 nos.	MR			
	A	Total numbers	08 nos.	CO ₂ & ABC	MR			
	В	Types	CO ₂ & ABC	ISI Marked	MR			
	C	ISI marking	ISI Marked	151 Markeu	IVIK			
6	First-Aid-Hose Reel:							
70	A	Total numbers of each floor	N/A	N/A	N/A			
	В	Length of hose reel hose	N/A	N/A	. N/A			
	C	Nozzle diameter	N/A	N/A	N/A			
7	Automatic Fire Detection and Alarming System:							
A. Am	A	Type of detectors	N/A	N/A	N/A			
	B	Location of main panel	N/A	N/A	N/A			
	C	Location of repeater panel	N/A	N/A	N/A			
	D	Alternate source of power	N/A	N/A	N/A			
	E	Hooters	N/A	N/A	N/A			
8	2550	OEFA:	N/A	Provided	MR			
9	1.000	742-74 (A. 170)		Provided	MR			
10	A	blic Address System:	N/A	Frovided	IVIIC			
10	A	tomatic Sprinkler System: Basement	Guerra I	NT/A	N/A			
	35.75	- Action of the Control of the Contr	N/A	N/A				
	В	Upper floor	N/A	N/A	N/A			
	C	Sprinkler above false ceiling	N/A	N/A	N/A			
11								
	A	Size of riser/down-comer	N/A	N/A	N/A			
	В	Number of hydrants per floor	N/A	N/A	N/A			
	C	Hose box	N/A	N/A	N/A			
12	Ya	Yard Hydrants:						
	A	Total number of hydrants	N/A	N/A	N/A			
	В	Hose box	N/A	N/A	N/A			
13	Pumping Arrangements:							
1	Ground level							
	A	Discharge of main pump	N/A	N/A	N/A			
	В	Head of main pump	N/A	N/A	N/A			
	C	Number of main pumps	- N/A	N/A	N/A			
	D	Jockey pump out put	N/A	N/A	N/A			
	E	Jockey pump head	N/A	N/A	N/A			
	F	Standby pump out put	N/A	N/A	N/A			
		Standby pump head	N/A	N/A	N/A			
	G H	Auto starting /manual	N/A	N/A	N/A			
	п	stopping		NI/A	N/A			
	I	Pump house access	N/A	N/A	I IN/A			
		race Level	77/4	N/A	N/A			
-	A	Discharge of pump	N/A		N/A			
	19100	Head of the pump	N/A	N/A N/A	N/A			
-	B	Power supply	N/A	N/A	N/A			
	C D	Auto starting of pump	N/A	IN/A	147			

B.S Memorial Public School located at B-6, Rajveer Colony, Village Gharoli, Delhi-110096

14							
	A	Underground tank capacity	N/A	N/A	N/A		
	B	Draw-off connection	N/A	. N/A	N/A		
	C	Fire service inlet	N/A	N/A	N/A		
	D	Access to tank	N/A	N/A	N/A		
		Overhead tank capacity	N/A	1,000 litr.	MR		
15	Ex	it Signage:	Required	Provided	MR		
16	Pro	ovision of Lifts:	y old style				
	A	Pressurization of lift shaft	N/A	N/A	N/A		
	B	Pressurization of lift lobby	N/A	N/A	N/A		
	C	Communication in lift car	N/A	N/A	N/A		
	D	Firemen's grounding switch	N/A	N/A	N/A		
7375 VI	E	Lift signage	N/A	N/A	N/A		
17	Standby Power Supply:		N/A	N/A	N/A		
18	Refuge Area:						
	A	Total area	N/A	N/A	N/A		
	B	Location	N/A	N/A			
19	Fire Control Room:						
	A	Detector system panel	N/A	N/A	N/A		
	B	Flow switch panel	N/A	N/A	N/A		
	C	PA system panel	N/A	N/A	N/A		
	D	Battery backup	N/A	N/A	N/A		
20	E	Building floor plans	N/A	N/A	N/A N/A		
20	Spe pro	ecial Fire Protection systems for otection of special Risks, if any:	N/A	N/A	N/A		

The fire protection system was randomly checked and tested and was found functional at the time of inspection.

Keeping in view of the deemed compliance of minimum standards on fire prevention and fire safety measures as required under the Rules the Fire Safety Certificate issued vide letter no. F6/MS/DFS/06/2553 dated 15/09/2006, Renewal under rule 35(6) of the Delhi Fire Rules 2010 is recommended.

No file is pending with me before disposal of this case.

Signature of the Inspecting Officer
Name Yashwant Singh Meena
Designation ADO (L.N)

DY. CHO (NXZ)

28/02

Di neeter 19/1

ANDA

D.T.O