## **HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE** NEW DELHI-110 001.

No. F.6/DFS/MS/School/2025/SZ/ 18

Dated: 21/05/2025

## **FIRE SAFETY CERTIFICATE**

Certified that the Building No. 118/1/2 (0-12) & 119/2 (1-16)located at Masudabad Village, Najafgarh, New Delhi- 110043, running at ground floor only, owned/occupied by Satkarya Home Hostess Skill Training School. The school building was inspected by the officer concerned of this department on dated 13.05.2025 in the presence of Mr. H.S. Sodhi (Architect), and found that the school building have complied with fire prevention and fire safety requirements in accordance with the Rules 33 of the Delhi Fire Service Rules 2010, and that the building/ premises (ground floor only) is fit for occupancy class B "Educational Building" with effect from 2105/2025 for a period of threeyears in accordance with the Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010, printed below.

Issued on 21/05 at New Delhi.

Delhi Fire Service

Copy to:-

1. Vijay Kumar Kapoor, Satkarya Home Hostess Skill Training School located at Building No. 118/1/2 (0-12) & 119/2 (1-16), Masudabad Village, Najafgarh, New Delhi- 110043.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi - 110054.

## Conditions for validity of fire safety certificate: -

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. The means of escape shall be kept unlocked and unobstructed for unhindered evacuation of occupants in case of emergency.
- 3. Any loss of life or property due to non-functional fire safety measures shall be at the risk and responsibility of the management.
- 4. The trained staff should be available round the clock.
- 5. Any deviations w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 6. The certificate may not be treated in any case for the regularization of the unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in the form 'K' provided in the first schedule of Delhi Fire Servicep Rules 2010, form is available on www.dfs.delhigovt.nic.in.
- 8. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in the Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry.

## INSPECTION REPORT

1. Name & address of the building :

Satkarya Home Hostess Skill Traning School at Building No. 118/1/2 (0-12) & 119/2 (1-16), Masudabad Village, New Delhi- 110043.

Building is comprised of 3. Type of Occupancy

Ground floor only

4. Type of Case

**Educational Building** New

5. Details of Previous NOC

N/A

6. Fire Safety directives letter No : 7. Date of inspection

N/A 13.05.2025

8. Name of Inspecting Officer

A.D.O. R.K. Yadav

9. Name and designation of officers

Mr. H.S. Sodhi (Architect)

From the building side 10. Year of Construction

2024

11. Applicant's letter No.

Nil, dated 15.04.2025

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR			
1.	Access to building						
	<ul> <li>Road width</li> <li>Gate width</li> <li>Width of internal road</li> </ul>	Accessible 06 m 4.5 m N/A	06 m Directly accessible from road N/A	MR MR N/A			
2.	Number, Width, Type & Arrangement of	of Exits		13/71			
	a. Number of staircases						
	Upper Floors	N/A	N/A	N/A			
	Basements	N/A	N/A	N/A			
	b. Width of staircases						
	Upper Floor	N/A	N/A	N/A			
	Basements	N/A	N/A	N/A			
	c. Protection of exits						
	Fire check door	N/A	N/A	N/A			
	Pressurization	N/A	N/A	N/A			
	d. No. of continuous staircases to	N/A	N/A	N/A			
	e. Width of Corridor	N/A	N/A	N/A			
	f. Door Size	1.0 m	Provided	MR			
3.	Compartmentation		7707.000				
San	Fire check door	N/A	N/A	N/A			
4.	705 N W OF	N/A	N/A	N/A			
	Sealing of electrical shafts     Fire Rating of shaft door	N/A	N/A	N/A			
	Water Curtain	PROMINE.	851953	N/A			
	Fire Dampers	N/A	N/A N/A	N/A			
	Smoke Management System	N/A	IVA	- 1			
	Working Control of Reference of the Control of the	N/A	N/A	N/A			
	Basements	Required	Natural ventilation provided	MR			
	Upper floors	Required					
5.	Fire Extinguishers						
	Total numbers	10 no's	Provided	MR			
	• Types	ABC/CO <sub>2</sub> type	Provided	MR			
	IS marking	ISI marked	Provided	MR			
6.	First-Aid Hose Reels						
	Total numbers on each floor	N/A	02 nos.	N/A			
	Length of hose reel hose	N/A	30 m	N/A			
	Nozzle diameter	N/A	05 mm	N/A			

NU
----

la en		NA			
7.	Automatic fire detection and alarming system				
	Type of detectors	N/A	N/A	N/A	
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
8.	MOEFA	Required	Provided	MR	
9.	Public Address System			MR	
10.	Automatic Sprinkler System	Required	Provided		
	Automatic Sprinkler System				
	Basement	N/A	N/A	N/A	
	Ground Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
1.	Internal Hydrants				
	Size of riser/down-comer	N/A	100 mm	N/A	
	Number of hydrants per floor	N/A		N/A	
	Hose Box	N/A	02 nos. 02 nos.	N/A	
2.	Yard Hydrants	IVA	02 1108.	- 22-2	
			1		
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
•	Pumping Arrangements				
	Ground Level				
	Discharge of main Pump	N/A	N/A	N/A	
	➤ Head of Main pump	N/A	N/A	N/A	
	> Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	➤ Standby Pump out put	0.25 (0.5 (0.5)	N/A	N/A	
	➤ Standby Pump Head	N/A			
- 1	> Auto Starting/Manual	N/A	N/A	N/A	
	Stopping	N/A	N/A	N/A	
		N/A	N/A	N/A	
	> Pump House Access	1071	1.7	1	
	Terrace level	N/A	900 LPM	N/A	
	Discharge of pump	N/A	40 m	N/A	
	Head of the pump	N/A N/A	Provided	N/A	
	> Power Supply	N/A N/A	Provided	N/A	
	Auto Starting of pump	N/A	Tiovided		
1	Captive Water Storage for fire fighting				
,		N/A	N/A	N/A	
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Draw-off connection</li> <li>Fire service inlet</li> </ul>		N/A	N/A	
	> Access to tank	N/A	N/A	N/A	
	Overhead Tank capacity	N/A	20,000 ltrs	N/A	
	- Overhead rank suparry	N/A	Provided	MR	
E	xit Signage.	Required		\$155,5	
+	Provision of Lifts. (No Lift)				
P	TOVISION OF LINES.		N/A	N/A	
	Pressurization of Lift Shaft	N/A		N/A	
1	Pressurization of Lift lobby	N/A	N/A	N/A N/A	
	Communication In lift Car	N/A	N/A	52,187,522	
	Fireman's Grounding Switch	N/A	N/A	N/A	
	Lift Signage	N/A	N/A	N/A	
1	- Divi DiBing				

17.	Standby power supply	N/A	N/A	N/A			
18.	Refuge Area.	fuge Area.					
	> Total Area	N/A	N/A	N/A			
	➤ Location	N/A	N/A	N/A			
19.	Fire Control Room						
	Detector System Panel	N/A	N/A	N/A			
	<ul> <li>Flow Switch Panel</li> <li>PA System Panel</li> </ul>	N/A	N/A	N/A			
	Battery backup     Building Floor Plans	N/A	N/A	N/A			
		N/A	N/A	N/A			
		N/A	N/A	N/A			
20.	Special Fire Protection System for	N/A	N/A	N/A			

The fire protection systems provided in the building were test checked and found not functional at the time of inspection.

Note: - Total plot area is 2114.86 sqm. This is the school for skill development of poor girls, widows and unemployed men. The overall height of the building is 8.5 m. The construction of the roof is constructed with RCC slab.

Keeping in view of the above compliance of the minimum standards of fire prevention and fire safety measures under Rule 35 of the Delhi Fire Service Rules 2010, it's recommended to grant Fire Safety Certificate.

Signature of the Inspecting Officer

Name- R.K. Yadav Designation- ADO (JKP)

DO (South West)

13/2/22 (17)

Cfo

15 51 3025

Director

MODING

helter .

but up for sign.

2 3 200

DIRECTOR

X X 7 7 7