

496



GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001


No F 6/DFS/MS/2025/SZ/ 636

FIRE SAFETY CERTIFICATE

Dated 03/12/2025

Certified that the Auditorium /Lecture hall at Central Armed Police Force Institute of Medical Science (CAPFIMS) at Maidan Garhi, New Delhi comprised of ground floor & one upper floor have complied with the fire prevention and fire safety requirements in accordance with rule 33 of Delhi Fire Service Rules, 2010 and verified by officers concerned of this department on 20.11.2025 in the presence of Sh. Rakesh Joshi (AE, Elect.), CPWD & Sh. Rahul Tashiwal (AE, Civil), CPWD and that the building/ premises is fit for occupancy class " assembly " auditorium/lecture hall at ground floor with effect from 03/12/2025 for a period of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 03/12/2025 at New Delhi by


(A.K. Malik)
Dy. Chief Fire Officer
Delhi Fire Service
o/c

Copy to:-

1. The Executive Engineer (Elect). CPWD, CAPFIMS, PED, Room No.208 Vidut Bhawan , New Delhi : to kindly ensure the occupancy as detailed above and deviation in construction if any.
2. The Section Officer (PF-IV/LO) Government of India , MHA(Police-II) Division PF-I desk , Kartyva Bhawan -3 New Delhi.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction, covered area, set back area , lift , electrical installation etc shall be verified by the concerned building sanctioning agency.
5. This certificate cannot be treated in any case for regularizations of unauthorized construction.
6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
7. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building : Auditorium/Lecture hall at Central Armed Police Force Institute of Medical Science at Maidan Garhi (CAPFMIS) New Delhi
Gr.+ first floor
2. Type of occupancy : Assembly at ground floor & AHU at first floor
3. Type of case:- :New
4. Details of previous FSC : N/A
5. Fire safety directives No. : No. F6/DFS/MS/BP/2016/279 dated 08.11.2016
20/11/2025
6. Date of inspection:-
7. Name of the inspecting officer : Sh. Ravinder Singh (DO/SD) &
Sh. Y.S.Meena (ADO/BCP)
8. Name & designation of officer
From the building side : Sh. Rakesh Joshi (AE, elect.) &
Sh. Rahul Tashiwal (AE, Civil)
9. Year of construction : 2025
10. Applicant's letter No :NO.II27012/39/2021-PF-I(CF No.
3584492) dated 22.10.2025

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirements as per guidelines	Provided at site	Remarks MR/NMR
1.	Access to Building	F6/DFS/MS//Hospital/2024/SZ/735 dated 13.12.2024) to CAPFIMS		
	1) Road width	06 mtr.	Provided	MR
	2) Gate width	06 mtr.	Provided	MR
	3)Width of internal road	NA	NA	NA
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors(AHU room)	01Nos.	01 Nos.	MR
	2. Basements	NA	NA	NA
	B. Width of staircase			
	1. Upper floors	1.5m	Provided	MR
	2. Basements	NA	NA	NA
	C. Protection of exits			
	1. Fire check door	NA	NA	NA
	2. Pressurization	NA	NA	NA
	D. No. of continuous staircase to terrace	01nos.	Provided	MR
	E. Width of corridor	NA	NA	NA
	F. Door size	6x2.0 mtr.	Provided	MR
3.	Compartmentation			
	1) Fire check door	Required	Provided	MR
	2) Sealing of electrical shafts	Required	Provided	MR
	3) Fire rating of shaft door	NA	NA	NA
	4) Water curtain	NA	NA	NA
	5) Fire Dampers	NA	NA	NA
4.	Smoke Management System			
	1) Basements	NA	NA	NA
	2) Upper floors	Mechanical	provided	MR
5.	Fire Extinguishers			
	1) Total numbers	08 Nos.	Provided	MR
	2) Types	ABC, CO2,	ABC, CO2,	MR
	3) ISI marking	Required	Provided	MR
6.	First-Aid Hose Reel			
	1)Total number	02 nos	Provided	MR
	2) Length of hose reel hose	30 m	Provided	MR

	3) Nozzle diameter	5 mm	Provided	MR
7.	Automatic Fire Detection & Alarming System :Common with hospital (CAPFIMS)			
	1) Type of detectors	Beam type	Provided	MR
	2) Location of main panel	Gr. Floor	Provided	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Required	Provided	MR
	5) Hooter's Location	Ground floor	Provided	MR
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	Required	Provided	MR
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants: connected with hospital		Common with hospital (CAPFIMS)	
	1) Size of riser/down-comer	100 MM	Provided	MR
	2) Total Number of hydrants	02	Provided	MR
	3) Hose box each floor	02	Provided	MR
12.	Yard Hydrants			
	1) Total number of hydrants	02	Provided	MR
	2) Hose box	02	Provided	MR

13.	Pumping Arrangement	Common with hospital (CAPFIMS)		
	1) Ground level			
	a) Discharge of main pump	2280 LPM	As above	MR
	b) Head of main pump	55 mtr.	As above	MR
	c) Number of main pump	01	As above	MR
	d) Jockey pump out put	180 LPM	As above	MR
	e) Jockey pump head	55 mtr.	As above	MR
	f) Stand by pump output	2280 LPM	As above	MR
	g) Stand by pump head	55 mtr.	As above	MR
	h) Auto starting/Manual stopping	Required	As above	MR
	2) Terrace level			
	a) Discharge of pump	450 LPM	Provided	MR
	b) Head of pump	40 m	Provided	MR
	c) Power supply	Required	Provided	MR
	d) Auto starting of pump	Required	Provided	MR
14.	Captive Water Storage for Fire Fighting: Common with hospital (CAPFIMS)			
	1) Under ground tank capacity	1,00,000 ltr.	As above	MR
	a) Draw-off connection	Required	As above	MR
	b) Fire service inlet	Required	As above	MR
	c) Access to tank	Required	As above	MR
	d) Over head tank capacity	5,000 ltr.	10,000 ltr	MR
15.	Exit Signage.	Required	Provided	MR


2/34

16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A
17.	Stand by Power Supply	Required	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	Common with hospital (CAPFIMS)		
	a) Detector system panel	N/A	Provided	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	Provided	N/A
	d) Battery backup	N/A	Provided	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection systems provided in the building were randomly tested, checked functional at the time of inspection. The FSC to CAPFIMS has already been issued vide letter no. F6/DFS/MS//Hospital/2024/SZ/735 dated 13.12.2024.


In view of the substantial compliance of the minimum standards of fire prevention and fire safety measures as required under the rules, if approved, it is recommended to issue the under rule 35 of the Delhi Fire Service Rules 2010, Accordingly, DFA is put up for kind perusal and signature please.

Signature of the Inspecting Officer



24/11/24

Name :- Ravinder Singh
Designation :- DO (SD)

Signature of the Inspecting Officer


24/11/2024

Name :- Y.S.Meena
Designation :- ADO (BCP)



24/11/24


24/11/24
A. K. MALIK


Principal Director

By. CDO to Secy.


By. CDO (Secy)


24/11/24