Faling and Lodging Losges Logge

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI - 110001

No. F6/DFS/MS/GH/NDZ/2025/529

Dated: 30 / 10 /2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Chand Palace located at 54, Arakashan Road, Pahar Ganj, New Delhi -110055, comprised of Ground + 05 upper floors: Ground floor - (reception + 03 guest rooms + 02 offices), 1st floor to 3rd floor - (09 guest rooms at each floor), 4th & 5th floor- (not in use), total 30 guest rooms upto 3rd floor was granted FSC by this department vide letter no. F6/DFS/MS/GH/NDZ/2022/458 dated 07.10.2022. The building/premises was re-inspected by the undersigned of this department on 22.10.2025 in presence of Mr. Deepak Tiwari (Manager) and found that the building have deemed complied with the fire prevention and fire safety requirements in accordance with Rule 33 of Delhi Fire Service Rules, 2010. The owner has submitted an affidavit on 23.10.2025 stating not to use any floor above third floor for any purpose. Accordingly, the premises is fit for occupancy of class "Residential" (Sub Division-A-1), ground floor - (reception + 03 guest rooms + 02 offices), 1st to 3rd floor - (09 guest rooms at each floor) for total 30 guest accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to conditions under rule 38 of Pelhi Fire service Rules, 2010 subject to condition printed below.

Issued on 30 10 2025 at New Delhi by

(Dr. S. K. Tomar)

Dy. Chief Fire Officer

Delhi Fire Service

Copy to:-

- 1. The Commissioner, MCD, Dr. SPM Civic Centre, New Delhi 110002. w.r.to ID No. 2025100714033 dated 07.10.2025:- to kindly ensure the occupancy as detailed above & deviation, if any.
- 2. The Licensee, M/s Chand Palace at 54, Arakashan Road, Pahar Ganj, New Delhi -110055.

Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction. if any.
- 6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 7. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director in form 'J' [sub rule (I) of rule 37] along with a copy of this Certificate, six month prior to its expiry".
- 8. Any change in the occupancy shall be intimated to this Deptt. and approval shall be obtained thereto before occupancy of the same.
- 9. The occupancy of above 3rd floor not allowed as per clause 7.31 in UBBL-2016.

	Na	me & address of the half	!	N/ C		t 54 Arakas	
-	Ivai	me & address of the building		M/s Chand Palace located at 54, Arakas			
	Building is comprised of			Road, Pahar Ganj, New Delhi -110055.			
-	Building is comprised or			(Ground + 05 upper floors) Ground floor – (reception + 03 guest rooms + offices) 1 st floor to 3 rd floor – (03 guest rooms at eafloor) 4 th & 5 th floor - (not in use as per affidavit date 23.10.2025)			
-							
3	Tvr	pe of occupancy		Residential, Sub Division-A			
1	Type of case		Renewal 107 10 20				
- 1			Renewal F6/DFS/MS/GH/NDZ/2022/458 dated 07.10.20				
5	Details of previous FSC			Nil			
6		e safety direction letter no.	- 10	22.10.2025			
7	1000	te of inspection	-	ADO (Hars)			
8		me of the inspecting officer		Mr. Deepak Tiv	vari (Manager)		
9		me of the designation	of	Mr. Deepak Tiwari (Manager)			
		icer from the building side	_			ingo da	
10		ar of construction		Ouline application	on ID No. 20251	100714033 da	
11	Ap	plicant's letter no.	- 1	Online application ID No. 2025100714033 date 07.10.2025			
	X.		_		Provided at	Remarks	
S.No	Mi	nimum Standards on fire	- 1	Requirement /	Site	MR/ NMR	
	Prevention and fire safety			Existing		NIVIK	
		uirements U/R 33			- 1		
1		cess To Building:		NA	04 m	NA	
	Road width			NA NA	NA	NA	
	Gate width			NA NA	NA	NA	
N Familie	Wi	dth of internal road mber, Width, Type and A	rran	gement of Exits:		-	
2	_	Number of staircases	T			MR	
	A	a Upper floor	0	l no.	01 no.	NA	
	1	b Basement	N	Α	NA	INA	
	В	Width of staircases			1.07	MR	
	D	a Upper floor		80 m	1.27 m NA	NA	
		b Basement	N	Α	IVA.		
	C	Protection of exits	N	Δ	NA	NA	
		a Fire check door	N		NA	NA	
	b Pressurization 0		_	no.	01 no.	MR	
	No. of continuous staircases to terrace						
	E	Width of corridor	N.		NA	NA	
	F Door size 1.		1.	0 m	1.0 m	MR	
3	Co	mpartmentation:	1			T ASSESSED	
	A Fire check door		N.		NA	NA	
	В	Sealing of electrical	N.	n.	NA	NA	
	shafts C Fire rating of shaft door N		N.	A	NA	NA	
	D Water curtain N		N.		NA	NA	
	E Fire dampers N		N/	A	NA	NA NA	
4	Sm	oke Management System:	112		Annual States	Land Land	
	A	Upper floors	Re	quired	Natural/	MR	
				-	exhaust fan		
	В	Basements Palace located at 54, Arakas	N/	1	Ventilation		
	100000000000000000000000000000000000000		- 14	-	DIA		

5.	Fir	e Extinguisher:		T	MR			
	A	Total numbers	10 nos.	10 nos.	Accesses			
	В	Types	CO ₂ & ABC	Provided	MR			
	C	ISI marking	Required	Provided	MR			
6	Fi	rst-Aid-Hose Reels:						
	A	Total numbers of each floor	01 no.	01 no.	MR			
	В	Length of hose reel hose	30 m	30 m	MR			
	C	Nozzle diameter	05 mm	05 mm	MR			
7	Au	tomatic Fire Detection And Ala	rming System:					
	A	Type of detectors (CO type)	Required	Provided	MR			
	В	Location of main panel	Ground floor	Provided	MR			
	C	Location of repeater panel	NA	NA	NA			
	D	Alternate source of power	Required	Provided	MR			
	E	Hooters	Required	Provided	MR			
8	M	OEFA:	Required	Provided /	MR			
9	Pu	blic Address System:	Required	Provided	MR			
10	Au	tomatic Sprinkler System:		Y				
	A	Basement	NA	NA -	NA			
	В	Upper floor	NA	NA	NA			
	C	Sprinkler above false ceiling	NA	NA	NA			
11	Internal Hydrants:							
	A	size of riser/down-comer	NA	NA	NA			
	В	Number of hydrants per floor	NA	NA	NA			
	C	Hose box	NA	NA	NA			
12	Ya	rd Hydrants:	2200	1	1 - 1 - 1			
	A	Total number of hydrants	NA	NA	NA			
	В	Hose box	NA	NA	NA NA			
13	Pur	nping Arrangements:		INA	INA			
	A							
	a)	Discharge of main pump	NA	NA	NA			
	b)	Head of main pump	NA	NA NA	Jew-Nove-			
	c)	Number of main pumps	NA NA		NA			
	d)	Jockey pump out put	NA NA	NA	NA			
1	e)	Jockey pump head		NA	NA			
	f)	Standby pump nead	NA NA	NA	NA			
-	g)	Standby pump head	NA NA	NA	NA			
H	h)	Auto starting /manual	NA NA	NA NA	NA			
	,	stopping	11A	INA	NA			
r	i)	Pump house access	NA	NA	NA			
	B	Terrace level			IVA			
	a)	Discharge of pump	450 LPM	450 LPM	MR			
_	b) -	Head of the pump	30 m	30 m	MR			
-	c)	Power supply	Required	Provided	MR			
	-,	- 0 d. o b	Required		1711			

14	Ca	ptive Water Storage For Fire	Fighting:		
	A	Underground tank capacity	NA NA	NA	NA
	В	Draw-off connection	NA	NA	NA
	Ċ	Fire service inlet	l NA	NA	NA
	D	Access to tank	NA	NA	NA
	Ē	Overhead tank capacity	2,500 ltrs.	2,500 ltrs.	MR
15		it Signage:	Required	Provided	MR
16	Provision of Lifts:				
	A	Pressurization of lift shaft	NA	NA	NA NA
	B	Pressurization of lift lobby	NA	NA	NA NA
		Communication in lift car	NA NA	NA	NA NA
	C		NA	NA	NA NA
	D	Firemen's grounding switch	NA NA	NA	MR
	E	Lift signage	Required	Provided	IVIL
17	Standby Power Supply: Required				
18	Re	Refuge Area: NA NA			
	A	Total area	NA	NA	NA
	В	Location	NA		NA.
19	Fir	e Control Room :	-T4	NA	NA NA
	A	Detector system panel	NA	NA	NA
	В	Flow switch panel	NA NA	NA	NA
	C	Pa system panel	NA NA	NA	NA
į		Battery backup	NA NA	NA	NA
		Building floor plans ecial Fire Protection Systems Fo	n staction of	NA	in entry sta

The fire protection systems provided in the building were tested, checked at random and found functional at the time of inspections.

found functional at the time of inspections.

Keeping in view of the deemed compliance of minimum standards of fire prevention and fire safety measures as required under the Rules, the FSC issued vide letter No F6/DFS/MS/GH/NDZ/2022/458 dated 07.10.2022 is recommended to be renewed upto 3rd floor only, under Rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer Name Sumit Kumar Designation ADO (Hqrs)

DO(CD) m 23/10/2

Dy. (FO(NOZ)

23/10/2r

Principal Director

M. CES

Ale | ~

14/10/51-

ADOCKO F.T. When is pur up for Signature, Please.