

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, NEW DELHI-110001



No. F6/DFS/MS/2025/WZ/ 603

Dated: |2 | 11 | 2025

FIRE SAFETY CERTIFICATE

Certified that the M/s Community Hall Building located at K(P) Block, Pitampura, Delhi110088, comprised of Ground + 02 upper floors has already been issued FSC by this department vide
letter No. F.6/DFS/MS/2022/390 dated 05.09.2022. The premises was re-inspected by the officer
concerned of this department on 27.10.2025 in the presence of Mr. Sanjeev Kumar Mishra, Manager
and found that the said building have deemed complied with the fire prevention and fire safety
requirements in accordance with Rule 33 of the Delhi Fire Service Rules, 2010 and that the premises
fit for occupancy class Assembly (Community Hall) with effect from \(\frac{12}{11} \) \(\frac{11}{202} \) for a period
of three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under
Rule 40 and subjected to compliance of the conditions under Rule 38 of the Delhi Fire Service Rules,
2010.

Issued on 12 11 2025 at New Delhi by

(S. K. Dua)

Dy. Chief Fire Officer (WZ)

Delhi Fire Service

Copy to: -

Mr. Rajeshwar Garg, Narsingh Dass Jan Sewa Samiti, KP Block, Pitam Pura, Delhi-110088.

2. The Joint Director (Bldg.) (L&I), DDA, Bldg. Section, Vikas Sadan, INA, New Delhi. Conditions for the validity of Fire Safety Certificate:

- 1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
- 2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.

5. This certificate cannot be treated in any case for regularizations of unauthorized construction.

- 6. The owner/occupier shall apply for renewal of this Fire Safety Certificate to the Director of Form 'J' [sub rule (1) of rule 37] along with a copy of this Certificate, six months prior to its expiry".
- 7. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on
- 8. All the means of escape shall be kept free of any obstruction all the time to evacuate the occupant, in a safe manner, in the event of emergency.

http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Fire+Safety+Acts+and+Rules/http://www.delhi.gov.in/wps/wcm/connect/doit_fire/FIRE/Home/Forms

		INSPE	CTION REPORT			
Name & a	ddress of the building	M/s Co	ommunity Hall Bui	lding located at K(P) F	Block Pitampura	
Name & a				g u. 11(1) 1	nock, i itampura,	
Type of O	ccupancy					
			val (Ground + 02 upper floors)			
			nite in the damage of the second			
			THE COURT OF THE C			
THE THE PERSON NAMED OF THE PERSON			105122230	DO (IV.: A O)		
S-17-30-30-100 17-51-51	The state of the s		· · · · · · · · · · · · · · · · · · ·	THE COURSE OF THE PERSON OF TH		
From the b	uilding side	S.	v Kumar Mishra, Mi	anager		
CARGODIA CORE LEGIS	Service of the service of the service	Managaran and St.				
. Applicant'	s letter No.	Control of the Parish	Charles the Annual State of the		Remarks	
		ention	report dated 18.08.2022	Provided at site	MR/NMR	
Access to.	building					
• Ro	ad width		12m	Provided	MR	
• Ga	te width		5m	a analysis more and section	MR	
• Wi	dth of internal road		-NA-	·-NA-	-NA-	
Number,	Width, Type & Arrange	ment of	Exits			
a. Numbe	r of staircases			1	1	
• 1	Upper Floors	11	02nos.		MR	
• 8]	Basements		-NA-	-NA-	-NA-	
b. Width	f staircases					
• 1	Upper Floor		Old	1.47m & 1.20-1.40m	MR(Old case)	
	A A CONTRACTOR OF THE CONTRACT		-NA-	-NA-	-NA-	
	A SCAN CONTROL SON					
			-NA-	-NA-	-NA-	
3 D	85/8		-NA-	-NA-	-NA-	
d. No. of c	96 M. S. T. GOLDE, T. A. S. G. S.	errace	02nos.	Provided	MR	
Mark and the second			Old case	Old case	MR	
SOND IN ILVERSION MOST			Old case	1.45m -1.80m	MR(Old case)	
Control of the Contro		1.1-	-NA-	-NA-	-NA-	
			-NA-	-NA- ·	-NA-	
			-NA-	-NA-	-NA-	
			-NA-	-NA-	-NA-	
	SECULARIZATION CONTRACTOR CONTRAC		-NA-	-NA-	-NA-	
			-NA-	-NA-	-NA-	
		I I KI	Required	Provided	MR	
	al numbers		16nos.	Provided	MR	
a) lota			ABC/CO2	ABC/CO2	. MR	
	es		ABereoz		Conductor Contractor	
b) Тур			ISI marked	Yes	MR	
b) Typ	narking				7	
b) Typ c) IS n First-Aid H	narking Iose Reels			Yes Provided	MR	
b) Type c) IS n First-Aid H	narking		ISI marked		1 1	
	Type of Oc Type of Ca Details of Fire Safety Date of ins Name of In Name and From the b Year of Co Applicant' Minimum and fire s: Access to Ro Ga Wi Number, a. Numbe b. Width c. Protec c. Protec c. Width of f. Door Si Compartn a) Fire b) Sea c) Fire d) Wa e) Fire Smoke Ma a) Bas b) Upp Fire Exting	Name and designation of officers From the building side Year of Construction Applicant's letter No. Minimum Standards on fire prevant fire safety U/R 33 Access to building Road width Gate width Width of internal road Number, Width, Type & Arrange Number of staircases Upper Floors Basements Upper Floor Basements Pressurization No. of continuous staircases to the Width of Corridor No. of continuous staircases to the Width of Corridor Road width Width of Staircases Upper Floor Basements Fire check door Pressurization No. of continuous staircases to the Width of Corridor Roor Size Compartmentation A) Fire check door B) Sealing of electrical shafts C) Fire Rating of shaft door d) Water Curtain e) Fire Dampers Smoke Management System A) Basements b) Upper floors Fire Extinguishers	Name & address of the building Type of Occupancy Type of Case Details of Previous NOC Fire Safety directives letter No Date of inspection Name of Inspecting Officer Name and designation of officers From the building side Year of Construction Applicant's letter No. Minimum Standards on fire prevention and fire safety U/R 33 Access to building Road width Gate width Width of internal road Number, Width, Type & Arrangement of a. Number of staircases Upper Floors Basements Upper Floor Basements Pressurization A No. of continuous staircases to terrace Width of Corridor Door Size Compartmentation a) Fire check door b) Sealing of electrical shafts c) Fire Rating of shaft door d) Water Curtain e) Fire Dampers Smoke Management System a) Basements b) Upper floors Fire Extinguishers	Type of Occupancy Type of Case Details of Previous NOC Fire Safety directives letter No Date of inspection of officer Date of inspection Date of i	Name & address of the building	



7.	Automatic fire detection and alarming sys	stem				
	a) Type of detectors	Smoke/Heat	Provided	MR		
	b) Location of Main Panel	Required	Provided	MR		
	c) Location of Repeater Panel	Required	Provided	MR		
	d) Alternate source of power	Entire building	Provided	MR		
	e) Hooters' Location	Required	Provided	MR		
8.	MOEFA	-NA-	-NA-	-NA-		
9.	Public Address System	-NA-	-NA-	-NA-		
10.	Automatic Sprinkler System					
	a) Basement	-NA-	-NA-	-NA-		
	b) Ground & Upper Floors	-NA-	-NA-	-NA-		
	c) Sprinkler above false ceiling	-NA-	-NA-	-NA-		
11.	Internal Hydrants					
100.0	a) Size of riser/down-comer	100mm	Provided	MR		
	b) Number of hydrants per floor	01nos.	Provided	MR		
	c) Hose Box	Required	Provided	MR		
12.	Yard Hydrants			1		
	a) Total number of hydrants	-NA-	-NA-	-NA-		
	b) Hose Box	-NA-	-NA-	-NA-		
13.	Pumping Arrangements					
	Ground Level					
	> Discharge of main Pump	-NA-	-NA-	-NA-		
	> Head of Main pump	-NA-	-NA-	-NA-		
	Number of main pumps	-NA-	-NA-	-NA-		
	Jockey Pump out put	-NA-	-NA-	-NA-		
	Jockey pump head	-NA-	-NA-	-NA-		
	Standby Pump out put	-NA-	-NA-	-NA-		
	> Standby Pump Head	-NA-	-NA-	-NA-		
	> Auto Starting/Manual Stopping	-NA-	-NA-	-NA-		
	> Pump House Access	-NA-	-NA-	-18/4-		
	Terrace level					
	Discharge of pump	450lpm	450lpm	MR MR		
	> Head of the pump	40m	40m	MR		
	> Power Supply	Required	Provided	MR		
	> Auto Starting of pump Required Provided					
14.	- 111					
	Underground tank capacity	50,000ltr	Provided	MR		
	> Draw-off connection	Required	Provided	MR		
	> Fire service inlet	Required	Provided	MR		
	> Access to tank	Required	Provided	MR		
	Overhead Tank capacity	10,000ltr	Provided	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.			-		
10.	15 OF ACCUPANCE OF THE PARTY OF	-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
		-NA-	-NA-	-NA-		
		1111	1 1/ 1-	-14/7-		
	d) Fireman's Grounding Switch e) Lift Signage	-NA-	-NA-	-NA-		

Refuge Area.	-NA-	-NA-	-NA
a) Total Area		-NA-	-NA
Contract to the contract to th	-NA-	-NA-	
b) Location			
Fire Control Room	-NA-	-NA-	-NA-
a) Detector System Panel		-NA-	-NA-
b) Flow Switch Panel	-NA-	-NA-	-NA-
	-NA-		-NA-
c) PA System Panel	-NA-	-NA-	
d) Battery backup	-NA-	-NA-	-NA-
e) Building Floor Plans		-NA-	-NA-
Special Fire Protection System for Protection of special Risks, if any:	-NA-	-1471;	

Accordingly, the fire protection systems provided in the building were tested/ checked randomly and found in working condition at the time of inspection.

found in working condition at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required as stipulated in NBC Part-4, and removal of shortcomings issued vide letter no. 456 dated 15.09.2025, the FSC issued vide letter no. F.6/DFS/MS/2022/390 dated 05.09.2022, renewal of FSC under rule 37 of the Delhi Fire Service Rules, 2010 is recommended.

Signature of the Inspecting Officer
Name Ajay Kumar Sharma
Designation ADO(Wazirpur/MN)

DO(W)- W\\

Je affect Sirp

Principal Director

F.T. please

ADO(WP)

for letter is pout up for our poursal and signature please.

Lufular.

Derolusi

F.P. wing